



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/06/2025

Incharge(s): V Balaji Naik

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|--|--|--|--|---------|
| 1 | OHP | CO29 | Over load acted 3 times | Reset done | 17:00:00 20:30:00 21:10:00 21:35:00 | 17:15:00 20:45:00 21:20:00 21:40:00 | |
| 2 | OHP | CO35 | Over load acted | Reset done | 19:40:00 | 19:50:00 | |
| 3 | OHP | TBS on CO20 | Left boom not working found MPCB trip | Reset and made on | 17:20:00 | 17:40:00 | |
| 4 | OHP | CO42a | BRS bypassed as per operational request | Entered in log book | 20:45:00 | 21:00:00 | |
| 5 | CHP | SCR2 on CC35 | Signal problem from CCR to SCR2 | Antena and pick tail cable changed then ok | 15:10:00 | 18:00:00 | |
| 6 | CHP | CC33 | Due to over load on CC51 | Reset done | 18:50:00 | 19:00:00 | |
| 7 | CHP | CC112 | Stpped due to over load on C51 | Reset done | 20:55:00 | 21:00:00 | |
| 8 | WT | OP3 | Not working found middle pad fallen down near cabin area | With c clamp adjustment middle pad adjusted to normal position then ok | 14:45:00 | 15:00:00 | |