



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 01/12/2025

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CC 40 SCr 2	signal missing,	LT done than ok	17:00:00	17:30:00	
2	OHP	CO 48	olr acted	reset	20:50:00	21:00:00	
3	OHP	TBS on CO 5A	LT not taking place,M\$ tripped continuously on olr	M4 connection removed	15:30:00	15:45:00	
4	OHP	BRC on CO 28	Reported B/C not running	Control checked and found okay. Tested okay	21:00:00	21:20:00	
5	CHP	CC-203 on CC-29	Reported flap gate not changing through system	Checked and found PLC fault at CCR.Remote I/O at LC-5 no power found due to I/C-2 tripped. I/C-2 made on and CCR PLC communication restored and tested okay	19:24:00	20:30:00	
6	CHP	CC 125	olr acted	reset	19:00:00	19:10:00	
7	CHP	CC 38 SCR6	Lt not working,OT acted	OT released	20:45:00	21:00:00	
8	CHP	CC 32 R1	b/c not running,olr acted	reset	16:00:00	16:15:00	
9	CHP	CC 51	mpd tripped	reset	17:20:00	20:30:00	5 times
10	CHP	CC 51	motor tripped in olr	reset	18:36:00	18:40:00	
11	CHP	CC 54	olr acted 2 times	reset	15:00:00	17:05:00	
12	CHP	CC 114	olr acted	reset	21:20:00	21:30:00	