



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 26/05/2025

Incharge(s): K SANKARA RAO

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 35	OLR ACTED	RESET	17:55:00	18:00:00	
2	OHP	CO 29	OLR ACTED	RESET	18:50:00	19:00:00	
3	OHP	TT2 ON CO21	POSITION INDICATION PROBLEM	BY PASSED	16:00:00	16:20:00	DUE TO SENSOR COVERED WITH JAMMING MATERIAL
4	CHP	CC 33 , SCR 4	BC ZSS probe not working	ZSS bypassed in IO rack	17:40:00	17:55:00	
5	CHP	CC 32 ,SCR 5	LT not working	Drive reset	18:10:00 18:45:00	18:20:00 18:55:00	
6	CHP	CC 36 , SCR 1	BC not running due to BSS acted	Belt offcentering , informed to mechanical. After operation request BSS bypassed	21:00:00	21:15:00	Bypassed in system