



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/05/2025

Shift: B

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO10A carriage drive	OLR tripped	Reset done	20:20:00	20:30:00	
2	OHP	CO25	Red olr acted	Reset done	18:15:00	18:25:00	
3	OHP	VS3A	MPCB tripped	Reset done	18:00:00	18:15:00	
4	OHP	BRC on 33M	BC not working chute sensor acting due to rain	Chute sensor bypassed and normalised	20:00:00	20:20:00	
5	OHP	BRC on CO32	BC not running olr acted	Reset done	20:20:00	20:35:00	
6	OHP	WOBR on CO26	LT not working and swing not working found machine damage due to over travel towards tail end	informed operation and mechanical LT made oFF	20:00:00	20:20:00	Not an electrical problem
7	OHP	CO26	OLR acted	Reset done	19:15:00	19:25:00	
8	OHP	CO37A	BRs bypassed as per operational request	By passed	19:45:00	20:00:00	
9	OHP	CO29TIS	ZSS by passed as per operational requirement	Done in module	19:45:00	20:00:00	
10	OHP	Few conveyors tripped	Found breaker tripped in LC3 feeding to LC4 and OM28	Breaker made on then ok	19:30:00	20:10:00	
11	CHP	CC32	Yard conveyoe stopped due to MPR trip on E0 fault	Reset done	14:15:00	14:20:00	
12	CHP	CC44	OLR tripped due to over load on belt	informed to operation to get clear the jam after jam clearance reset done	17:10:00	17:25:00	
13	CHP	CC107	OLR acted due to over load	After jam clearance Reset done	17:15:00	17:25:00	



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/05/2025

Incharge(s): V Balaji Naik

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	SCR9 ON CC104	Luffing and BC not working found no electrical problem abnormal sound in fluid coupling and BC hydraulic pressure problem	Informed to mechanical and operation	19:30:00	19:50:00	Not an electrical problem
15	CHP	R1 on CC31	BC not running due to rain chute sensor acting	Chute sensor bypassed and normalised	20:50:00	21:05:00	
16	CHP	SCR1 on CC36	TUL acting due to rain by passed	and removed	21:10:00	21:20:00	
17	CHP	SCR2 on CC34	No lighting auxiliary supply tripped	Reset done	18:30:00	18:40:00	
18	CHP	SCR5 on CC32	BC stopping frequently	PLC reset done then ok	20:50:00	21:05:00	
19	CHP	Cc32,CC36, CC38	BRs bypassed as per operational requirement	By pass removed	20:00:00	20:30:00	
20	WT	CP2	not moving found communication problem	PLC power recycling done	16:45:00	16:50:00	
21	WT	OP1 and OP2	Not moving found communication problem	PLC power recycling done	20:15:00	21:25:00	