



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL GENERAL SHIFT REPORT**

Date: 24/05/2025

Area: OHP

Equipment	Job
rsco-10a	both cjd's tested and found ok.
tis-4 on co-44	belt is tripping due to metal plate stuck , removed plate and restored for operation.
co-5	pullchord is rectified and kept in circuit. brs is continuing in bypass.
brc-34	ct guide roller structure is damaged, ct limit sw cable towards crmp got cut, rejoined, trail run to be taken after mechanical job.
co-3a beltsway	bypassed temporarily for offcentering adjustment, and kept back in circuit after operation clearance.