



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/05/2025

Shift: C

Incharge(s): V Balaji Naik, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	Stacker on CO22(Chute vibrator)	Starter tripped	Reset done	22:45:00	23:00:00	
2	OHP	CO26	electrical olr acted	Reset done	03:50:00	04:00:00	
3	OHP	CO25	Over load acted	Reset done	05:30:00	05:40:00	
4	OHP	TBS on CO5a	LT not stopped even in off condition	Push button released properly then ok	22:40:00	23:00:00	some times start push button is not releasing properly may check further
5	CHP	CC114	Over load tripped	Reset done	01:10:00	01:20:00	
6	CHP	CC114	BRS not healthy found return cable damaged	Jointing done then ok	22:35:00	22:45:00	
7	CHP	CC131	Tripped on over load due to over load due to deck sheets informed to operation(4 times)	Reset done	03:35:00	03:40:00	
8	CHP	CC54	Over load acted due to jamming ( 4 times)	Reset done	22:35:00	22:40:00	
9	CHP	CC44	OLR acted 2 times checked belt is in over load	Informed to operation and olr reset done	00:00:00 01:10:00 03:00:00	00:20:00 01:35:00 03:05:00	
10	CHP	SCR2 on CC35	LT not working found over tension limit acted	Reset done then ok	05:20:00 23:50:00	05:40:00 00:10:00	
11	CHP	SCR5 on CC32	LT not working found PCRD over load relay acted	Reset done	05:15:00	05:25:00	



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/05/2025

Incharge(s): V Balaji Naik,G Eswara Rao

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	WT	CT1 Inhaul	Over load acted	Reset done	22:30:00	22:40:00	
13	WT	OT1	Not rotating found drive2 tripped on PGF1 fault	Reset done	02:50:00	03:00:00	