



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/06/2025

Shift: A

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO11	Over load trip	Reset done	10:10:00	10:15:00	
2	OHP	Co11	MPCB tripped due to over load trip	Reset done	07:15:00	07:25:00	
3	OHP	TT1A flap gate	OLR acted reset done	Then ok	08:00:00	08:45:00	
4	OHP	BRC on Co26	Slewing not working found drive over load acated	Reset done	07:30:00	07:45:00	
5	OHP	CO9	Tripped in over load	Reset done	12:30:00	12:45:00	
6	CHP	CC131	Over load trip 3 times due to over load	Informed operation and reset done	07:30:00 08:00:00 08:15:00	07:35:00 08:05:00 08:20:00	
7	CHP	CC54	Over load acted	Reset done	06:15:00	06:20:00	
8	CHP	CC113 TIS	Bypassed as per operation request	Done	13:00:00	13:10:00	
9	CHP	CC29	TT flap tripped	Reset done	09:20:00	09:30:00	
10	CHP	SCR5 on CC32	LT not working found MPCB 4 tripped	Reset done	06:25:00	06:35:00	
11	CHP	All machines signal problem CCR	PLC micrologix replaced and IP sddress of PLC micrologix changed	Few mac addresses removed setting in Esteem modem changed to access from all to fixed given mac adresses	08:30:00 13:15:00	12:30:00 13:30:00	
12	CHP	R1 on CC31	GVM side position not showing in CCR	Bypassed in programm and gate way also changed	10:30:00	10:45:00	
13	WT	OC1a	Over load acted	Reset done	09:05:00	09:10:00	



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/06/2025

Incharge(s): V Balaji Naik

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	OP1	Not moving in reverse found jamming informed to operation	Breaker tripped in LC 2a made on	11:30:00	11:35:00	
15	WT	CO4 Carriage	Carriage drive tripped	Reset done	11:00:00	11:10:00	