



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 11/06/2025

Shift: A

Incharge(s): V Balaji Naik

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|--|--|----------|----------|---------|
| 1 | OHP | CO9 | Electronic olr trip | Reset done | 12:00:00 | 12:10:00 | |
| 2 | CHP | SCR3 on CC38 | Lower luffing limit bypassed as per operational request | After finishing reclaiming put back in ckt | 09:50:00 | 10:20:00 | |
| 3 | CHP | CC33 | No t healthy found olr acted | Reset done | 10:00:00 | 10:05:00 | |
| 4 | CHP | SCR5 on CC32 | MCCB tripped chute jammed BC offcentering | Informed to mechanical regarding jamming of deck sheets after that made on | 06:45:00 | 07:00:00 | |
| 5 | CHP | SCR6 on CC40 | slewing not working found jamming in slewing pinion area | Informed to operation after cleaning found healthy | 07:05:00 | 07:15:00 | |
| 6 | CHP | CC201 | relay tripped | Reset done | 06:20:00 | 06:30:00 | |
| 7 | CHP | SCR5 on CC32 | LT not working found drive tripped on over load | Reset done | 08:00:00 | 08:10:00 | |
| 8 | CHP | R1 on CC31 | BC not running found coal struck in ZSS cage | Coal removed then ok | 08:00:00 | 08:20:00 | |
| 9 | CHP | CC44 | OLR tripped due to jamming | informed to operation for cleaning Reset done | 09:25:00 | 10:30:00 | |
| 10 | CHP | SCR1 on CC36 | Luffing upper limit struck | made released then ok | 13:20:00 | 13:30:00 | |
| 11 | CHP | SCR10 on CC105 | BC not running found nothig | Reset done in panel then ok | 12:10:00 | 12:40:00 | |
| 12 | CHP | SCR8 on CC112 | Wrong complaint | cleared | 11:05:00 | 11:15:00 | |
| 13 | CHP | CC51 | olr tripped | Reset done | 10:25:00 | 10:30:00 | |
| 14 | CHP | CC54 | olr tripped 3 times | Reset done | 11:30:00 | 12:15:00 | |
| 15 | CHP | CC131 | olr tripped 2 times | Reset done | 10:45:00 | 11:20:00 | |