



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/06/2025

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO21	LT NOT TAKING PLACE M1 M3 OLR ACTED	RESET	08:00:00	08:20:00	
2	OHP	CO 29	OLR ACTED (2TIMES)	RESET	10:10:00	11:20:00	
3	OHP	BRC ON CO28	CT NOT TAKING PLACE MCC SIDE LIMIT STUCK UP	LIMIT SWITCH FREE IT AND WIRES TIGHT	10:30:00	10:50:00	
4	OHP	BRC ON CO28	B/C OLR ACTED	RESET	11:45:00	12:00:00	
5	OHP	TBS ON CO7A	LUFFING OLR ACTED	RESET AND BRAKE ADJUSTED BY MECH	10:40:00	10:50:00	
6	OHP	TBSONCO 7A	B/C AND LT NOTWORKING	B/C OLR REST AND BOOM KEPT IN RECLIMING HIGHT THAN LT OK	11:15:00	11:40:00	
7	CHP	CC 36 SCR1	slew not working,30 degree limit acted in left	limit released than ok	06:55:00	07:10:00	
8	CHP	CC 203	stop button pressed	released	07:10:00	07:15:00	
9	CHP	CC 31	OLr acted in cc 51 feeding conveyor	reset	08:30:00	08:35:00	
10	CHP	CC 33 SCR4	BC not working,zss acted,coal piece stuck in zss	zss cage cleaned	08:50:00	09:10:00	
11	CHP	CC 44	OLR acted	reset	11:48:00	11:53:00	
12	CHP	CC 125	olr acted	reset it done	10:30:00	10:40:00	
13	CHP	CC 51	OLR acted	reset it done	08:30:00	08:35:00	4 times
14	CHP	CC 54	motor trips in olr	reset it done	06:52:00	06:58:00	
15	CHP	CC 131	OLR acted	reset it done	08:15:00	08:30:00	



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/06/2025

Incharge(s): K SANKARA RAO

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
16	CHP	RG2 zss problem	pending from c shift ,module ok	setting changed than ok	06:30:00	06:50:00	
17	CHP	CC 26 A	not running,position sensor not showing on CC 38,operator selected HMI operation remote in route mode	checked and found all bit ok,position sensor bit is in program, told operator to kept in manual mode HMI operation remote .	11:20:00	12:20:00	
18	CHP	CC 13	ZSS acted,zss cage bolt loose,an sensor problem	cage adjusted, bolt tightened, probe replaced	09:00:00	09:30:00	
19	CHP	CC 25	olr acted	reset it	11:10:00	11:20:00	
20	WT	CP 1 and 4	no movement,communication probelm,poe was damaged in CT cabin	POE replaced in CT cabin, wireless power recycle done	10:25:00	10:45:00	
21	WT	OP5 and OP 6	no power i/c tripped	made it on	11:40:00	12:00:00	