



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 03/02/2026

Area: OHP

| Equipment  | Job   |
|--|---|
| co-41a,50,53,56 h/e hoists                                       | motor and panel side ppm is done.   |
| VF-16a chute vibrator  | bed bolts got loose, fixed them properly.   |
| OCR telecom room   | Exchange room sump pump is not working, spare pump is put and de watering was started.                    |
| rsco-6a,<br>co-10a,rsco-1a,rsco-2a,13a ;<br>bf-1a,2a,3a,4a,7a,8a | bss circuit is checked and found ok.  |
| co-8a,30,31,32,37a,65,69,70                                      | chute vibrators inspection is done, found working in auto mode as well.                                   |
| DE-23  | OM-16 panel side blowing done and megger values of fan motor are recorded , trail run needs to be taken . |
| co-34  | motor side half coupling was found damaged, changed coupling and fixed back in position.                  |
| wobr-3 on co-26  | crmp side slew limit striker was missing, welded new one in its place.                                    |
| co-8a, db-1, CO-17,18 ; co-31,32<br>; co-36b,rcs-2a              | motor and panel side ppm is done  |
| de-101   | ral-1, chp side ral motor faulty, disconnected.   |
| brc-4 on co-28   | Slip Ring B phase lug got cut , cleaning done at slipring box, re lug done and charged brc.               |
| co-10a   | jod kept in circuit after switch replacement.   |