



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 05/06/2025

Area: IOSA

Equipment	Job
OJH-4C	POWER CONTACTOR NOT GETTING ON IN ELECTRICAL HOIST. SWITCH PROBLEM IN PENDENT.
OJH-2A	ELECTRICAL HOIST FUNCTION NOT TAKING PLACE FROM PENDENT. DEFECT RECTIFIED AND CHECKED.
OC-23A	OC-23A TO OC-25A CHUTE VIBRATOR MOTOR CABLE GOT DAMAGED . CABLE JOINT AND CHECKED.
OC-23A	MPCB DEFECTIVE.REPLACED IN ELECTRICAL HOIST. TRIAL RUN TAKEN.
OC-16A and OC-17A	PPM DONE ON MOTOR