



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/05/2025

Incharge(s): K SANKARA RAO

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|------------|---------------------------------------|-------------------------------|----------|----------|---------|
| 1 | OHP | CO34 | OLR ACTED | RESET | 11:00:00 | 11:10:00 | |
| 2 | OHP | BF1A | STOPPING ON ZS | ZS PROBE GAP ADJUSTED THAN OK | 13:40:00 | 14:00:00 | |
| 3 | CHP | CC39 SCR 7 | ADEPTER PROBLEM | ADEPTOR CHANGED THAN OK | 07:10:00 | 07:25:00 | |
| 4 | CHP | CC112 R1 | SIGNAL MISSING | LT FORWARD MOVED THAN OK | 06:40:00 | 07:00:00 | |
| 5 | CHP | CC31 S3 | LT NOT MOVING POWER AND OFF CONDITION | BOTH ARE MADE ON | 10:40:00 | 11:00:00 | |
| 6 | CHP | CC35 SCR 2 | NOT SHOWING RECLAIMING MODE | PLC SUPPLY RECYCLE DONE | 11:30:00 | 11:52:00 | |
| 7 | CHP | CC35 SCR 2 | SLEW NOT WORKING DRIVE TRIPPED | RESET | 12:50:00 | 13:10:00 | |
| 8 | CHP | CC44 | OLR ACTED | RESET | 12:00:00 | 12:10:00 | |
| 9 | CHP | cc 39 | OLR ACTED | RESET | 13:35:00 | 13:45:00 | |
| 10 | WT | OP 2 | D1 OLR ACTED | RESET | 07:50:00 | 08:00:00 | |