



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/11/2025

Shift: B

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|------------------------------|--|----------|----------|------------------------|
| 1 | OHP | WOBR on CO-6A | B/C stopping on ZSS | ZSS probe damaged.Replaced | 15:30:00 | 15:50:00 | |
| 2 | OHP | CO-13 | Reported Tripped | OLR acted.Reset done | 17:10:00 | 17:20:00 | |
| 3 | OHP | CO-37A | Reported healthy stop | Contactar arc chute problem.Rectified | 15:15:00 | 15:35:00 | |
| 4 | OHP | BRC on CO-30 | B/C stopping | OLR acted(6 times).Reset done | 17:50:00 | 19:00:00 | |
| 5 | OHP | CO-85 | Reported tripped | OLR acted.Reset done | 18:25:00 | 19:45:00 | |
| 6 | OHP | CO-16 | BRS not healthy | Fuse blown in C.Jb.Replaced | 18:30:00 | 18:40:00 | |
| 7 | OHP | CO-29 | Reported tripped | OLR acted.Reset done | 20:10:00 | 20:20:00 | |
| 8 | OHP | RSCO-10A(C/D) | MPCB tripped | Reset done | 16:35:00 | 16:45:00 | |
| 9 | CHP | CC-51 | MPD tripped | REset done | 15:40:00 | 15:45:00 | |
| 10 | CHP | CC-52 | Reported tripped | OLR acted.Reset done | 21:54:00 | 21:58:00 | |
| 11 | CHP | CC105 scr 10 | SLEW and B/W not working | E pb acted.Released and tested okay | 17:20:00 | 17:35:00 | |
| 12 | CHP | CC014 SCR-9 | Reported slewing not working | OIL level low. | 19:02:00 | 20:30:00 | Informed to mechanical |
| 13 | CHP | CC-32 R-1 | Luffing down not working | Oil level low. air locked | 20:48:00 | 21:26:00 | Informed to mechanical |
| 14 | CHP | CC39 SCR-1 | B/c not working | cage made down and given for reclaiming.Rectified in program and removed ZSS | 21:30:00 | 21:40:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 06/11/2025

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------------------------|----------------------------------|------------------------------|----------|----------|---------|
| 15 | CHP | CC-125 | OLR acted | Reset done | 20:30:00 | 20:35:00 | |
| 16 | CHP | CC-45 | OLR acted | Reset done(3 times) | 16:00:00 | 17:20:00 | |
| 17 | CHP | CC-38 SCR-6 | Reported LT not working | Drive tripped.Reset done | 20:12:00 | 20:25:00 | |
| 18 | CHP | CC-28 position on CC-31 | Sensor problem | Bypassed | 14:10:00 | 14:20:00 | |
| 19 | WT | OT-1 | Drive 1 tripped on PGEF fault | Reset done | 20:30:00 | 20:35:00 | |
| 20 | WT | OT-3 | DRive 1 tripped on encoder fault | REset done | 21:40:00 | 21:45:00 | |
| 21 | IOSA | OC-21A | Reported ZSS acting | ZSS cage stuck up with stone | 20:00:00 | 20:15:00 | |