

| Reading # | Job               | Room        | Side | Component     | Substrate | Condition    | Color | Result   | PbC  | Units  |
|-----------|-------------------|-------------|------|---------------|-----------|--------------|-------|----------|------|--------|
| 1         | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 2         | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 3         | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 4         | 18045 NC Hwy 87 W | Living Room | A    | Wall          | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 5         | 18045 NC Hwy 87 W | Living Room | A    | Ceiling       | Wood      | Intact       | White | Negative | -0.1 | mg/cm2 |
| 6         | 18045 NC Hwy 87 W | Living Room | A    | Crown Molding | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 7         | 18045 NC Hwy 87 W | Living Room | A    | Baseboard     | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 8         | 18045 NC Hwy 87 W | Living Room | A    | Door          | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 9         | 18045 NC Hwy 87 W | Living Room | A    | Door Casing   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 10        | 18045 NC Hwy 87 W | Living Room | A    | Window Sash   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 11        | 18045 NC Hwy 87 W | Living Room | A    | Window Casing | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 12        | 18045 NC Hwy 87 W | Living Room | A    | Window Sill   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 13        | 18045 NC Hwy 87 W | Dining Room | A    | Wall          | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 14        | 18045 NC Hwy 87 W | Dining Room | C    | Crown Molding | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 15        | 18045 NC Hwy 87 W | Dining Room | C    | Baseboard     | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 16        | 18045 NC Hwy 87 W | Dining Room | C    | Door          | Wood      | Deteriorated | White | Negative | 0.2  | mg/cm2 |
| 17        | 18045 NC Hwy 87 W | Dining Room | C    | Door Jamb     | Wood      | Deteriorated | White | Negative | 0.3  | mg/cm2 |
| 18        | 18045 NC Hwy 87 W | Dining Room | C    | Door Casing   | Wood      | Deteriorated | White | Negative | 0.3  | mg/cm2 |
| 19        | 18045 NC Hwy 87 W | Kitchen     | B    | Wall          | Wood      | Intact       | Brown | Negative | 0.2  | mg/cm2 |
| 20        | 18045 NC Hwy 87 W | Kitchen     | B    | Baseboard     | Wood      | Intact       | Brown | Negative | 0.2  | mg/cm2 |
| 21        | 18045 NC Hwy 87 W | Kitchen     | D    | Window Sash   | Wood      | Intact       | Brown | Negative | 0.3  | mg/cm2 |
| 22        | 18045 NC Hwy 87 W | Kitchen     | D    | Window Casing | Wood      | Intact       | Brown | Negative | 0.1  | mg/cm2 |
| 23        | 18045 NC Hwy 87 W | Kitchen     | D    | Window Sill   | Wood      | Intact       | Brown | Negative | 0.5  | mg/cm2 |
| 24        | 18045 NC Hwy 87 W | Kitchen     | C    | Door Casing   | Wood      | Intact       | Brown | Negative | 0.4  | mg/cm2 |
| 25        | 18045 NC Hwy 87 W | Den         | C    | Door Casing   | Wood      | Intact       | Brown | Negative | 0.4  | mg/cm2 |
| 26        | 18045 NC Hwy 87 W | Den         | C    | Door Casing   | Wood      | Deteriorated | Brown | Negative | 0.3  | mg/cm2 |
| 27        | 18045 NC Hwy 87 W | Den         | C    | Door Jamb     | Wood      | Deteriorated | Brown | Negative | 0.2  | mg/cm2 |
| 28        | 18045 NC Hwy 87 W | Den         | C    | Window Sash   | Wood      | Intact       | Brown | Negative | 0.3  | mg/cm2 |
| 29        | 18045 NC Hwy 87 W | Den         | C    | Window Casing | Wood      | Intact       | Brown | Negative | 0.0  | mg/cm2 |
| 30        | 18045 NC Hwy 87 W | Den         | C    | Window Sill   | Wood      | Intact       | Brown | Negative | 0.0  | mg/cm2 |
| 31        | 18045 NC Hwy 87 W | Den         | C    | Baseboard     | Wood      | Intact       | Brown | Negative | 0.0  | mg/cm2 |
| 32        | 18045 NC Hwy 87 W | Bedroom 3   | D    | Wall          | Wood      | Intact       | Beige | Negative | 0.0  | mg/cm2 |
| 33        | 18045 NC Hwy 87 W | Bedroom 3   | D    | Crown Molding | Wood      | Intact       | Beige | Negative | 0.1  | mg/cm2 |
| 34        | 18045 NC Hwy 87 W | Bedroom 3   | D    | Baseboard     | Wood      | Intact       | Beige | Negative | 0.2  | mg/cm2 |
| 35        | 18045 NC Hwy 87 W | Bedroom 3   | D    | Door Jamb     | Wood      | Intact       | Beige | Negative | 0.4  | mg/cm2 |
| 36        | 18045 NC Hwy 87 W | Bedroom 3   | D    | Door Casing   | Wood      | Intact       | Beige | Negative | 0.2  | mg/cm2 |
| 37        | 18045 NC Hwy 87 W | Bedroom 3   | B    | Window Sash   | Wood      | Intact       | Beige | Negative | 0.0  | mg/cm2 |
| 38        | 18045 NC Hwy 87 W | Bedroom 3   | B    | Window Casing | Wood      | Intact       | Beige | Negative | 0.1  | mg/cm2 |
| 39        | 18045 NC Hwy 87 W | Bedroom 3   | B    | Window Sill   | Wood      | Intact       | Beige | Negative | 0.0  | mg/cm2 |
| 40        | 18045 NC Hwy 87 W | Bedroom 2   | C    | Wall          | Wood      | Intact       | Beige | Negative | 0.1  | mg/cm2 |
| 41        | 18045 NC Hwy 87 W | Bedroom 2   | C    | Crown Molding | Wood      | Intact       | Beige | Negative | -0.2 | mg/cm2 |
| 42        | 18045 NC Hwy 87 W | Bedroom 2   | C    | Baseboard     | Wood      | Intact       | Beige | Negative | 0.2  | mg/cm2 |
| 43        | 18045 NC Hwy 87 W | Bedroom 2   | C    | Door          | Wood      | Intact       | Beige | Negative | 0.2  | mg/cm2 |
| 44        | 18045 NC Hwy 87 W | Bedroom 2   | C    | Door Jamb     | Wood      | Intact       | Beige | Negative | 0.2  | mg/cm2 |
| 45        | 18045 NC Hwy 87 W | Bedroom 2   | C    | Door Casing   | Wood      | Intact       | Beige | Negative | 0.2  | mg/cm2 |
| 46        | 18045 NC Hwy 87 W | Bedroom 2   | A    | Window Sash   | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 47        | 18045 NC Hwy 87 W | Bedroom 2   | A    | Window Sash   | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 48        | 18045 NC Hwy 87 W | Bedroom 2   | A    | Window Sill   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 49        | 18045 NC Hwy 87 W | Bathroom    | C    | Wall          | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 50        | 18045 NC Hwy 87 W | Bathroom    | C    | Baseboard     | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 51        | 18045 NC Hwy 87 W | Bathroom    | C    | Door          | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 52        | 18045 NC Hwy 87 W | Bathroom    | C    | Door Jamb     | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 53        | 18045 NC Hwy 87 W | Bathroom    | C    | Door Casing   | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 54        | 18045 NC Hwy 87 W | Bathroom    | C    | Window Sash   | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 55        | 18045 NC Hwy 87 W | Bathroom    | C    | Window Casing | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 56        | 18045 NC Hwy 87 W | Bathroom    | C    | Window Sill   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 57        | 18045 NC Hwy 87 W | Bedroom 1   | D    | Wall          | Wood      | Intact       | White | Negative | 0.2  | mg/cm2 |
| 58        | 18045 NC Hwy 87 W | Bedroom 1   | D    | Crown Molding | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 59        | 18045 NC Hwy 87 W | Bedroom 1   | D    | Door          | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 60        | 18045 NC Hwy 87 W | Bedroom 1   | D    | Door Jamb     | Wood      | Intact       | White | Negative | 0.0  | mg/cm2 |
| 61        | 18045 NC Hwy 87 W | Bedroom 1   | D    | Door Casing   | Wood      | Intact       | White | Negative | 0.3  | mg/cm2 |
| 62        | 18045 NC Hwy 87 W | Bedroom 1   | A    | Window Sash   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 63        | 18045 NC Hwy 87 W | Bedroom 1   | A    | Window Casing | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 64        | 18045 NC Hwy 87 W | Bedroom 1   | A    | Window Sill   | Wood      | Intact       | White | Negative | 0.1  | mg/cm2 |
| 65        | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 66        | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 67        | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 68        | 18045 NC Hwy 87 W | House       | A    | Door          | Wood      | Deteriorated | White | Positive | 4.3  | mg/cm2 |
| 69        | 18045 NC Hwy 87 W | House       | A    | Door Casing   | Metal     | Intact       | White | Positive | 3.9  | mg/cm2 |
| 70        | 18045 NC Hwy 87 W | House       | A    | Window Casing | Metal     | Intact       | White | Positive | 3.1  | mg/cm2 |
| 71        | 18045 NC Hwy 87 W | House       | A    | Window Sill   | Metal     | Intact       | White | Negative | 0.6  | mg/cm2 |
| 72        | 18045 NC Hwy 87 W | House       | A    | Fascia        | Metal     | Intact       | White | Negative | 0.2  | mg/cm2 |
| 73        | 18045 NC Hwy 87 W | House       | A    | Wall          | Metal     | Intact       | White | Positive | 1.9  | mg/cm2 |
| 74        | 18045 NC Hwy 87 W | House       | B    | Wall          | Metal     | Intact       | White | Negative | 0.1  | mg/cm2 |
| 75        | 18045 NC Hwy 87 W | House       | B    | Window Casing | Metal     | Intact       | White | Negative | 0.0  | mg/cm2 |
| 76        | 18045 NC Hwy 87 W | House       | C    | Window Casing | Metal     | Intact       | White | Negative | 0.1  | mg/cm2 |
| 77        | 18045 NC Hwy 87 W | House       | C    | Window Sill   | Metal     | Intact       | White | Negative | 0.1  | mg/cm2 |
| 78        | 18045 NC Hwy 87 W | House       | C    | Wall          | Metal     | Intact       | White | Negative | 0.1  | mg/cm2 |
| 79        | 18045 NC Hwy 87 W | House       | D    | Wall          | Metal     | Intact       | White | Positive | 1.4  | mg/cm2 |
| 80        | 18045 NC Hwy 87 W | House       | D    | Window Casing | Metal     | Intact       | White | Positive | 3.8  | mg/cm2 |
| 81        | 18045 NC Hwy 87 W | House       | D    | Window Sill   | Metal     | Intact       | White | Positive | 2.4  | mg/cm2 |
| 82        | 18045 NC Hwy 87 W | Front Porch | A    | Porch Ceiling | Vinyl     | Intact       | White | Positive | 1.1  | mg/cm2 |
| 83        | 18045 NC Hwy 87 W | Front Porch | A    | Porch Header  | Vinyl     | Intact       | White | Positive | 1.8  | mg/cm2 |
| 84        | 18045 NC Hwy 87 W | Front Porch | A    | Porch Column  | Metal     | Intact       | Black | Negative | 0.3  | mg/cm2 |
| 85        | 18045 NC Hwy 87 W | Front Porch | A    | Porch Floor   | Wood      | Deteriorated | Grey  | Negative | 0.3  | mg/cm2 |
| 86        | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 87        | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |
| 88        | 18045 NC Hwy 87 W | Calibration |      |               |           |              |       | Positive | 1.0  | mg/cm2 |