

Reading #	Job	Room	Side	Component	Substrate	Condition	Color	Result	PbC	Units
1	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
2	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
3	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
4	18045 NC Hwy 87 W	Living Room	A	Wall	Wood	Intact	White	Negative	0.1	mg/cm2
5	18045 NC Hwy 87 W	Living Room	A	Ceiling	Wood	Intact	White	Negative	-0.1	mg/cm2
6	18045 NC Hwy 87 W	Living Room	A	Crown Molding	Wood	Intact	White	Negative	0.1	mg/cm2
7	18045 NC Hwy 87 W	Living Room	A	Baseboard	Wood	Intact	White	Negative	0.2	mg/cm2
8	18045 NC Hwy 87 W	Living Room	A	Door	Wood	Intact	White	Negative	0.2	mg/cm2
9	18045 NC Hwy 87 W	Living Room	A	Door Casing	Wood	Intact	White	Negative	0.1	mg/cm2
10	18045 NC Hwy 87 W	Living Room	A	Window Sash	Wood	Intact	White	Negative	0.1	mg/cm2
11	18045 NC Hwy 87 W	Living Room	A	Window Casing	Wood	Intact	White	Negative	0.2	mg/cm2
12	18045 NC Hwy 87 W	Living Room	A	Window Sill	Wood	Intact	White	Negative	0.1	mg/cm2
13	18045 NC Hwy 87 W	Dining Room	A	Wall	Wood	Intact	White	Negative	0.2	mg/cm2
14	18045 NC Hwy 87 W	Dining Room	C	Crown Molding	Wood	Intact	White	Negative	0.1	mg/cm2
15	18045 NC Hwy 87 W	Dining Room	C	Baseboard	Wood	Intact	White	Negative	0.2	mg/cm2
16	18045 NC Hwy 87 W	Dining Room	C	Door	Wood	Deteriorated	White	Negative	0.2	mg/cm2
17	18045 NC Hwy 87 W	Dining Room	C	Door Jamb	Wood	Deteriorated	White	Negative	0.3	mg/cm2
18	18045 NC Hwy 87 W	Dining Room	C	Door Casing	Wood	Deteriorated	White	Negative	0.3	mg/cm2
19	18045 NC Hwy 87 W	Kitchen	B	Wall	Wood	Intact	Brown	Negative	0.2	mg/cm2
20	18045 NC Hwy 87 W	Kitchen	B	Baseboard	Wood	Intact	Brown	Negative	0.2	mg/cm2
21	18045 NC Hwy 87 W	Kitchen	D	Window Sash	Wood	Intact	Brown	Negative	0.3	mg/cm2
22	18045 NC Hwy 87 W	Kitchen	D	Window Casing	Wood	Intact	Brown	Negative	0.1	mg/cm2
23	18045 NC Hwy 87 W	Kitchen	D	Window Sill	Wood	Intact	Brown	Negative	0.5	mg/cm2
24	18045 NC Hwy 87 W	Kitchen	C	Door Casing	Wood	Intact	Brown	Negative	0.4	mg/cm2
25	18045 NC Hwy 87 W	Den	C	Door Casing	Wood	Intact	Brown	Negative	0.4	mg/cm2
26	18045 NC Hwy 87 W	Den	C	Door Casing	Wood	Deteriorated	Brown	Negative	0.3	mg/cm2
27	18045 NC Hwy 87 W	Den	C	Door Jamb	Wood	Deteriorated	Brown	Negative	0.2	mg/cm2
28	18045 NC Hwy 87 W	Den	C	Window Sash	Wood	Intact	Brown	Negative	0.3	mg/cm2
29	18045 NC Hwy 87 W	Den	C	Window Casing	Wood	Intact	Brown	Negative	0.0	mg/cm2
30	18045 NC Hwy 87 W	Den	C	Window Sill	Wood	Intact	Brown	Negative	0.0	mg/cm2
31	18045 NC Hwy 87 W	Den	C	Baseboard	Wood	Intact	Brown	Negative	0.0	mg/cm2
32	18045 NC Hwy 87 W	Bedroom 3	D	Wall	Wood	Intact	Beige	Negative	0.0	mg/cm2
33	18045 NC Hwy 87 W	Bedroom 3	D	Crown Molding	Wood	Intact	Beige	Negative	0.1	mg/cm2
34	18045 NC Hwy 87 W	Bedroom 3	D	Baseboard	Wood	Intact	Beige	Negative	0.2	mg/cm2
35	18045 NC Hwy 87 W	Bedroom 3	D	Door Jamb	Wood	Intact	Beige	Negative	0.4	mg/cm2
36	18045 NC Hwy 87 W	Bedroom 3	D	Door Casing	Wood	Intact	Beige	Negative	0.2	mg/cm2
37	18045 NC Hwy 87 W	Bedroom 3	B	Window Sash	Wood	Intact	Beige	Negative	0.0	mg/cm2
38	18045 NC Hwy 87 W	Bedroom 3	B	Window Casing	Wood	Intact	Beige	Negative	0.1	mg/cm2
39	18045 NC Hwy 87 W	Bedroom 3	B	Window Sill	Wood	Intact	Beige	Negative	0.0	mg/cm2
40	18045 NC Hwy 87 W	Bedroom 2	C	Wall	Wood	Intact	Beige	Negative	0.1	mg/cm2
41	18045 NC Hwy 87 W	Bedroom 2	C	Crown Molding	Wood	Intact	Beige	Negative	-0.2	mg/cm2
42	18045 NC Hwy 87 W	Bedroom 2	C	Baseboard	Wood	Intact	Beige	Negative	0.2	mg/cm2
43	18045 NC Hwy 87 W	Bedroom 2	C	Door	Wood	Intact	Beige	Negative	0.2	mg/cm2
44	18045 NC Hwy 87 W	Bedroom 2	C	Door Jamb	Wood	Intact	Beige	Negative	0.2	mg/cm2
45	18045 NC Hwy 87 W	Bedroom 2	C	Door Casing	Wood	Intact	Beige	Negative	0.2	mg/cm2
46	18045 NC Hwy 87 W	Bedroom 2	A	Window Sash	Wood	Intact	White	Negative	0.2	mg/cm2
47	18045 NC Hwy 87 W	Bedroom 2	A	Window Sash	Wood	Intact	White	Negative	0.0	mg/cm2
48	18045 NC Hwy 87 W	Bedroom 2	A	Window Sill	Wood	Intact	White	Negative	0.1	mg/cm2
49	18045 NC Hwy 87 W	Bathroom	C	Wall	Wood	Intact	White	Negative	0.1	mg/cm2
50	18045 NC Hwy 87 W	Bathroom	C	Baseboard	Wood	Intact	White	Negative	0.0	mg/cm2
51	18045 NC Hwy 87 W	Bathroom	C	Door	Wood	Intact	White	Negative	0.1	mg/cm2
52	18045 NC Hwy 87 W	Bathroom	C	Door Jamb	Wood	Intact	White	Negative	0.0	mg/cm2
53	18045 NC Hwy 87 W	Bathroom	C	Door Casing	Wood	Intact	White	Negative	0.0	mg/cm2
54	18045 NC Hwy 87 W	Bathroom	C	Window Sash	Wood	Intact	White	Negative	0.0	mg/cm2
55	18045 NC Hwy 87 W	Bathroom	C	Window Casing	Wood	Intact	White	Negative	0.1	mg/cm2
56	18045 NC Hwy 87 W	Bathroom	C	Window Sill	Wood	Intact	White	Negative	0.1	mg/cm2
57	18045 NC Hwy 87 W	Bedroom 1	D	Wall	Wood	Intact	White	Negative	0.2	mg/cm2
58	18045 NC Hwy 87 W	Bedroom 1	D	Crown Molding	Wood	Intact	White	Negative	0.0	mg/cm2
59	18045 NC Hwy 87 W	Bedroom 1	D	Door	Wood	Intact	White	Negative	0.0	mg/cm2
60	18045 NC Hwy 87 W	Bedroom 1	D	Door Jamb	Wood	Intact	White	Negative	0.0	mg/cm2
61	18045 NC Hwy 87 W	Bedroom 1	D	Door Casing	Wood	Intact	White	Negative	0.3	mg/cm2
62	18045 NC Hwy 87 W	Bedroom 1	A	Window Sash	Wood	Intact	White	Negative	0.1	mg/cm2
63	18045 NC Hwy 87 W	Bedroom 1	A	Window Casing	Wood	Intact	White	Negative	0.1	mg/cm2
64	18045 NC Hwy 87 W	Bedroom 1	A	Window Sill	Wood	Intact	White	Negative	0.1	mg/cm2
65	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
66	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
67	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
68	18045 NC Hwy 87 W	House	A	Door	Wood	Deteriorated	White	Positive	4.3	mg/cm2
69	18045 NC Hwy 87 W	House	A	Door Casing	Metal	Intact	White	Positive	3.9	mg/cm2
70	18045 NC Hwy 87 W	House	A	Window Casing	Metal	Intact	White	Positive	3.1	mg/cm2
71	18045 NC Hwy 87 W	House	A	Window Sill	Metal	Intact	White	Negative	0.6	mg/cm2
72	18045 NC Hwy 87 W	House	A	Fascia	Metal	Intact	White	Negative	0.2	mg/cm2
73	18045 NC Hwy 87 W	House	A	Wall	Metal	Intact	White	Positive	1.9	mg/cm2
74	18045 NC Hwy 87 W	House	B	Wall	Metal	Intact	White	Negative	0.1	mg/cm2
75	18045 NC Hwy 87 W	House	B	Window Casing	Metal	Intact	White	Negative	0.0	mg/cm2
76	18045 NC Hwy 87 W	House	C	Window Casing	Metal	Intact	White	Negative	0.1	mg/cm2
77	18045 NC Hwy 87 W	House	C	Window Sill	Metal	Intact	White	Negative	0.1	mg/cm2
78	18045 NC Hwy 87 W	House	C	Wall	Metal	Intact	White	Negative	0.1	mg/cm2
79	18045 NC Hwy 87 W	House	D	Wall	Metal	Intact	White	Positive	1.4	mg/cm2
80	18045 NC Hwy 87 W	House	D	Window Casing	Metal	Intact	White	Positive	3.8	mg/cm2
81	18045 NC Hwy 87 W	House	D	Window Sill	Metal	Intact	White	Positive	2.4	mg/cm2
82	18045 NC Hwy 87 W	Front Porch	A	Porch Ceiling	Vinyl	Intact	White	Positive	1.1	mg/cm2
83	18045 NC Hwy 87 W	Front Porch	A	Porch Header	Vinyl	Intact	White	Positive	1.8	mg/cm2
84	18045 NC Hwy 87 W	Front Porch	A	Porch Column	Metal	Intact	Black	Negative	0.3	mg/cm2
85	18045 NC Hwy 87 W	Front Porch	A	Porch Floor	Wood	Deteriorated	Grey	Negative	0.3	mg/cm2
86	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
87	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2
88	18045 NC Hwy 87 W	Calibration						Positive	1.0	mg/cm2