

SECURITE

231500 UTC NOV 25

NAVAREA IX 547/25

BUOY REPLACED CANCEL NAVAREA IX

082/25 AND THIS MSG

-----  
221500 UTC NOV 25

NAVAREA IX 546/25

PERSIAN GULF, KHOWR E MUSA

IRAN

CHARTS GB 2884 (INT 7278) AND ENC IR308760

CHANNEL ESTABLISHED FROM PORT HAND BOUY NO 14 TO PORT  
HAND BEACON NO 32 WITH DEPTH 9M AND LENGTH 14.5NM

JOINING FOLLOWING COORDINATES:

1. 29-54.51N 049-09.68E
2. 29-57.00N 049-05.14E
3. 30-00.18N 049.01.55E
4. 30-05.35N 048-59.32E
5. 30-05.41N 048-59.49E
6. 30-04.60N 048-59.91E
7. 30-00.30N 049-01.76E
8. 29-57.15N 049-05.31E
9. 29-54.69N 049-09.82E

MARINERS CAUTIONED

-----  
221500 UTC NOV 25

NAVAREA IX 545/25

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751), BA 38, 39 AND 707

1. NAVAL SHIPS WILL CONDUCT LIVE FIRING BETWEEN 0200-0900 UTC  
ON 25 AND 26 NOV 25 IN AREA BOUNDED BY FOLLOWING COORDINATES:

24-13.51N 067-06.78E

24-23.64N 067-09.67E

25-18.00N 063-38.00E

25-07.00N 063-35.00E

MARINERS CAUTIONED

2. CANCEL THIS MSG 261000 UTC NOV 25

-----  
220300 UTC NOV 25

NAVAREA IX 544/25

SELF CANCELLING

NAVIGATIONAL WARNINGS INFORCE:

2021 SERIES: 109, 397, 399, 445, 448, 490 AND 491

2022 SERIES: 027, 039, 067, 095, 102, 112, 185, 198, 220, 294, 295,  
311, 328, 331, 358, 443, 477, 480, 489, 497, 507 AND 513

2023 SERIES: 028, 034, 058, 067, 068, 071, 094, 096, 111, 116, 159,

177, 190, 221, 226, 293, 307, 314, 318, 326, 338, 341, 346, 355, 376, 435, 447, 448, 453 AND 475

2024 SERIES: 042, 048, 076, 094, 103, 115, 130, 132, 139, 140, 141, 163, 168, 198, 200, 240, 250, 253, 267, 281, 285, 288, 289, 299, 311, 329, 333, 340, 361, 362, 363, 365, 382, 399, 402, 403, 432, 452, 468, 470, 476, 486, 488, 501, 509, 519, 529 AND 531

2025 SERIES: 002, 006, 014, 018, 021, 024, 047, 063, 066, 071, 082, 090, 094, 101, 111, 147, 158, 176, 185, 216, 218, 227, 246, 250, 254, 256, 261, 267, 272, 280, 287, 289, 292, 297, 300, 321, 325, 328, 331, 332, 335, 339, 349, 352, 353, 356, 365, 375, 377, 379, 387, 388, 399, 405, 418, 434, 439, 440, 441, 442, 443, 448, 450, 453, 458, 463, 467, 477, 481, 484, 485, 502, 505, 508, 516, 522, 524, 526, 527, 529, 530, 535, 536, 540, 542 AND 543

-----  
211500 UTC NOV 25

NAVAREA IX 542/25

PAKISTAN

PORT MUHAMMAD BIN QASIM CHANNEL

CHARTS PAK 20 (INT 7316) AND BA 59

1. MAXIMUM PERMISSIBLE DRAUGHTS/ DIMENSIONS FOR SHIPS CALLING AT  
PORT MUHAMMAD BIN QASIM TILL 15 MAY 26 ARE AS UNDER:

BERTH	PERMISSIBLE DRAUGHT (METER)	LENGTH OVER ALL (METER)	BEAM (METER)
LCT	10*	210	33
MW-1	9.5	225	33
MW-2	10	225	33
MW-3	10	225	33
MW-4	10.5*	225	33
QICT-I (BERTH NO 5)	12**	UP TO 310	48
QICT-I (BERTH NO 5)	12**	MORE THAN 310 AND UP TO 340	46.5
QICT-I (BERTH NO 7)	12.5**	UP TO 310	48
QICT-I (BERTH NO 7)	12.5**	MORE THAN 310 AND UP TO 340	46.5
QICT-II	13	UP TO 310	48
QICT-II	13	MORE THAN 310 AND UP TO 340	46.5
FAP (GRAIN AND FERTILIZER)	13 (MAXDWT 75000 TONS)	250	43.5
EVTL-13	11	225	40
IOCB	12 (MAX DWT 75000 TONS)	230	40
EETL (LNG-1)	12***	295	43.4
PGPC (LNG-2)	12***	295	43.4
FOTCO OIL	13 (MAX DWT 75000 TONS)	245	42

TERMINAL			
SSGC/LPG	10	163	33
PIBT	13	230	33
PQEPC	12	210	33

TERMINAL

\* VESSELS MORE THAN 9.5 METER AND UPTO 10 METER DRAUGHT AT LCT  
 TERMINAL AND VESSELS MORE THAN 10 METER AND UPTO 10.5 METER  
 DRAUGHT AT MW-4 WILL BE ALLOWED BY TAKING BENEFIT OF TIDE

\*\* VESSELS MORE THAN 11.5 METER AND UPTO 12 METER DRAUGHT AT  
 QICT-I (BERTH NO 5) AND VESSELS MORE THAN 12 METER AND UPTO  
 12.5 METER DRAUGHT AT QICT-I (BERTH NO 7) WILL BE ALLOWED BY  
 TAKING BENEFIT OF TIDE

\*\*\* LNG Q-FLEX CALLING TO EETL TERMINAL UNDER DISPENSATION  
 ARE ALLOWED FROM 16 SEP TO 15 MAY UPTO DRAUGHT OF 11.5 METER

2. CANCEL THIS MSG 16 MAY 26

-----  
 201500 UTC NOV 25

NAVAREA IX 540/25

PAKISTAN

ORMARA

CHARTS PAK 24, 33, 57(INT 751), BA 38 AND 707

1. MILITARY EXERCISE SCHEDULED FROM 0330 - 0830

UTC ON 21 TO 26 NOV 25 IN AREA BOUNDED

BY FOLLOWING COORDINATES:

25-11.81N 064-38.23E

25-13.17N 064-35.99E

24-58.24N 064-23.26E

24-56.45N 064-29.89E

MARINERS CAUTIONED

2. CANCEL THIS MSG 260930 UTC NOV 25

-----  
 151130 UTC NOV 25

NAVAREA IX 535/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SEISMIC ACQUISITION OPERATION WILL BE CONDUCTED ON 16 NOV 25

BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:

AREA 32

A. 26-48.08N 051-53.95E

B. 26-43.32N 051-59.79E

C. 26-41.03N 051-57.46E

D. 26-43.62N 051-54.28E

E. 26-47.28N 051-53.15E

AREA 31

A. 26-36.98N 051-55.50E

B. 26-36.40N 051-58.27E

C. 26-32.34N 052-02.84E

D. 26-31.40N 052-03.39E

E. 26-30.04N 052-03.03E

F. 26-25.31N 051-59.36E

G. 26-27.18N 051-57.07E

H. 26-32.72N 051-54.19E

MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND KEEP  
CLEAR FROM MENTIONED AREA

2. CANCEL NAVAREA IX 394/24

-----  
111500 UTC NOV 25

NAVAREA IX 530/25

CENTRAL GULF

QATAR

CHARTS BA 2886, 3781, 3790 AND 3950

1. SUBSEA PIPELINE INSTALLATION OPERATION WILL BE CONDUCTED  
FROM 12 TO 26 NOV 25 BY BARGE MC DERMOTT (DB32) IN AREA BOUNDED  
BY FOLLOWING COORDINATES:

A. 25-58.99N 051-51.38E

B. 25-59.94N 051-53.48E

C. 25-58.75N 052-00.93E

D. 25-57.48N 052-03.12E

E. 25-56.12N 052-01.87E

F. 25-57.10N 051-53.10E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION  
GIVE WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH  
ON VHF CHANNEL 12 AND 16

-----  
101500 UTC NOV 25

NAVAREA IX 529/25

SOUTHERN GULF

UAE, RAS AL KHAIMAH

CHARTS BA 2888, 3174 AND 3175

1. SINKER PIPELINE TEMPORARILY WET STORED BETWEEN AL MARJAN ISLAND AND AL JAZEERA  
PORT

RESTRICTED AREA AROUND PIPELINE DESIGNATED BY FOLLOWING CARDINAL BUOYS:

NORTH CARDINAL BUOY 25-43.05N 055-45.82E

EAST CARDINAL BUOY 25-42.87N 055-46.38E

SOUTH CARDINAL BUOY 25-42.51N 055-46.24E

WEST CARDINAL BUOY 25-42.70N 055-45.68E

MARINERS CAUTIONED

2. CANCEL NAVAREA IX 337/25

-----  
101500 UTC NOV 25

NAVAREA IX 527/25

PAKISTAN

KARACHI APPROACHES

CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40  
CHANNEL BUOY S-5 IN POSITION 24-44.94N 066-57.63E  
REPORTED MISSING MARINERS CAUTIONED

-----  
090745 UTC NOV 25  
NAVAREA IX 526/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523, 2883 AND 2886  
SPM BUOY NO 3 IN POSITION 26-38.81N 051-53.50E  
REPORTED UNLIT MARINERS CAUTIONED

-----  
071500 UTC NOV 25  
NAVAREA IX 524/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523 AND 2886  
1. SUBSEA PIPELINE INSTALLATION AND OTHER MISCELLANEOUS ACTIVITIES WILL BE  
CONDUCTED BY DERRICK BARGE-30 SUPPORTED BY MULTI VESSELS FROM 08 TO 30 NOV 25  
IN AREA BOUNDED BY FOLLOWING COORDINATES:  
A. 25-56.58N 051-32.57E  
B. 25-57.84N 051-33.14E  
C. 25-57.40N 051-35.54E  
D. 25-55.54N 051-34.74E  
2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE BERTH OF 2NM  
AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

-----  
051400 UTC NOV 25  
NAVAREA IX 522/25  
ARABIAN SEA  
PAKISTAN  
CHARTS PAK 33, 57(INT 751) AND BA 39

FISHING VESSEL MASHAALLAH SUNK IN POSITION  
23-02.00N 067-24.00E AND REPORTED MAN OVER BOARD(.)  
VESSELS TRANSITING THE AREA ARE REQUESTED TO KEEP A SHARP  
LOOKOUT AND RENDER ASSISTANCE

-----  
021500 UTC NOV 25  
NAVAREA IX 516/25  
GULF OF OMAN  
OMAN  
CHARTS BA 2837, 3171 AND 3520  
1. CABLE INSTALLATION OPERATION IN PROGRESS BY VESSEL  
C/S ILE DE BATZ ALONG THE LINE JOINING FOLLOWING POINTS:  
WP1 25-39.58N 056-46.23E

WP2 25-30.70N 056-48.90E  
WP3 25-24.20N 056-52.10E  
WP4 25-22.60N 056-51.60E  
WP5 25-20.40N 056-50.30E  
WP6 25-18.20N 056-49.10E  
WP7 25-15.40N 056-48.30E  
WP8 25-12.50N 056-48.40E  
WP9 25-07.10N 056-45.30E  
WP10 25-03.10N 056-42.50E  
WP11 25-00.60N 056-41.40E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION  
GIVE WIDE BERTH OF 1NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 16

-----  
301500 UTC OCT 25

NAVAREA IX 508/25

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751), BA 38 AND 707

1. NAVAL SHIPS WILL CONDUCT LIVE FIRING PRACTICE BETWEEN 0300 TO 1900  
UTC FROM 03-07, 10-14, 17-21 AND 24-28 NOV 25 IN FOLLOWING AREAS:

A.

24-24.30N 066-42.00E

24-19.00N 066-58.00E

24-00.00N 066-39.00E

24-11.00N 066-27.00E

B.

24-36.02N 062-30.03E

24-36.02N 063-15.03E

24-21.02N 063-15.03E

24-21.02N 062-30.03E

C.

24-36.02N 061-45.03E

24-36.02N 062-30.03E

24-21.02N 062-30.03E

24-21.02N 061-45.03E

D. DEPTH CHARGE FIRING AREA

24-22.00N 066-27.00E

24-16.30N 066-33.00E

24-10.30N 066-27.00E

24-16.18N 066-20.50E

MARINERS KEEP WELL CLEAR OFF EXERCISE AREAS

2. CANCEL THIS MSG 282000 UTC NOV 25

-----  
281500 UTC OCT 25

NAVAREA IX 505/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SUBSEA INSTALLATION OF BRIDGES, BOLLARDS AND PRELAY ROUTE SURVEY ACTIVITIES IN PROGRESS BY DSV CONSTRUCTOR IN AREA BOUNDED BY FOLLOWING COORDINATES:

- A. 26-28.58N 051-43.78E
- B. 26-30.36N 051-45.47E
- C. 26-34.44N 051-49.35E
- D. 26-35.50N 051-50.33E
- E. 26-36.76N 051-53.24E
- F. 26-37.50N 051-57.94E
- G. 26-37.30N 051-58.18E
- H. 26-38.11N 051-58.54E
- I. 26-38.11N 051-58.54E
- J. 26-36.98N 051-58.59E
- K. 26-36.69N 051-58.20E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

-----  
261330 UTC OCT 25

NAVAREA IX 502/25

CENTRAL GULF

QATAR

CHARTS BA 2886 AND 2887

DIVING OPERATION WITH DIVING SUPPORT VESSEL HYSY 285 IS STARTING FROM 27 OCT 25 FOR SHROUD REMOVAL, RISER FLANGE INSPECTION, CATHODIC PROTECTION INSTALLATION AND ROV SURVEY AT AL KHALIJ FIELD IN AREA BOUNDED BY FOLLOWING COORDINATES:

- A. 26-01.77N 052-41.77E
- B. 26-00.92N 052-40.77E
- C. 25-58.29N 052-40.08E
- D. 25-56.48N 052-40.53E
- E. 25-52.60N 052-43.06E
- F. 25-52.82N 052-44.47E
- G. 25-56.40N 052-45.64E
- H. 26-00.97N 052-42.77E

MARINERS CAUTIONED

-----  
171500 UTC OCT 25

NAVAREA IX 485/25

NORTHERN GULF

KUWAIT

CHARTS BA 1223, 2884 AND 3773

BATHYMETRIC SURVEY IN PROGRESS BY VESSEL SEALINE-8 ALONG FOLLOWING POSITIONS:

- A. 29-07.20N 048-08.23E
- B. 29-06.85N 048-08.34E
- C. 29-07.34N 048-08.76E
- D. 29-07.01N 048-08.88E

MARINERS CAUTIONED  
-----

171500 UTC OCT 25

NAVAREA IX 484/25

SOUTHERN GULF

UAE

CHARTS BA 2889, 3177 AND 3178

1. PIPELINE INSTALLATION OPERATION IN PROGRESS BY MULTI  
VESSELS TILL 15 FEB 26 ALONG LINE JOINING:

START POINT 24-30.82N 054-01.29E

END POINT 24-53.45N 053-03.62E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND  
MAINTAIN LISTENING WATCH ON VHF CHANNEL 23 AND 12

-----  
151500 UTC OCT 25

NAVAREA IX 481/25

NORTHERN GULF

KUWAIT

CHARTS BA 1223, 3773 AND KU CHART 01

MOORING BUOY SIB IN POSITION 29-06.72N 048-17.54E

FL(4).Y.20 SEC TEMPORARILY WITHDRAWN

MARINERS CAUTIONED

-----  
141500 UTC OCT 25

NAVAREA IX 477/25

SOUTHERN GULF

UAE DELMA ISLAND

CHARTS BA 2837 AND 3951

BATHYMETRIC SURVEY OPERATION WILL BE CONDUCTED BY VESSELS BLUE WAVES,  
OWN OCEAN DEZIRE UNTIL 30 OCT 25 IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 24-30.00N 052-15.00E

B. 24-20.00N 052-15.00E

C. 24-20.00N 052-23.00E

D. 24-30.00N 052-23.00E

MARINERS ARE REQUESTED TO NAVIGATE WITH EXTREME CAUTION

-----  
091500 UTC OCT 25

NAVAREA IX 467/25

CENTRAL GULF

QATAR

CHARTS BA 2523, 2886 AND 3950

1. TOPSIDE INSTALLATION OPERATION IN PROGRESS BY VESSELS  
MCDERMOTT DB50, WISH WAY AND SUPPORT VESSELS IN AREA  
BOUNDED BY FOLLOWING COORDINATES:

A. 25-53.06N 051-54.04E

B. 25-52.98N 051-57.03E

C. 25-50.90N 051-57.04E

D. 25-50.88N 051-54.03E

2. WAVERIDER BUOY INSTALLED IN POSITION 25-51.80N 051-56.08E



AND MOORING BUOY INSTALLED IN POSITION 25-51.55N 051-54.83E  
MARINERS CAUTIONED

-----  
071500 UTC OCT 25  
NAVAREA IX 463/25  
SOUTHERN GULF  
UAE  
CHARTS BA 2888 AND 2889  
1. SPECIAL MARK BUOYS WITH FLASHING YELLOW LIGHTS TEMPORARILY  
RELOCATED TO FOLLOWING POSITIONS:  
UID01 25-19.91N 054-49.78E  
UID02 25-25.75N 054-52.53E  
UID03 25-22.64N 054-48.64E  
UID04 25-25.98N 054-48.35E  
MARINERS CAUTIONED  
2. CANCEL NAVAREA IX 429/25

-----  
050300 UTC OCT 25  
NAVAREA IX 458/25  
SOUTHERN GULF  
UAE  
CHARTS BA 2889 AND 2444  
ZAQQUM LIGHT BUOY IN POSITION 25-06.56N 053-25.06E REPORTED RACON  
NOT OPERATIONAL AND LANTERN FLASH CHARACTERISTIC MALFUNCTIONING  
MARINERS CAUTIONED

-----  
031500 UTC OCT 25  
NAVAREA IX 453/25  
NORTHERN GULF  
KUWAIT  
CHARTS BA 1214, 1235, 2884, 3773 AND KU 1  
1. AIDS TO NAVIGATION DEVELOPMENT AND SEABED SURVEY OPERATION  
WILL BE CONDUCTED BY MULTI VESSELS IN FOLLOWING AREAS:  
DOHA  
A. 29-23.68N 047-52.47E  
B. 29-23.70N 047-54.25E  
C. 29-21.43N 047-54.10E  
D. 29-21.44N 047-52.45E  
FAYLAKA ISLAND  
A. 29-32.84N 048-37.57E  
B. 29-32.84N 048-12.26E  
C. 29-21.40N 048-12.22E  
D. 29-21.40N 048-37.66E  
BUBIYAN ISLAND  
A. 29-43.37N 048-34.40E  
B. 29-29.47N 048-11.35E  
C. 29-56.87N 047-56.01E

D. 30-01.12N 048-09.46E

2. TEMPORARY SPECIAL MARK BUOYS WILL BE DEPLOYED DURING MAINTENANCE  
OF AIDS TO NAVIGATION MARINERS CAUTIONED

-----  
011500 UTC OCT 25

NAVAREA IX 450/25

CENTRAL GULF

QATAR

CHARTS BA 2523, 2886 AND 3950

1. ROV SURVEY OPERATION IN PROGRESS BY VESSEL HALUL-51 TILL  
31 DEC 25 ALONG THE FOLLOWING ROUTES:

MIDSTREAM LINE ROUTE (QATAR TO UAE)

A. 25-56.62N 051-31.25E

B. 25-59.28N 051-32.78E

C. 25-57.08N 051-48.39E

D. 25-52.38N 052-02.00E

E. 25-23.11N 053-01.96E

F. 25-25.66N 053-27.76E

G. 24-49.99N 054-36.08E

H. 24-45.45N 054-40.17E

UPSTREAM ROUTE (QATAR)

A. 25-56.52N 051-31.18E

B. 25-57.49N 051-31.76E

C. 25-59.13N 051-32.71E

D. 26-06.28N 051-55.03E

E. 26-09.27N 052-02.43E

F. 26-12.25N 052-07.25E

G. 26-14.79N 052-09.74E

H. 26-17.32N 052-12.24E

I. 26-19.15N 052-14.45E

J. 26-19.34N 052-14.67E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND  
GIVE WIDE BERTH OF 2NM

-----  
010900 UTC OCT 25

NAVAREA IX 448/25

ARABIAN GULF

SAUDI ARABIA

CHARTS BA 3777, 3788 AND 3812

LIFE BOAT REPORTED MISSING FROM MV CELINA (IMO NO 9306378)

IN VICINITY OF POSITION 26-34.66N 050-19.48E MARINERS  
CAUTIONED

-----  
291500 UTC SEP 25

NAVAREA IX 443/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SUBSEA PIPELINE INSTALLATION OPERATION IN PROGRESS TILL  
15 OCT 25 BY DERRICK BARGE 30 ASSISTED BY MULTI VESSELS IN  
AREA BOUNDED BY FOLLOWING COORDINATES:

26-31.76N 051-59.05E

26-28.89N 051-56.09E

26-30.47N 051-54.03E

26-33.08N 051-56.71E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE  
BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

3. CANCEL NAVAREA IX 433/25

-----  
291500 UTC SEP 25

NAVAREA IX 442/25

NORTHERN GULF

KUWAIT

CHARTS BA 1214, 3773 AND KU 1

SEABED SURVEY IN PROGRESS BY MULTI VESSELS ALONG FOLLOWING POSITIONS:

MPA-1 29-21.17N 047-50.56E

MPA-2 29-20.63N 047-50.71E

MPA-3 29-21.56N 047-50.78E

MPA-4 29-21.18N 047-53.23E

LTMP-1 29-21.61N 047-52.35E

LTMP-2 29-24.78N 047-54.45E

LTMP-3 29-25.82N 048-05.31E

MARINERS CAUTIONED

-----  
291500 UTC SEP 25

NAVAREA IX 441/25

PERSIAN GULF

IRAN

CHARTS BA 2883 AND IR 3059(INT 7247)

FOLLOWING AIDS TO NAVIGATION ESTABLISHED:

A. PORT HAND BEACON TOWER WITH TOPMARK FL (2) 5SEC 3M IN POSITION

27-09.70N 052-54.70E

B. SAFEWATER PILLAR BUOY WITH TOPMARK ISO 4SEC 5M IN POSITION

27-08.45N 052-55.27E

C. STARBOARD HAND PILLAR BUOY WITH TOPMARK FL (2) 5SEC 3M IN POSITION 27-09.21N  
052-55.24E

D. PORT HAND PILLAR BUOY WITH TOPMARK FL (2) 5SEC 3M IN POSITION

27-09.12N 052-55.02E

E. STARBOARD HAND PILLAR BUOY WITH TOPMARK FL (2) 5SEC 3M IN POSITION 27-09.75N  
052-54.92E

MARINERS CAUTIONED

-----  
281500 UTC SEP 25

NAVAREA IX 440/25

RED SEA  
SAUDI ARABIA, YANBU INDUSTRIAL PORT  
CHARTS BA 158, 326 AND 328  
BUOY NO (W) IN POSITION 23-55.00N 038-12.52E REPORTED MISSING MARINERS CAUTIONED

-----  
271500 UTC SEP 25  
NAVAREA IX 439/25  
CENTRAL GULF  
QATAR  
CHARTS BA 3772, 2523 AND 2886  
ROV OPERATION WILL BE CONDUCTED BY VESSEL HALUL 51 FROM 28 SEP 25 ALONG  
FOLLOWING POSITIONS:  
A. 25-57.32N 051-30.13E  
B. 26-00.68N 051-32.25E  
C. 26-05.20N 051-33.73E  
D. 26-07.22N 051-31.83E  
E. 26-12.43N 051-32.97E  
F. 26-17.26N 051-34.91E  
G. 26-27.66N 051-42.79E  
H. 26-36.89N 051-51.65E  
I. 26-36.89N 051-56.43E  
J. 26-38.11N 051-57.58E  
MARINERS CAUTIONED

-----  
241500 UTC SEP 25  
NAVAREA IX 434/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523 AND 2886  
1. SUBSEA PIPELINE INSTALLATION OPERATION WILL BE CONDUCTED BY NON-PROPELLED BARGE  
MC DERMOTT DB32 SUPPORTED BY MULTI VESSELS IN POSITION 25-57.00N 051-32.50E  
FROM 24 SEP TO 15 OCT 25  
2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE BERTH OF 2NM AND  
MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

-----  
151500 UTC SEP 25  
NAVAREA IX 418/25  
SOUTHERN GULF  
UAE  
CHARTS BA 3520, 3709 AND 3723  
1. FUJAIRAH BEACON FL 5 SECONDS 176 METERS 20M SHIFTED  
PERMANENTLY TO POSITION 25-10.61N 056-20.76E MARINERS  
CAUTIONED  
  
2. CANCEL NAVAREA IX 515/24  
  
-----

031500 UTC SEP 25  
NAVAREA IX 405/25  
PAKISTAN  
KARACHI APPROACHES  
CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40  
CHANNEL BUOY S-13 24-46.84N 066-59.38E REPORTED  
MISSING MARINERS CAUTIONED

-----  
011500 UTC SEP 25  
NAVAREA IX 399/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2886  
1. SUBSEA PIPELINE INSTALLATION OPERATION IN PROGRESS TILL 15 DEC 25  
BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:  
26-22.70N 051-33.50E  
26-27.30N 052-27.80E  
25-46.90N 052-27.30E  
25-46.30N 051-42.90E  
25-57.70N 051-24.40E  
2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE  
BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

-----  
261500 UTC AUG 25  
NAVAREA IX 388/25  
SOUTHERN GULF  
UAE  
CHARTS BA 3951 AND 2889  
WAVE BUOY PTM-61182 WITH CHARACTERISTICS FL.Y.15  
TEMPORARILY DEPLOYED IN POSITION 24-38.58N 052-35.31E  
(.) MARINERS CAUTIONED

-----  
261500 UTC AUG 25  
NAVAREA IX 387/25  
SOUTHERN GULF  
UAE  
CHARTS BA 2837, 2889 AND 3412  
1. RESTRICTED AREA ESTABLISHED IN OFFSHORE  
UMM SUQEIM COASTAL AREA BOUNDED BY FOLLOWING COORDINATES:  
A. 25-11.20N 055-11.36E  
B. 25-11.75N 055-11.80E  
C. 25-11.52N 055-12.90E  
D. 25-10.60N 055-12.90E  
E. 25-10.32N 055-12.59E  
F. 25-10.06N 055-11.88E  
G. 25-10.15N 055-11.56E  
2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

AND KEEP CLEAR FROM MENTIONED AREA

3. CANCEL NAVAREA IX 278/25

-----  
221500 UTC AUG 25

NAVAREA IX 379/25

SOUTHERN GULF

UAE

CHARTS BA 2889 AND 3176

1. RESTRICTED AREA ESTABLISHED IN VICINITY  
OF BURJ AL ARAB AND MADINAT JUMEIRAH BOUNDED  
BY FOLLOWING COORDINATES:

A. 25 07.99N 055 10.77E

B. 25 08.29N 055 10.63E

C. 25 08.98N 055 11.22E

D. 25 08.91N 055 11.38E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION  
AND KEEP CLEAR FROM MENTIONED AREA.

-----  
201500 UTC AUG 25

NAVAREA IX 377/25

CENTRAL GULF

QATAR

CHARTS BA 2523, 2886, 3772 AND 3950

1. PIPELINE INSPECTION OPERATION WILL BE CONDUCTED  
BY VESSELS FUGRO PEGASUS AND LADY BEATRICE IN AREA  
BOUNDED BY FOLLOWING COORDINATES:

25-57.72N 051-30.12E

26-01.68N 051-32.30E

26-01.72N 051-42.03E

26-05.41N 051-57.83E

26-10.95N 052-04.10E

26-08.01N 052-06.08E

26-03.04N 051-59.50E

25-59.06N 051-42.56E

25-59.05N 051-33.09E

25-56.59N 051-32.06E

2. MARINERS ARE REQUESTED TO GIVE WIDE BERTH  
AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 16

-----  
131500 UTC AUG 25

NAVAREA IX 375/25

CENTRAL GULF

QATAR, AL SHAHEEN FIELD

CHARTS BA 2523, 2837, 2883, AND 2886

PIPE LAYING AND SLEEPERS INSTALLATION OPERATION WILL BE CONDUCTED  
ON 14 AUG 25 BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:  
26-18.90N 051-48.90E

26-37.70N 051-51.00E  
26-42.50N 051-53.50E  
26-40.20N 052-00.70E  
26-35.60N 052-00.40E  
MARINERS CAUTIONED

-----  
031500 UTC AUG 25  
NAVAREA IX 365/25  
PAKISTAN  
KARACHI APPROACHES  
CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40  
CHANNEL BUOY S-3 24-44.30N 066-57.14E REPORTED MISSING  
MARINERS CAUTIONED

-----  
251500 UTC JUL 25  
NAVAREA IX 356/25  
SOUTHERN GULF  
UAE  
CHARTS BA 2889, 3179 AND 3413  
YELLOW MOORING BUOY IN POSITION 25-07.24N 052-53.04E  
REPORTED UNLIT MARINERS CAUTIONED

-----  
221500 UTC JUL 25  
NAVAREA IX 353/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523, 2886 AND 3950  
CABLE LAYING OPERATION IN PROGRESS BY VESSEL POSH ENDEAVOUR  
IN AREA BOUNDED BY FOLLOWING POSITIONS:  
A. 25-56.30N 051-34.40E  
B. 25-58.00N 051-35.33E  
C. 26-01.87N 052-05.17E  
D. 26-00.42N 052-05.27E  
E. 25-57.33N 051-35.80E  
F. 25-56.13N 051-35.33E  
MARINERS CAUTIONED

-----  
211500 UTC JUL 25  
NAVAREA IX 352/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523, 2886, 2887, AND 2889  
1. SUBSEA COMPOSITE CABLE INSTALLATION AND MISCELLANEOUS  
ACTIVITIES ARE IN PROGRESS BY MULTI VESSELS IN AREA BOUNDED  
BY FOLLOWING POSITIONS:  
25-57.71N 051-24.37E

26-22.65N 051-33.50E  
26-27.29N 052-27.79E  
25-46.92N 052-27.29E  
25-46.27N 051-42.91E  
2. MARINERS CAUTIONED

-----  
171500 UTC JUL 25  
NAVAREA IX 349/25  
PAKISTAN  
GWADAR PORT APPROACHES  
CHART PAK 40  
CHANNEL BUOY NO 1 FL.Q.G(GREEN) AT 25-06.98N 062-24.16E  
REPORTED BROKEN MARINERS CAUTIONED

-----  
120830 UTC JUL 25  
NAVAREA IX 339/25  
RED SEA  
CHARTS BA 1, 157 AND 2964  
1. MV ETERNITY C (IMO 9588249) REPORTED SUNK IN POSITION 14-42.00N  
042-26.00E 10 CREW MEMBERS RESCUED AND REMAINING STILL PRESUMED  
IN WATER ALL VESSELS IN VICINITY ARE REQUESTED TO MAINTAIN SHARP  
LOOKOUT AND RENDER ASSISTANCE  
  
2. CANCEL NAVAREA IX 333/25

-----  
101500 UTC JUL 25  
NAVAREA IX 335/25  
PAKISTAN  
KARACHI APPROACHES  
CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40  
CHANNEL BUOY S-7 24-45.49N 066-58.13E REPORTED MISSING  
MARINERS CAUTIONED

-----  
091500 UTC JUL 25  
NAVAREA IX 332/25  
SOUTHERN GULF  
UAE  
BA CHARTS 2889, 3179 AND 3780

1.DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS  
PORT IN PROGRESS FOLLOWING NAVIGATIONAL BUOYS TEMPORARILY CHANGED:  
GS-12 24-08.54N 052-46.66E TO 24-08.58N 052-46.63E  
TRB-4 24-08.41N 052-46.87E TO 24-08.39N 052-46.82E  
2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND  
MAINTAIN LISTENING WATCH ON CHANNEL VHF 21



-----  
081500 UTC JUL 25  
NAVAREA IX 331/25  
PERSIAN GULF  
IRAN  
CHARTS BA 2523, 2886 AND 2887  
FOUR LEGGED JACKET ESTABLISHED AT POSITION 26-18.09N 052-32.92E  
MARINERS CAUTIONED

-----  
080700 UTC JUL 25  
NAVAREA IX 328/25  
RED SEA  
YEMEN  
CHARTS BA 6, 143 AND 157  
RISK OF EXPLOSION MAY EXIST IN VICINITY OF ATTACKED VESSEL MV MAGIC SEAS  
CAUTION AREA ESTABLISHED BOUNDED BY FOLLOWING COORDINATES:  
A. 14-38.00N 42-08.00E  
B. 14-10.00N 42-34.00E  
C. 14-04.00N 42-26.00E  
D. 14-30.00N 42-00.00E  
MARINERS CAUTIONED

-----  
071500 UTC JUL 25  
NAVAREA IX 327/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2886 AND 3950  
1. SEISMIC OPERATION IN PROGRESS BY MULTI VESSELS  
IN AREA BOUNDED BY FOLLOWING COORDINATES:  
A. 25-46.60N 052-04.91E  
B. 25-41.02N 052-11.67E  
C. 25-21.60N 051-52.17E  
D. 25-21.64N 051-45.41E  
E. 25-23.01N 051-41.28E  
MARINERS CAUTIONED  
2. CANCEL NAVAREA IX 239/25

-----  
021500 UTC JUL 25  
NAVAREA IX 321/25  
IRAN  
BANDAR-E KUHESTAK  
CHARTS BA 2837, 2888 AND 3173  
FOLLOWING ESTABLISHED:  
A. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(1)5SEC 3M AT  
26-47.91N 057-00.95E  
B. PORT HAND BEACON TOWER WITH TOPMARK FL(1)5SEC 3M AT  
26-47.93N 057-01.06E

MARINERS CAUTIONED

-----  
191600 UTC JUN 25  
NAVAREA IX 300/25  
PORT OF FUJAIRAH  
UAE  
CHARTS BA 3520 AND 3171  
MT ADALYNN IMO 9231767 ANCHORED IN POSITION 25-36.99N 056-24.85E AT  
DIBBA ANCHORAGE AREA W REPORTED UNMANNED AND IN COMPLETE BLACKOUT  
MARINERS CAUTIONED

-----  
191500 UTC JUN 25  
NAVAREA IX 297/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2886 AND 3950  
SEABED DEBRIS SURVEY WILL BE CONDUCTED BY VESSEL HALUL 83  
FROM 19 JUN 25 IN AREA BOUNDED BY FOLLOWING COORDINATES:  
25-45.28N 051-56.59E  
25-45.28N 051-57.04E  
25-44.87N 051-57.04E  
25-44.87N 051-56.59E  
MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND  
MAINTAIN LISTENING WATCH ON VHF CHANNEL 16

-----  
171500 UTC JUN 25  
NAVAREA IX 292/25  
NORTHERN GULF  
KUWAIT  
CHARTS BA 2882, 2884 AND 3773  
1.RIG ORIENTAL PHOENIX STATIONED ON POSITION 29-14.35N  
048-20.56E UNTIL END OF JUN 26(.) RESTRICTED AREA OF 0.5 NM  
ESTABLISHED MARINERS CAUTIONED  
2.CANCEL NAVAREA IX 262/25

-----  
161500 UTC JUN 25  
NAVAREA IX 289/25  
SOUTHERN GULF  
UAE  
CHARTS BA 3178 AND 3179  
FOLLOWING UNLIT MOORING BUOYS DEPLOYED TEMPORARILY:  
7086 24-53.92N 053-01.57E  
8995 24-53.85N 053-02.02E  
3972 24-53.67N 053-01.96E  
MARINERS CAUTIONED

-----  
151500 UTC JUN 25

NAVAREA IX 287/25

SOUTHERN GULF

UAE

CHARTS BA 2837, 2888 AND 3174

1. BATHYMETRIC SURVEY WILL BE CONDUCTED FROM 16 JUN 25  
BY BOAT ECO-1 IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 26-01.57N 056-03.68E

B. 26-01.31N 056-04.85E

C. 26-00.52N 056-04.62E

D. 26-00.78N 056-03.45E

2. SPECIAL MARK BOUY TEMPORARILY ESTABLISHED IN POSITION  
26-01.12N 056-03.85E MARINERS CAUTIONED

-----  
101500 UTC JUN 25

NAVAREA IX 280/25

SOUTHERN GULF

UAE

BA CHARTS 3179, 3780, 3778 AND 3796

1. DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS  
PORT IN PROGRESS FOLLOWING NAVIGATIONAL BUOYS  
TEMPORARILY WITHDRAWN:

GS-20 24-07.97N 052-46.95E

GS-22 24-07.87N 052-46.90E

FOLLOWING NAVIGATIONAL BUOYS TEMPORARILY DEPLOYED:

TRB-5 24-07.69N 052-46.95E Q.R

TRB-6 24-07.59N 052-46.90E FL(3).R.10S

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION  
AND MAINTAIN LISTENING WATCH ON CHANNEL VHF 21

-----  
071500 UTC JUN 25

NAVAREA IX 272/25

RED SEA

SAUDI ARABIA

CHARTS BA 326, 327 AND 328

FOLLOWING BUOYS REPORTED MISSING:

A. BUOY NO.7 23-55.07N 038-09.17E

B. BUOY NO.08R 23-54.05N 038-17.22E

MARINERS CAUTIONED

-----  
051500 UTC JUN 25

NAVAREA IX 267/25

SOUTHERN GULF

UAE

CHARTS BA 3176 AND 3739  
SPECIAL MARK BUOY IN POSITION 25-04.02N 054-48.00E REPORTED UNLIT  
MARINERS CAUTIONED

-----  
311500 UTC MAY 25  
NAVAREA IX 261/25  
NORTHERN GULF  
KUWAIT  
CHARTS BA 2882, 2884, AND 3773

RESTRICTED AREA ESTABLISHED AT POSITION 29-13.10N 048-44.42E  
WITH 600 METER DIAMETER MARINERS CAUTIONED

-----  
291500 UTC MAY 25  
NAVAREA IX 256/25  
RED SEA  
SAUDI ARABIA, JEDDAH  
CHARTS BA 158, 2599, 2658 AND 2659  
BUOY 04W 21-26.80N 039-03.50E REPORTED MISSING  
MARINERS CAUTIONED  
25-09.98N 052-51.45E  
25-09.98N 052-52.14E  
25-09.88N 052-52.14E  
25-09.57N 052-51.64E  
25-09.57N 052-51.45E  
MARINERS CAUTIONED

-----  
291500 UTC MAY 25  
NAVAREA IX 254/25  
IRAN  
BANDAR E LENGHEH  
CHARTS BA 2441, 2887 AND 2888  
ISOLATED DANGER BEACON IN POSITION 26-32.21N 054-57.79E  
PERMANENTLY DISCONTINUED ISOLATED DANGER PILLAR  
LIGHTBUOY WITH TOPMARK FL(2)6SEC 5 MILES ESTABLISHED  
IN POSITION 26-32.31N 054-57.83E MARINERS CAUTIONED

-----  
241500 UTC MAY 25  
NAVAREA IX 246/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523 AND 2886  
SELF PROPELLED DP2 VESSEL "HYSY289" WILL BE CARRYING OUT SLEEPERS  
INSTALLATION IN FOLLOWING BOUNDED AREA:  
A- 26-41.99N 051-53.26E  
B- 26-41.94N 052-00.75E

C- 26-37.65N 052-00.72E  
D- 26-37.70N 051-53.23E  
MARINERS CAUTIONED

-----  
131500 UTC MAY 25

NAVAREA IX 227/25

RED SEA

SAUDI ARABIA

CHARTS BA 158, 326, 327 AND 328

1. FOLLOWING BUOYS ARE OUT OF SERVICE:

BUOY	TYPE	POSITION
LIGHT		
NAME		
	CHARACTERISTICS	
EAST	EAST CARDINAL BUOY	24-05.90N 037-47.15E Q.(3).10S
REEF		
S02	LATERAL PORT BUOY	23-27.96N 038-25.86E FL(2)R.5S
10	SOUTH CARDINAL BUOY	23-56.20N 038-11.28E V.Q.(6)+FL.10S
16	SOUTH CARDINAL BUOY	23-54.20N 038-15.15E V.Q.(6)+FL.10S

MARINERS CAUTIONED

2. ISOLATED DANGER BUOY FL(2)5S IN POSITION 23-55.00N 038-12.52E

OPERATIONAL CANCEL NAVAREA IX 454/24

-----  
081500 UTC MAY 25

NAVAREA IX 218/25

SOUTHERN GULF

UAE

CHARTS BA 3174 AND 3175

FOLLOWING SPECIAL MARK DATA BUOY ESTABLISHED:

25-44.21N, 055-41.60E QY

MARINERS CAUTIONED

-----  
061500 UTC MAY 25

NAVAREA IX 216/25

ARABIAN GULF

SAUDI ARABIA, PORT RAS AL KHAIR

CHARTS BA 2882 AND 3775

FOLLOWING BUOYS REPORTED MISSING:

RAZ-17 27-38.19N 049-17.96E

RAZ-18 27-38.11N 049-18.02E

MARINERS CAUTIONED

-----  
241500 UTC APR 25

NAVAREA IX 185/25

NORTHERN GULF

KUWAIT

CHARTS BA 1235 AND 2884

BATHYMETRIC SURVEY AND EXCAVATION OPERATION WILL BE  
CONDUCTED ON FOLLOWING POSITIONS:

- A. 29-54.04N 048-17.98E
- B. 29-51.85N 048-21.48E
- C. 29-51.40N 048-22.03E
- D. 29-50.68N 048-22.73E
- E. 29-49.30N 048-22.28E
- F. 29-51.52N 048-19.54E
- G. 29-53.77N 048-17.68E

TIDE STATION (T), CURRENT OBSERVATION PROFILE (C) AND WAVE  
OBSERVATION STATION (WA) WILL BE INSTALLED IN FOLLOWING  
POSITIONS:

- T1 29-36.12N 048-10.44E
  - T2 29-59.21N 048-07.90E
  - T3 29-51.96N 048-19.95E
  - T4 29-48.58N 048-23.78E
  - C1 29-36.12N 048-10.44E
  - C2 29-59.21N 048-07.90E
  - C3 29-53.24N 048-19.03E
  - WA 29-48.58N 048-23.78E
- MARINERS CAUTIONED

-----  
201500 UTC APR 25

NAVAREA IX 176/25

RED SEA

SAUDI ARABIA, YANBU INDUSTRIAL PORT

CHARTS BA 158 AND 326

BUOY S-10 IN POSITION 23-49.08N 038-17.82E REPORTED UNLIT

MARINERS CAUTIONED

-----  
091500 UTC APR 2025

NAVAREA IX 158/25

PAKISTAN

PORT MUHAMMAD BIN QASIM

CHARTS PAK 5 (INT 7314), 20 (INT 7316) AND BA 59

1. AHSAN CHANNEL BEACON NO.7 TEMPORARILY REPLACED WITH  
BUOY IN POSITION 24-36.38N 067-05.24E MARINERS CAUTIONED

2. CANCEL NAVAREA IX 294/24

-----  
281500 UTC MAR 2025

NAVAREA IX 147/25

SOUTHERN GULF

UAE

BA CHARTS 3179, 3780, 3778 AND 3796

DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS PORT

IN PROGRESS FOLLOWING THREE NAVIGATIONAL BUOYS TEMPORARILY  
WITHDRAWN:

GS-14 24-08.43N 052-46.83E Q(3).R.10S

GS-16 24-08.31N 052-47.01E Q.R

GS-18 24-08.21N 052-47.04E Q(2).R.10S

FOLLOWING TWO NAVIGATIONAL BUOYS TEMPORARILY DEPLOYED:

TRB-3 24-08.27N 052-46.97E Q.R

TRB-4 24-09.40N 052-46.88E FL(3).R.10S

MARINERS CAUTIONED

-----  
061500 UTC MAR 25

NAVAREA IX 111/25

CENTRAL GULF

BAHRAIN

BA CHARTS 3734, 3736 AND 3737

1. DREDGING OPERATION WILL BE CONDUCTED EAST OF BAHRAIN  
STEEL TERMINAL ON 08 MAR 25 A TEMPORARY SPECIAL MARK  
BUOY DEPLOYED 26-10.73N 050-41.70E FOLLOWING BUOYS  
TEMPORARILY SHIFTED:

BS 3 26-11.24N 050-41.84E

BS 5 26-11.39N 050-41.65E

2. MARINERS EXERCISE EXTREME CAUTION AND GIVE WIDE BERTH

-----  
281500 UTC FEB 25

NAVAREA IX 101/25

SOUTHERN GULF

UAE

BA CHARTS 3179, 3780, 3778 AND 3796

1. DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS  
PORT IN PROGRESS NO-GO AREA HAS BEEN ESTABLISHED MARKED  
BY FOLLOWING BUOYS:

24-09.82N 052-47.25E FL.Y

24-09.70N 052-47.34E FL.Y

24-09.57N 052-47.14E FL.Y

24-09.69N 052-47.04E FL.Y

2. MARINERS EXERCISE EXTREME CAUTION MAINTAIN CONTINUOUS  
LISTENING WATCH ON VTIS VHF CH 21

3. CANCEL NAVAREA IX 080/25

-----  
240730 UTC FEB 25

NAVAREA IX 094/25

SOUTHERN GULF

UAE

CHARTS BA 2889, 3179, 3778 AND 3780

CHANNEL DREDGING OPERATION IN PROGRESS AT NORTH WEST OF  
RUWAIS PLANTS MARKER BUOYS UPDATED POSITION ARE AS UNDER:  
M 3 24-11.16N 052-39.58E  
M 5 24-10.02N 052-39.33E  
M 6 24-09.10N 052-40.57E  
ENV 2 24-10.78N 052-38.92E  
SILT SCREEN-4 START 24-10.43N 052-40.46E  
SILT SCREEN-4 END 24-10.45N 052-40.50E  
MARINERS CAUTIONED MAINTAIN SAFE DISTANCE OF 500 METERS  
FROM LOCATION

-----  
201500 UTC FEB 25  
NAVAREA IX 090/25  
NORTHERN GULF  
KUWAIT  
CHARTS BA 1214, 2884 AND 3773  
FOLLOWING SPECIAL MARK BUOYS TEMPORARILY DEPLOYED  
SHOWING BORDERS OF KUWAIT SPORTS CLUB RACETRACK:  
BUOY 1 29-20.35N 048-06.05E  
BUOY 2 29-20.50N 048-06.09E  
MARINERS CAUTIONED

-----  
111500 UTC FEB 25  
NAVAREA IX 071/25  
SOUTHERN GULF  
UAE  
CHARTS BA 7179 AND 2889  
WAVE RIDER BUOY TEMPORARILY DEPLOYED 24-08.89N 052-46.54E  
MARINERS CAUTIONED

-----  
101500 UTC FEB 25  
NAVAREA IX 066/25  
CENTRAL GULF  
QATAR  
CHARTS BA 2523 AND 2886  
FOLLOWING NAVIGATION LIGHTS AT AL SHAHEEN  
FIELD REPORTED UNLIT FOR MAINTENANCE:  
PLATFORM B 26-38.31N 051-57.10E  
PLATFORM G 26-26.93N 051-58.34E  
MARINERS CAUTIONED

-----  
071600 UTC FEB 25  
NAVAREA IX 063/25  
SOUTHERN GULF  
UAE  
CHARTS BA 2444, 3179 AND 3413



ANCHOR WITH 2.5 SHACKLE CHAIN REPORTED LOST  
25-07.69N, 052-53.09E  
MARINERS REQUESTED NOT TO ANCHOR IN VICINITY

-----  
281500 UTC JAN 2025  
NAVAREA IX 047/25  
SOUTHERN GULF  
UAE, RAS AL KHAIMAH  
BA CHARTS 2888, 3174 AND 3175  
1. DREDGING OPERATION IN PROGRESS BY VESSELS TSHD  
ROTTERDAM AND SUPPORTING TUGS IN FOLLOWING AREA:  
25-44.46N 055-41.92E  
25-44.92N 055-45.58E  
25-43.21N 055-44.98E  
25-42.87N 055-42.87E  
2. TEMPORARY CARDINAL MARK BUOYS DEPLOYED IN FOLLOWING POSITIONS:  
NORTH CARDINAL 25-42.56N 055-45.00E  
EAST CARDINAL 25-41.99N 055-45.57E  
WEST CARDINAL 25-42.11N 055-43.85E  
3. SPECIAL MARK BUOYS DEPLOYED TO INDICATE THE DRAUGHT RESTRICTED ARE  
(MAX 3 METERS) AND PIPELINE IN FOLLOWING POSITIONS:  
A. 25-41.60N 055-45.79E  
B. 25-41.52N 055-46.05E  
C. 25-41.11N 055-45.82E  
4. VESSELS INTENDING TO ENTER 1.5 NM RADIUS OF TSHD ROTTERDAM  
COORDINATE ON VHF CH 11 AND 16 MARINERS CAUTIONED  
5. CANCEL NAVAREA IX 347/24

-----  
151500 UTC JAN 2025  
NAVAREA IX 024/25  
PAKISTAN  
KARACHI  
CHARTS PAK 5 (INT 7314), 30 (INT 7315), BA 40 AND 58  
CHANNEL BUOY S-11 24-46.58N 066-59.16E REPORTED MISSING  
(.) MARINERS CAUTIONED

-----  
131500 UTC JAN 2025  
NAVAREA IX 021/25  
NORTHERN GULF  
KUWAIT  
CHARTS BA 1223, 2847, 2858, 2884 AND 3773  
1. METEOROLOGICAL TOWER REPORTED COLLAPSED 28-46.00N 048-26.10E  
POSITION MARKED BY YELLOW BUOY FL(4)15SEC 5NM MARINERS CAUTIONED  
2. CANCEL NAVAREA IX 135/23

-----  
111800 UTC JAN 2025

NAVAREA IX 018/25

SOUTHERN GULF

UAE,

CHART BA 2444, 2889

1. DATA BUOY DWR 25-07.14N 052-56.06E PERMANENTLY WITHDRAWN

DATA BUOY MIDI 018 25-03.01N 053-04.16E FL(5).Y.20S REMAINS MARINERS CAUTIONED

2. CANCEL NAVAREA IX 433/24

-----  
081500 UTC JAN 2025

NAVAREA IX 014/25

NORTHERN GULF

KUWAIT

CHARTS BA 2882, 2884 AND 3773

RESTRICTED AREA ESTABLISHED AT POSITION 29-24.10N 048-50.50E

WITH 600 METER DIAMETER MARINERS CAUTIONED

-----  
061500 UTC JAN 2025

NAVAREA IX 006/25

NORTHERN GULF

KUWAIT

CHARTS BA 2882, 3773 AND KU CHART 1

RESTRICTED AREA ESTABLISHED AT POSITION 28-52.49N 048-21.63E WITH 600 METER DIAMETER

MARINERS CAUTIONED

-----  
021500 UTC JAN 2025

NAVAREA IX 002/25

PAKISTAN

PORT MUHAMMAD BIN QASIM

CHARTS PAK 5, 20 AND BA 59

1. FOLLOWING NAVIGATIONAL CHANNEL BUOYS TEMPORARILY MOVED

FOR DREDGING OPERATION:

BUOY NAME	CHARTED POSITION	NEW POSITION
K-7	24-47.24N 067-15.39E	24-47.20N 067-15.27E
K-11	24-47.31N 067-15.66E	24-47.28N 067-15.65E
K-13	24-47.31N 067-16.04E	24-47.28N 067-16.02E
K-15	24-47.22N 067-16.52E	24-47.16N 067-16.47E

MARINERS CAUTIONED

2. CANCEL NAVAREA IX 227/22

-----  
291500 UTC DEC 2024

NAVAREA IX 531/24

CENTRAL GULF

BAHRAIN

CHARTS BA 3736 AND 3737, BH 1501

MSI-2 BUOY ALTERED IN POSITION 26-11.68N 050-36.68E MARINERS CAUTIONED

-----  
261500 UTC DEC 2024

NAVAREA IX 529/24

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751), BA 39 AND 707

1. MSV TAJDARE HARAM (MMSI 419956194) REPORTED SUNK  
IN POSITION 22-55.50N 066-56.50E MARINERS CAUTIONED
2. CANCEL NAVAREA IX 523/24

-----  
231500 UTC DEC 2024

NAVAREA IX 519/24

SAUDI ARABIA

RED SEA, JIZAN

CHARTS BA 15

BUOY F2 IN POSITION 16-49.40N 042-18.20E REPORTED MISSING  
MARINERS CAUTIONED

-----  
191045 UTC DEC 2024

NAVAREA IX 509/24

RED SEA

1. VESSEL ISA STAR (IMO 9210270) REPORTED AGROUND 18-26.00N 041-06.00E  
MARINERS CAUTIONED
2. CANCEL NAVAREA IX 508/24

-----  
141500 UTC DEC 2024

NAVAREA IX 501/24

NORTHERN GULF

KUWAIT

CHARTS KU 1, BA 3773

1. RIG 'ORIENTAL DRAGON 1' WILL BE MOVED FROM  
POSITION 28-52.490 048-21.634E TO 28-55.298N  
048-28.485E ON 14 DEC 24 AND WILL REMAIN STATIONED  
UNTIL END OF DEC 25 MARINERS CAUTIONED KEEP  
WELL CLEAR OF ABOVE MENTIONED AREA

-----  
101500 UTC DEC 24

NAVAREA IX 488/24

IRAN

KUH-E MAND

CHARTS BA 2847, 2883 AND 2884

FOLLOWING LATERAL MARKS ESTABLISHED:

- A. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(2)6SEC 7M  
ESTABLISHED 28-14.55N 051-16.29E
- B. PORT HAND BEACON TOWER WITH TOPMARK FL(2)6SEC 7M  
ESTABLISHED 28-14.48N 051-16.24E

C. PORT HAND BEACON TOWER WITH TOPMARK FL(2)6SEC 7M  
ESTABLISHED 28-31.89N 051-05.09E  
MARINERS CAUTIONED

-----  
091500 UTC DEC 24  
NAVAREA IX 486/24  
RED SEA  
SAUDI ARABIA, JIZAN  
CHARTS BA 15, 16, 157 AND 2964  
1. BUOY FCH-4 FL (2) R 6 SEC IN POSITION 16-51.12N 042 24.74E REPORTED  
MISSING MARINERS CAUTIONED  
2. BUOY F1 RESTORED CANCEL NAVAREA IX 474/24

-----  
040700 UTC DEC 24  
NAVAREA IX 476/24  
ARABIAN SEA  
PAKISTAN  
CHARTS PAK 33, 57 (INT 751), BA 707 AND 4705  
MSV AL PIRANPIR (MMSI 419956499) REPORTED SUNK IN  
POSITION 22-44N 066-24E MARINERS CAUTIONED

-----  
011500 UTC DEC 24  
NAVAREA IX 470/24  
SOUTHERN GULF  
UAE  
BA CHARTS 3179, 3778 AND 3780  
DREDGING OPERATION IN PROGRESS BY MULTI VESSELS  
IN AREA BOUNDED BY FOLLOWING POSITION  
AC-01 24-08.77N 052-40.19E  
AC-02 24-08.85N 052-40.31E  
AC-03 24-10.14N 052-40.72E  
AC-04 24-11.28N 052-41.51E  
AC-05 24-11.37N 052-41.41E  
AC-06 24-09.20N 052-39.89E  
MARINERS CAUTIONED

-----  
011500 UTC DEC 24  
NAVAREA IX 468/24  
SOUTHERN GULF  
UAE  
CHARTS BA 3178, 3179 AND 2889  
ENVIRONMENTAL MONITORING AND MARKER BOUYS TEMPORARILY DEPLOYED IN FOLLOWING  
POSITIONS  
ENV BOUY 1 24-11.23N 052-40.96E FL.Y.2S  
ENV BOUY 2 24-10.89N 052-39.76E FL.Y.2S  
ENV BOUY 3 24-10.72N 052-41.83E FL.Y.2S

ENV BOUY 4	24-15.04N	052-47.48E	FL.Y.2S
ENV BOUY 5	25-07.56N	052-39.20E	FL.Y.2S
MARKER BOUY 1	24-11.53N	052-41.38E	FL.Y.5S
MARKER BOUY 2	24-11.29N	052-41.66E	FL.Y.5S
MARKER BOUY 3	24-10.31N	052-40.48E	FL.Y.5S
MARKER BOUY 4	24-10.05N	052-40.85E	FL.Y.5S
MARKER BOUY 5	24-09.16N	052-40.12E	FL.Y.5S
MARKER BOUY 6	24-09.10N	052-40.57E	FL.Y.5S

MARINERS CAUTIONED

-----

181500 UTC NOV 2024  
 NAVAREA IX 452/24  
 CENTRAL GULF  
 QATAR  
 CHARTS BA 2523 AND 2886  
 SCUBA DIVING OPERATION WILL BE CONDUCTED FOR CORAL  
 RELOCATION ENVIRONMENT PROJECT IN AREA BOUNDED BY  
 FOLLOWING COORDINATES:  
 26-05.33N 051-26.25E  
 26-05.23N 051-26.25E  
 26-05.22N 051-26.38E  
 26-05.33N 051-26.38E  
 MARINERS CAUTIONED

-----

041500 UTC NOV 24  
 NAVAREA IX 432/24  
 PERSIAN GULF  
 IRAN, DARGAHAN AND BOSTANEH PORTS  
 CHARTS BA 2441, 2887, 3173, 3599 AND IR 3086  
 FOLLOWING LATERAL MARKS ESTABLISHED:  
 A. PORT HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M  
 26-58.04N 056-02.77E  
 B. STARBOARD HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M  
 26-58.04N 056-02.71E  
 C. PORT HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M  
 26-30.44N 054-39.93E  
 B. STARBOARD HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M  
 26-30.48N 054-39.85E  
 MARINERS CAUTIONED

-----

161500 UTC OCT 24  
 NAVAREA IX 403/24  
 SAUDI ARABIA  
 APPROACHES TO DAMMAM  
 CHARTS BA 3777 AND 3812  
 BUOY D-7 FL(2)G.6S 26-35.26N 050-12.45E REPORTED UNLIT MARINERS CAUTIONED

-----  
161500 UTC OCT 24  
NAVAREA IX 402/24  
IRAN  
BANDAR-E SHENAS  
CHARTS BA 2441, 2887 AND 2888  
FOLLOWING LATERAL MARKS ESTABLISHED:  
A. PORT HAND BEACON TOWER WITH TOPMARK FL(1)5SEC 3M  
26-29.75N 054-46.98E  
B. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(1)5SEC  
3M 26-29.80N 054-47.02E  
MARINERS CAUTIONED

-----  
141500 UTC OCT 24  
NAVAREA IX 399/24  
SAUDI ARABIA  
ARABIAN GULF, APPROACHES TO JUBAIL  
CHARTS BA 3719 AND 3788  
BUOY ANCHORAGE 3 FL.Y.5S 27-10.82N 049-47.00E REPORTED  
MISSING MARINERS CAUTIONED

-----  
271500 UTC SEP 24  
NAVAREA IX 382/24  
CENTRAL GULF  
QATAR  
CHARTS BA 2523, 2883 AND 2886  
1. ROV OPERATIONS BY VESSEL MPSV HALUL 49 FOR SEVERAL PLATFORMS  
IN AREA BOUNDED BY FOLLOWING COORDINATES EXTENDED TILL END OF JAN 25:  
A. 26-43.55N 051-50.86E  
B. 26-43.55N 052-04.14E  
C. 26-26.81N 052-04.14E  
D. 26-26.81N 051-50.86E  
MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND GIVE WIDE BERTH  
2. CANCEL NAVAREA IX WARNING 209/24

-----  
181500 UTC SEP 24  
NAVAREA IX 365/24  
NORTHERN GULF  
KUWAIT  
CHARTS BA 1223, 2882 AND 3773  
MOORING BUOY M1 PERMANENTLY MOVED FROM POSITION  
29-06.44N 048-17.68E TO 29-06.57N 048-17.27E  
MARINERS CAUTIONED

-----  
161530 UTC SEP 24  
NAVAREA IX 363/24

IRAN  
KHALIJ-E CHABAHAR  
CHART BA 38, 2851 AND 2858  
PORT HAND PILLAR LIGHTBUOY FL(2)5SEC 5M MOVED 0.2M  
NORTH-EAST FROM 25 18.61N 060 34.82E TO 25 18.72N  
060 34.98E(.) MARINERS CAUTIONED

-----  
161530 UTC SEP 24  
NAVAREA IX 362/24  
SOUTHERN GULF  
UAE  
CHARTS BA 2889 AND 3175  
MV KNIDOS REPORTED SUNK WITH FLOATING DEBRIS IN POSITION  
25-35.02N 054-51.15E MARINERS NAVIGATE WITH CAUTION  
AND KEEP CLEAR OF THE AREA

-----  
161500 UTC SEP 24  
NAVAREA IX 361/24  
IRAN  
JAZIREH-YE LARK  
CHARTS BA 2851, 2888 AND 3173  
NORTH CARDINAL PILLAR LIGHT BUOY WITH TOPMARK Q 5M 4 METERS ESTABLISHED  
IN POSITION 26-53.49N 056-21.26E MARINERS CAUTIONED

-----  
031500 UTC SEP 24  
NAVAREA IX 340/24  
IRAN  
JAZIREH-YE QEYS  
CHARTS BA 2887 AND 3409  
FOLLOWING LATERAL MARKS ESTABLISHED:  
A.STARBOARD BEACON TOWER WITH TOPMARK FL(2)6SEC 3M ESTABLISHED  
IN POSITION 26-31.35N 054-02.98E  
B.PORT BEACON TOWER WITH TOPMARK FL(2)6SEC 3M ESTABLISHED  
IN POSITION 26-31.36N 054-03.03E  
C.STARBOARD BEACON TOWER WITH TOPMARK FL(1)5SEC 3M ESTABLISHED  
IN POSITION 26-34.66N 053-56.80E  
D.PORT BEACON TOWER WITH TOPMARK FL(1)5SEC 3M ESTABLISHED  
IN POSITION 26-34.60N 053-56.76E  
MARINERS CAUTIONED

-----  
011500 UTC SEP 24  
NAVAREA IX 333/24  
GULF OF OMAN  
IRAN  
CHARTS BA 2888, 3171, 3173 AND 3599  
FOLLOWING NEW TRAFFIC CONTROL TOWERS ESTABLISHED:

A. SHAHID BAHONAR TRAFFIC CONTROL TOWER, 22 METERS HEIGHT,  
IN POSITION 27-09.22N 056-12.22E  
B. SHAHID HAGHANI TRAFFIC CONTROL TOWER, 12 METERS HEIGHT,  
IN POSITION 27-10.45N 056-16.91E  
C. BUNJI TRAFFIC CONTROL TOWER, 5 METERS HEIGHT, IN  
POSITION 25-54.67N 057-16.50E  
D. JASK TRAFFIC CONTROL TOWER, 25 METERS HEIGHT, IN  
POSITION 25-38.74N 057-46.02E  
MARINERS CAUTIONED

-----  
291500 UTC AUG 24  
NAVAREA IX 329/24  
CENTRAL GULF  
QATAR  
CHARTS BA 2523, 2887, 2886 AND 3950  
PIPE LAYING OPERATION IN PROGRESS BY NON-PROPELLED BARGE  
'DERRICK BARGE 30' IN AREA BOUNDED BY FOLLOWING POSITIONS:  
25-57.01N 051-27.34E  
25-47.74N 052-06.21E  
26-15.43N 052-24.61E  
26-15.49N 052-16.53E  
MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTIONED, GIVE  
WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF  
CHANNEL 16

-----  
211500 UTC AUG 2024  
NAVAREA IX 311/24  
RED SEA  
SAUDI ARABIA  
PORT OF NEOM (DUBA PORT)  
CHART BA 12  
LIGHT (Fl.12s 15m 5M) AND RACON IN POSITION  
27-39.10N 035-16.70E REPORTED UNRELIABLE  
(.) MARINERS CAUTIONED

-----  
151500 UTC AUG 2024  
NAVAREA IX 299/24  
CENTRAL GULF  
BAHRAIN  
CHARTS BA 3736, 3737 AND 3790  
1. OPERATIONS FOR TRESTLE CONSTRUCTION, SEABED EXCAVATION AND PIPELINE  
LAYING ACTIVITIES OF BAPCO TERMINAL TO SITRA PORT EXTENDED TILL END OF JUN 25  
IN THE FOLLOWING BOUNDED AREA:  
26-10.03N 050-39.57E  
26-10.05N 050-39.72E  
26-10.07N 050-40.00E  
26-09.98N 050-40.28E



26-09.77N 050-40.42E  
26-09.73N 050-40.37E  
26-10.00N 050-39.90E  
26-09.95N 050-39.72E  
26-09.88N 050-39.58E  
26-09.95N 050-39.55E

MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION, MAINTAIN LISTENING WATCH ON VHF CHANNEL 16/72/74 (BAHRAIN PORT CONTROL AND BAPCO WHARF CONTROL)

2. CANCEL NAVAREA IX WARNING 007 OF 24

-----  
061500 UTC AUG 2024  
NAVAREA IX 289/24  
RED SEA  
SAUDI ARABIA (SHAYBARA ISLAND)  
CHARTS BA 159  
SEAPLANE LANDING AREA ESTABLISHED  
BOUNDED BY FOLLOWING POSITIONS:  
25-22.54N 036-55.03E  
25-21.90N 036-55.76E  
25-21.48N 036-54.97E  
25-21.95N 036-55.84E  
MARINERS CAUTIONED

-----  
051500 UTC AUG 2024  
NAVAREA IX 288/24  
CENTRAL GULF  
QATAR  
CHARTS BA 2523 AND 2886  
WAVE RIDER BUOY FL (5)Y 2.5S DEPLOYED IN POSITION  
26-26.52N 051-57.86E MARINERS CAUTIONED

-----  
021500 UTC AUG 2024  
NAVAREA IX 285/24  
ARABIAN SEA  
YEMEN  
CHARTS BA 6, 2964, 2970 AND 3784  
UNLIT VESSEL ROYAL BLUE (IMO NO 8795962) ANCHORED IN POSITION  
14-21.60N, 048-59.92E MARINERS CAUTIONED

-----  
311500 UTC JUL 2024  
NAVAREA IX 281/24  
SOUTHERN GULF  
UAE  
CHARTS BA 2887, 2888, 3176 AND 3739  
SPECIAL MARK BUOY FL Y DEPLOYED IN POSITION  
25-12.10N 055-00.63E MARINERS CAUTIONED

-----  
181500 UTC JUL 2024  
NAVAREA IX 267/24  
OMAN  
ARABIAN SEA  
CHARTS OM 1, 3501 AND BA 3785  
SAR OPERATION FOR VESSEL "PRESTIGE FALCON" MISSING CREW IN PROGRESS  
CENTERED AROUND 19-09.50N, 058-18.30E MARINERS ARE ADVISED TO  
NAVIGATE WITH CAUTION AND KEEP SHARP LOOK FOR MISSING CREW

-----  
081500 UTC JUL 2024  
NAVAREA IX 253/24  
BANDAR-E PARS  
IRAN  
CHART BA 2883  
STARBOARD BEACON TOWER WITH TOPMARK FL(1)5SEC 7M 9 METERS  
ESTABLISHED AT 27-34.96N 052-30.66E PORT BEACON TOWER WITH  
TOPMARK FL(1)5SEC 7M 9 METERS ESTABLISHED AT 27-34.82N 052-30.47E  
(.) MARINERS CAUTIONED

-----  
061500 UTC JUL 2024  
NAVAREA IX 250/24  
NORTHERN GULF  
KUWAIT  
CHARTS KU 1, 4, BA 1265, 2884 AND 3773  
A TEMPORARILY RESTRICTED AREA ESTABLISHED FOR 'NO NAVIGATION,  
FISHING AND ANCHORING' IN LOCATION CENTERED AT 29-24.10N  
048-50.50E WITH 600 METERS DIAMETER MARINERS CAUTIONED

-----  
031500 UTC JUL 2024  
NAVAREA IX 240/24  
IRAN  
BANDAR-E SHAHID RAJAI  
CHARTS BA 3173 AND 3599  
SHAHID RAJA'I CONTROL TOWER (HEIGHT 66 METERS) INSTALLED  
AT LOCATION 27-06.13N 056-04.57E NON-IALA RED FLASHING  
LANTERN INSTALLED ON 12 METER LATTICE TOWER ON TOP OF  
CONTROL TOWER MARINERS CAUTIONED

-----  
281500 UTC MAY 2024  
NAVAREA IX 200/24  
ARABIAN GULF  
SAUDI ARABIA (JIZAN)  
CHARTS BA 15, 157 AND 2964  
FOLLOWING BUOYS REPORTED UNLIT:

NO.103 16 59.79N 41 20.56E (LATERAL STBD)  
NO.109 17 10.40N 41 22.62E (LATERAL PORT)  
MARINERS CAUTIONED

-----  
261230 UTC MAY 2024  
NAVAREA IX 198/24  
IRAN  
SHATT AL ARAB  
CHART BA 3842 (INT 7292)  
STARBOARD HAND PILLAR BUOY WITH TOPMARK, CHARACTERISTICS  
FL(3)18SEC 5M ESTABLISHED AT 29-52.58N 048-40.86E  
MARINERS CAUTIONED

-----  
291400 UTC APR 2024  
NAVAREA IX 168/24  
PAKISTAN  
KHOBAR CREEK  
CHARTS PAK 28, 33, BA 39 AND 707  
1. FISHING VESSEL REPORTED SUNK IN VICINITY OF POSITION  
23-51.8N 067-20.9E MARINERS CAUTIONED  
2. CANCEL NAVAREA IX 113/24

-----  
261500 UTC APR 2024  
NAVAREA IX 163/24  
SOUTHERN GULF  
UAE  
CHARTS BA 2442, 2887 AND 3413  
“ZH” PLATFORM IN POSITION 25-38.82N 054-24.85E  
IN FATEH OIL FIELD REPORTED UNLIT MARINERS CAUTIONED

-----  
081500 UTC APR 2024  
NAVAREA IX 141/24  
ARABIAN GULF  
SAUDI ARABIA (PORT AL JUBAIL)  
CHARTS BA 3718 AND 3719  
BUOY NO 7 IN POSITION 27 02.07N 049 41.60E UNLIT  
MARINERS CAUTIONED

-----  
071500 UTC APR 2024  
NAVAREA IX 140/24  
BANDAR E JASK  
IRAN  
CHARTS BA 2888 AND 2851  
LATTICE BEACON 25-38.19N 057-45.86E TEMPORARILY REMOVED  
MARINERS CAUTIONED

-----  
061500 UTC APR 2024  
NAVAREA IX 139/24  
PERSIAN GULF  
IRAN  
CHARTS BA 2837 AND 2888  
STARBOARD BEACON WITH TOPMARK FL(1) 5 SEC 3M 6 METERS ESTABLISHED  
IN POSITION 26-58.42N 055-44.99E MARINERS CAUTIONED

-----  
011500 UTC APRIL 2024  
NAVAREA IX 132/24  
ARABIAN GULF  
SAUDI ARABIA (PORT AL JUBAIL)  
CHARTS BA 3718 AND 3719  
FOLLOWING BUOYS REPORTED UNLIT:  
BUOY NO 2 27 14.63N 049 58.92E  
BUOY CH 5 27 02.02N 049 41.88E  
MARINERS CAUTIONED

-----  
011500 UTC APRIL 2024  
NAVAREA IX 130/24  
IRAN  
SHATT AL ARAB  
CHART BA 3842 (INT 7292)  
STARBOARD LIGHTBUOY NO.11 FL(2)18SEC 5M MOVED FROM 29-52.74N  
048-40.94E TO 29-52.58N 048-40.86E MARINERS CAUTIONED

-----  
160930 UTC MAR 2024  
NAVAREA IX 115/24  
IRAN  
RAS AL KUH  
CHARTS BA 2888 AND 3171  
SINGLE POINT MOORING BUOY NO.1 ESTABLISHED IN POSITION 25-50.75N  
057-14.54E MARINERS CAUTIONED

-----  
041500 UTC MAR 24  
NAVAREA IX 103/24  
SAUDI ARABIA  
RED SEA  
CHARTS BA 15  
WEST CARDINAL BUOY 'MAK' IN POSITION 17-01.60N 041-13.45E  
REPORTED MISSING MARINERS CAUTIONED

-----  
291500 UTC FEB 2024

NAVAREA IX 094/24

SOUTHERN GULF

UAE

CHARTS BA 3174, AND 3404

RECLAMATION WORK IN PROGRESS IN AREA BOUNDED BY FOLLOWING COORDINATES:

25-58.19N 056-02.13E

25-58.01N 056-02.82E

25-57.38N 056-02.87E

25-57.62N 056-01.95E

FOLLOWING TEMPORARY MARKER BUOYS DEPLOYED:

B1 YELLOW FLASHING 25-58.15N 056-02.30E

B2 YELLOW FLASHING 25-57.85N 056-02.21E

B3 YELLOW FLASHING 25-57.56N 056-02.11E

MARINERS CAUTIONED

-----  
191500 UTC FEB 24

NAVAREA IX 076/24

SOUTHERN GULF

UAE

CHARTS BA 2443, 2887 AND 2889

SEMI-SUBMERGED UNLIT WRECK REPORTED IN VICINITY  
OF POSITION 25-11.64N 054-10.12E MARINERS CAUTIONED

-----  
SECURITE

291500 UTC JAN 2024

NAVAREA IX 048/24

CENTRAL GULF

BAHRAIN

CHARTS BA 3736, 3737 AND 3738

1. TWO NEW PIPELINES ESTABLISHED IN  
ROUTES BOUNDED BY FOLLOWING COORDINATES:

26-12.06N 050-39.61E

26-11.15N 050-39.24E

26-10.10N 050-39.20E

26-09.79N 050-39.14E

MARINERS CAUTIONED

2. CANCEL NAVAREA IX 026/24

-----  
SECURITE

251500 UTC JAN 2024

NAVAREA IX 042/24

NORTHERN GULF

KUWAIT

CHARTS BA 1223, 3773, LOCAL CHARTS 1, 4, 8

1. CARGO VESSEL BAHAREH REPORTED SUNK IN POSITION 29-05.49N  
048-22.09E ISOLATED DANGER BUOY TEMPORARILY DEPLOYED IN

POSITION 29-05.52N 048-22.06E WITH CHARACTERISTICS FL(2) 5SEC  
(.) MARINERS CAUTIONED  
2. CANCEL NAVAREA IX 020/24

-----  
SECURITE  
271500 UTC DEC 2023  
NAVAREA IX 475/23  
IRAN  
JAZIREH-YE KHARKU  
CHARTS BA 11, 2882 AND 2884  
EMERGENCY WRECK MARKING BUOY IN POSITION 29-19.24N 050-19.70E  
PERMANENTLY DISCONTINUED WEST CARDINAL PILLAR BUOY WITH  
TOPMARK Q (9) 15SEC 5M ESTABLISHED IN POSITION 29-19.20N 050-19.70E  
(.) MARINERS CAUTIONED

-----  
SECURITE  
041500 UTC DEC 2023  
NAVAREA IX 453/23  
RED SEA  
SAUDI ARABIA  
CHARTS BA 158, 326, 327, 328  
ISOLATED DANGER BUOY A3-1 GP FL(2)10SEC WITH  
TOPMARK 2 BLACK SPHERES ESTABLISHED IN POSITION  
23-57.95N 038-09.63E MARINERS CAUTIONED

-----  
SECURITE  
011500 UTC DEC 2023  
NAVAREA IX 448/23  
CENTRAL GULF  
BAHRAIN  
CHARTS BA 3736, 3737 AND 3790  
1. MINA SALMAN OUTER REAR LEADING LIGHT IN POSITION  
26-11.17N 050-39.25E SHIFTED TO 26-11.165N 050-39.261E  
AND RESTORED TO NORMAL MARINERS CAUTIONED  
2. CANCEL NAVAREA IX 445/23

-----  
SECURITE  
291500 UTC NOV 2023  
NAVAREA IX 447/23  
PERSIAN GULF  
IRAN  
CHARTS BA 2523, 2837, 2883 AND 2886  
SEAPAD ACCOMMODATION BARGE TEMPORARILY MOORED AT 26-41.40N 052-15.50E IN  
SOUTH PARS GAS FIELD WITH ANCHORS POSITIONED AT FOLLOWING LOCATIONS:  
STARBOARD SIDE PORT SIDE  
S1: 26-42.20N 052-15.15E P1: 26-41.84N 052-14.67E

S3: 26-42.23N 052-15.72E P3: 26-41.22N 052-14.58E  
S5: 26-41.60N 052-16.42E P4: 26-40.59N 052-15.24E  
S6: 26-41.13N 052-16.40E P6: 26-40.58N 052-15.74E  
MARINERS CAUTIONED

-----  
SECURITE

201500 UTC NOV 2023

NAVAREA IX 435/23

IRAN

BANDAR-E AFTAB

CHART BA 2837, 2887

FISH FARM ESTABLISHED IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 26-42.29N 054-03.88E

B. 26-42.15N 054-04.08E

C. 26-41.97N 054-03.89E

D. 26-42.12N 054-03.68E

MARINERS CAUTIONED

-----  
SECURITE

091500 UTC OCT 2023

NAVAREA IX 376/23 IRAN TANGHEH-YE HORMOZ

CHARTS BA 2888, 2851 AND 3173

2. FOLLOWING CHANGES IN AIDS TO NAVIGATION OF  
HORMOZGAN COASTAL WATERS

A. STARBOARD HAND BEACON TOWER FL 5 SEC 5 M 5 METERS  
ESTABLISHED IN POSITION 25-40.99N 057-51.93E

B. PORT HAND BEACON TOWER FL 5 SEC 5 M 5 METERS  
ESTABLISHED IN POSITION 25-41.04N 057-51.92E

C. LATTICE BEACON TEMPORARILY DISCONTINUED IN  
POSITION 27-05.25N 056-49.48E

D. ISOLATED DANGER BUOY PERMANENTLY REMOVED IN  
POSITION 27-04.38N 056-44.10E AND ISOLATED DANGER  
PERCH BEACON WITH TOP MARK FL(2)6 SEC 5 M ESTABLISHED  
ON WRECK IN POSITION 27-04.23N 056-44.62E

E. PORT HAND BUOY FL 5 SEC 5 M IN POSITION  
27-06.18N 056-14.88E MOVED TO 27-06.62N 056-14.95E

F. TOWER BEACON FL(2) 15 SEC 18 M 40 METERS RACON  
INOPERATIVE IN POSITION 25-49.85N 057-19.20E

3. MARINERS CAUTIONED

4. CANCEL NAVAREA IX WARNING 375 OF 2023

-----  
SECURITE

191500 UTC SEP 2023

NAVAREA IX 355/23 SOUTHERN GULF UAE

CHARTS BA 2444 AND 3413

2. LOST ANCHOR WITH CHAIN REPORTED IN POSITION  
25-07.23N 052-53.27E

3. MARINERS ARE ADVISED NOT TO ANCHOR IN THE VICINITY

-----  
SECURITE

131500 UTC SEP 2023

NAVAREA IX 346/23 CENTRAL GULF BAHRAIN

CHARTS BA 2837, 2847 AND 2886

2. CABLE INSTALLATION OPERATION IN PROGRESS BY VESSELS  
HALL-1, ABS, OCEAN-10 BARGE, OCEAN CAT AND TUG OCEAN  
CABLE IS BEING LAID BETWEEN RAS AL BAR AND HAWAR ISLAND  
ON FOLLOWING ROUTE:

25-47.89N 050-34.07E

25-46.59N 050-37.04E

25-44.47N 050-37.68E

25-42.04N 050-44.08E

25-41.95N 050-45.27E

3. VESSELS WILL BE RESTRICTED IN THEIR ABILITY TO MANOEUVRE  
AND AN EXCLUSION AREA OF 500 METERS IS REQUESTED

4. MARINERS CAUTIONED

5. CANCEL NAVAREA IX WARNING 239 OF 2023

-----  
SECURITE

111500 UTC SEP 2023

NAVAREA IX 341/23 IRAN KHALIJ-E-CHABAHAR

CHART OM 7501

2. FOLLOWING AIDS TO NAVIGATION HAVE BEEN MOVED TO  
NEW POSITIONS IN KHALIJ-E CHABAHAR

BUOY NAME	OLD POSITION	NEW POSITION
STARBOARD HAND BUOY FL (2) 5s 5M	25-18.89N 060-35.78E	25-18.86N 060-35.81E
STARBOARD HAND BUOY FL (2) 5s 5M	25-18.97N 060-35.96E	25-18.98N 060-36.06E
PORT HAND BUOY FL (2) 5s 5M	25-18.54N 060-34.74E	25-18.61N 060-34.82E

3. SPECIAL BUOY FL(1) 5s 3M ESTABLISHED IN POSITION

25-18.41N 060-36.05E

4. MARINERS CAUTIONED

-----  
SECURITE

091500 UTC SEP 2023

NAVAREA IX 338/23 PERSIAN GULF (IRAN)

LAVAN ISLAND CHART BA 2883, 2886 AND 2887

2. SOUTH CARDINAL LIGHTBUOY, Q(6)+LFL 15SEC 5M ESTABLISHED  
IN POSITION 26-47.92N 053-12.83

3. MARINERS CAUTIONED

-----  
SECURITE



031500 UTC SEP 2023

NAVAREA IX 326/23 IRAN KHALIJ-E-CHABAHAR

CHART OM 7501(INT 7016)

2. SPECIAL BUOY FL (1)5SEC 3M MOVED FROM 25-18.41N 060-36.05E TO 25-18.52N 060-35.99E
3. MARINERS CAUTIONED

-----  
SECURITE

281500 UTC AUG 2023

NAVAREA IX 318/23 SOUTHERN GULF UAE

CHARTS BA 2443, 2889, 3178 AND 3179

2. OLD SPM SOUTH OF ZIRKUH ISLAND IN POSITION 24-51.60N, 053-05.41E REPORTED UNLIT
3. MARINERS CAUTIONED

-----  
SECURITE

271500 UTC AUG 2023

NAVAREA IX 314/23 RED SEA SAUDI ARABIA

(.) RA'S KURKUMA UMMAHAT ALSHAYKH ISLAND

CHARTS BA 159

2. SEA PLANE LANDING AND OPERATIONAL AREA ESTABLISHED AT UMMAHAT ALSHAYKH ISLAND IN FOLLOWING POSITIONS:  
25 32.31N 036 43.59E  
25 34.88N 036 44.71E  
25 33.40N 036 48.15E  
25 31.06N 036 46.43E
3. MARINERS CAUTIONED

-----  
SECURITE

231500 UTC AUG 2023

NAVAREA IX 307/23 IRAN JAZIREH YE QESHM CHART

BA 2441, 2887 AND 2888

2. ESTABLISHMENT AND MOVEMENT OF AIDS TO NAVIGATION IN JAZIREH YE QESHM
  - A. NORTH CARDINAL PILLAR BUOY WITH TOPMARK Q(1)  
1 SEC 5M 3 METER ESTABLISHED IN POSITION 26-39.42N 055-14.85E
  - B. WEST CARDINAL PILLAR BUOY WITH TOPMARK Q(9)  
15 SEC 5M 3 METER ESTABLISHED IN POSITION 26-35.63N 055-12.76E
  - C. WEST CARDINAL PILLAR BUOY WITH TOPMARK 26-37.21N 055-12.88E Q(9) 15 SEC 7M 3 METER MOVED IN POSITION 26-37.40N 055-12.71E
  - D. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(1)  
5 SEC 3M ESTABLISHED IN POSITION 26-39.67N 055-16.15E
  - E. PORT HAND BEACON TOWER WITH TOPMARK FL(1)  
5 SEC 5M ESTABLISHED IN POSITION 26-39.71N 055-16.08E
3. MARINERS CAUTIONED

-----  
SECURITE

071600 UTC AUG 2023

NAVAREA IX 293/23 PAKISTAN ORMARA

CHARTS PAK 24, PAK 33, PAK 57 (INT 751), PAK 58 (INT 7019)  
AND BA 38

2. FISHING BOAT AL-MUSTAFA REPORTED SUNK IN VICINITY OF  
POSITION (25-10N 065-04E)
3. MARINERS CAUTIONED

-----  
SECURITE

301500 UTC MAY 2023

NAVAREA IX 226/23 IRAN KHOWR-E MINAB

CHARTS BA 2888 AND 3173

2. FOLLOWING LATERAL BUOYS ESTABLISHED AT ENTRANCE  
OF KOLAHY PORT:
  - A. STARBOARD HAND PILLAR LIGHTBUOY WITH TOP MARK  
IN POSITION 27-03.49N 056-47.43E, CHARACTERISTICS  
FL(1) 5 SEC 3 MILE
  - B. PORT HAND PILLAR LIGHTBUOY WITH TOP MARK IN  
POSITION 27-03.55N 056-47.40E, CHARACTERISTICS  
FL(1) 5 SEC 3 MILE
3. MARINERS CAUTIONED

-----  
SECURITE

280230 UTC MAY 2023

NAVAREA IX 221/23 PAKISTAN SONMIANI BAY

CHARTS BA-39, 707, PAK 22 AND 33

2. MV ERA (IMO NO 8121422) REPORTED GROUNDED IN  
POSITION 25 08.60N 066 42.90E.
3. MARINERS CAUTIONED.
4. CANCEL NAVAREA IX WARNING 220 OF 2023

-----  
SECURITE

031500 UTC MAY 2023

NAVAREA IX 190/23 IRAN TOREH-YE KHVORAN

CHART BA 2837, 2888 AND 3173

2. SUBMERGED PIPELINE (01 MILE LONG) ESTABLISHED FROM  
27-01.35N 055-56.90E TO 27-00.73N 055-57.87E.
  3. ISOLATED DANGER PILLAR BUOYS WITH TOPMARK, FL(2) 6SEC 5M,  
ESTABLISHED IN FOLLOWING POSITIONS:
    - A. 27-01.09N 055-57.36E
    - B. 27-01.03N 055-57.46E
    - C. 27-00.76N 055-57.88E
  4. MARINERS CAUTIONED
-

SECURITE

271500 UTC APR 2023

NAVAREA IX 177/23 SOUTHERN GULF UAE

CHARTS BA 2444, 2889 AND 3178

2. LOST ANCHOR REPORTED IN POSITION 25-01.57N 053-03.22E
3. MARINERS ARE ADVISED NOT TO ANCHOR IN THE VICINITY

-----  
SECURITE

071500 UTC APR 2023

NAVAREA IX 159/23 SOUTHERN GULF U A E

CHARTS BA 2837, 2858, 2889, 3178 AND 3179

2. MAJOR CONSTRUCTION WORKS IN PROGRESS TO CONSTRUCT ARTIFICIAL ISLANDS INSIDE HAIL AND GHASHA OIL FIELDS AT ABU DHABI OFFSHORE ON THE FOLLOWING BOUNDARIES:

GHASHA FIELD AREA:

P01 24-40.22N 052-52.61E  
P02 24-39.08N 053-00.18E  
P03 24-30.79N 053-03.24E  
P04 24-26.33N 052-56.63E  
P05 24-30.70N 052-52.08E

HAIL FIELD AREA:

P01 24-24.56N 053-21.72E  
P02 24-24.46N 053-28.22E  
P03 24-17.96N 053-28.09E  
P04 24-18.07N 053-21.60E

3. ENTRY IN BOUNDED AREA IS STRICTLY PROHIBITED, MAINTAIN COMMUNICATION WITH MARINE CONTROL CENTER ON VHF CH.16
4. CANCEL NAVAREA IX WARNING 024/21

-----  
SECURITE

101500 UTC MAR 2023

NAVAREA IX 116/23 PAKISTAN KARACHI APPROACHES CHARTS PAK 5

BA 40, BA 58 AND BA 707

2. WRECK BUOY IN POSITION 24-46.861N 066-56.048E REPORTED UNLIT
3. MARINERS CAUTIONED

-----  
SECURITE

071500 UTC MAR 2023

NAVAREA IX 111/23 IRAN BANDARE JASK

CHART BA 2888

2. PILLER BUOYS ESTABLISHED AS FOLLOWS:
  - A. STARBOARD HAND PILLER BUOY IN POSITION 25-39.13N 057-45.95E WITH TOP MARK AND CHARACTERISTICS FL(2) 5 SEC 5 MILE
  - B. PORT HAND PILLER BUOY IN POSITION 25-39.10N 057-46.02E WITH TOP MARK AND CHARACTERISTICS FL(2) 5 SEC 5 MILE
3. MARINERS CAUTIONED

-----  
SECURITE

281500 UTC FEB 2023

NAVAREA IX 096/23 IRAN BANDAR-E SHAHID RAJAI CHART BA 2888, 3173 AND 3599

2. CHANGES IN CHARACTERISTICS OF AIDS TO NAVIGATION:

A. STARBOARD HAND PILE BEACON WITH TOPMARK IN POSITION

27-06.34N 056-04.94E, FL(3) 5 SEC 7 MILES 7 METERS

B. PORT HAND PILE BEACON WITH TOPMARK IN POSITION 27-06.30N 056-04.77E, FL(3) 5  
SEC 7

MILES 7 METERS

C. STARBOARD HAND PILE BEACON WITH TOPMARK IN POSITION

27-06.14N 056-05.01E, FL(2) 5 SEC 7 MILES 5 METERS

D. PORT HAND PILE BEACON WITH TOPMARK IN POSITION 27-06.20N 056-04.84E, FL(2) 5  
SEC 7

MILES 5 METERS

3. MARINERS CAUTIONED

-----  
SECURITE

271500 UTC FEB 2023

NAVAREA IX 094/23 IRAN BANDARE KHAMIR CHART BA 2888

2. ESTABLISHMENT OF PILLER BUOYS IN TANGHEH-YE KHURAN

A. STARBOARD HAND PILLER BUOYS WITH TOP MARK FL(1) 5 SEC 5 MILE ESTABLISHED IN  
POSITION:

BUOY NO 01: 26-58.08N 055-43.50E

BUOY NO 03: 26-57.90N 055-40.94E

BUOY NO 05: 26-57.78N 055-39.65E

B. PORT HAND PILLER BUOYS WITH TOP MARK FL(1) 5 SEC 5 MILE ESTABLISHED IN POSITION:

BUOY NO 02: 26-57.90N 055-42.54E

BUOY NO 04: 26-57.62N 055-39.68E

3. MARINERS CAUTIONED

-----  
SECURITE

151600 UTC FEB 2023

NAVAREA IX 071/23 SOUTHERN GULF DUBAI

(AL FATEH OIL FIELD) CHARTS BA 3413

2. SUBSEA GAS LEAKAGE OBSERVED IN POSITION 25 38.9N 054 27.8E

SURFACE MARKER BUOY FITTED WITH RADAR REFLECTOR

AND WHITE FLASHING LIGHT LAID

3. MARINERS CAUTIONED

-----  
SECURITE

141500 UTC FEB 2023

NAVAREA IX 068/23 NORTHERN GULF KUWAIT

(ASH SHUWAYKH PORT) CHARTS BA 1214 AND 2884

2. DEVELOPMENT OF ANCHORAGE AREA NUMBER 1 TO 7

IN PROGRESS IN POSITION 29-21.16N 047-56.10E

3. MARINERS CAUTIONED

-----  
SECURITE

141500 UTC FEB 2023

NAVAREA IX 067/23 SOUTHERN GULF UAE (DUBAI)

CHARTS BA 2887, 2888, 2889, 3412 AND 3414

2. MOORING BUOYS DEPLOYED IN FOLLOWING POSITIONS:

25-08.14N 055-09.52E

25-07.78N 055-09.65E

25-14.77N 055-12.60E

25-14.34N 055-12.75E

3. MARINERS CAUTIONED

-----  
SECURITE

091500 UTC FEB 2023

NAVAREA IX 058/23 CENTRAL GULF QATAR

CHARTS BA 2523, 2837, 2883 AND 2886

2. SAFETY ZONES OF 1500 METER ESTABLISHED AROUND  
SPMs IN FOLLOWING POSITIONS:

SPM2 26-35.496N 052-01.986E

SPM3 26-38.808N 051-53.496E

SPM4 26-40.375N 051-53.896E

3. MARINERS ARE ADVISED TO OBTAIN APPROVAL FROM  
AL SHAHEEN OIL TERMINAL ON VHF CHANNEL 16 OR 72  
WHILE ENTERING THE AREA

-----  
SECURITE

231500 UTC JAN 2023

NAVAREA IX 034/23 SAUDI ARABIA JIZAN

CHARTS BA 15, 157 AND 2964

2. JIZAN APPROACH CHANNEL BUOYS REPORTED UNLIT/  
DAMAGED/MISSING FROM CHARTED POSITION AS UNDER:

BUOY	POSITIONS	TYPE AND ISSUE
101	16-56.77N 041-17.37E	SAFE WATER (UNLIT)
102	16-56.71N 041-18.84E	STBD LATERAL (UNLIT)
104	16-59.72N 041-19.28E	ISOLATED DANGER (MISSING)
108	17-08.41N 041-24.40E	STBD LATERAL (MISSING)
110	17-13.52N 041-34.57E	STBD LATERAL (UNLIT)
111	17-14.70N 041-33.30E	PORT LATERAL (MISSING)
112A	17-19.15N 041-40.95E	PORT LATERAL (UNLIT)
113	17-15.45N 041-49.63E	PORT LATERAL (UNLIT)
117	17-06.25N 042-03.82E	PORT LATERAL WITH RECON B (UNLIT)
118	17-02.30N 042-02.10E	STBD LATERAL (UNLIT)
122	17-04.95N 042-10.41E	STBD LATERAL (DAMAGED UNLIT)
124	17-09.82N 042-13.02E	PORT LATERAL (DAMAGED UNLIT)
129	17-13.47N 042-14.49E	PORT LATERAL MARK (UNLIT)

209	17-17.81N 042-07.10E	SPECIAL MARK (UNLIT)
210	17-15.39N 042-16.09E	SPECIAL MARK (UNLIT)
211	17-17.38N 042-15.15E	SPECIAL MARK (UNLIT)
212	17-17.51N 042-12.61E	SPECIAL MARK (UNLIT)
213	17-14.45N 042-12.07E	SPECIAL MARK (UNLIT)
214	17-15.40N 042-08.20E	SPECIAL MARK (UNLIT)
215	17-19.48N 042-07.29E	SPECIAL MARK (UNLIT)
216	17-20.30N 042-10.09E	SPECIAL MARK (UNLIT)
217	17-20.30N 042-11.70E	SPECIAL MARK (UNLIT)
302	17-14.64N 042-16.97E	PORT LATERAL MARK (UNLIT)
303	17-14.76N 042-17.41E	STBD LATERAL MARK (UNLIT)
307	17-15.29N 042-18.05E	STBD LATERAL MARK (UNLIT)
308	17-15.44N 042-17.92E	PORT LATERAL MARK (UNLIT)
313	17-16.09N 042-19.01E	STBD LATERAL MARK (MISSING)
314	17-16.24N 042-18.89E	PORT LATERAL MARK (MISSING)
316	17-16.50N 042-19.21E	PORT LATERAL MARK (UNLIT)
602	17-14.92N 042-10.13E	SPECIAL MARK (UNLIT)
603	17-16.60N 042-07.65E	SPECIAL MARK (UNLIT)
604	17-17.80N 042-09.00E	SPECIAL MARK (UNLIT)
606	17-18.65N 042-07.19E	SPECIAL MARK (UNLIT)
607	17-19.88N 042-08.69E	SPECIAL MARK (UNLIT)
608	17-17.44N 042-13.88E	SPECIAL MARK (UNLIT)
609	17-16.72N 042-15.46E	SPECIAL MARK (UNLIT)
610	17-16.05N 042-15.79E	SPECIAL MARK (UNLIT)
611	17-14.43N 042-15.29E	SPECIAL MARK (UNLIT)
908	17-14.46N 042-16.58E	PORT LATERAL MARK (UNLIT)

3. MARINERS CAUTIONED

-----  
SECURITE

171500 UTC JAN 2023

NAVAREA IX 028/23 RED SEA SAUDI ARABIA (JEDDAH)

BA CHARTS 158 AND 2659

2. DGPS STATION 961 IN POSITION 21-28.4N 039-08.9E  
REPORTED OFF AIR

3. MARINERS CAUTIONED

-----  
SECURITE

221500 UTC DEC 2022

NAVAREA IX 513/22 RED SEA SAUDI ARABIA (YANBU)

(.) CHARTS BA 158 AND 327

2. YANBU COMMERCIAL PORT MOORING BUOY B-3 IN POSITION  
23-57.82N, 038-01.30E REPORTED MISSING

3. MARINERS CAUTIONED

-----  
SECURITE

151500 UTC DEC 2022

NAVAREA IX 507/22 IRAN BANDAR ABBAS

(BANDAR-E SHAHID RAJAI) CHARTS BA 2888, 3173  
AND 3599

2. ISOLATED DANGER LIGHTBUOY (FL (2) 6 SECOND 5 M)  
ESTABLISHED IN POSITION 27-06.60N 056 05.96E
3. SOUTH CARDINAL BEACON (Q (6) + LFL 15 SECOND 5 M)  
ESTABLISHED IN POSITION 27-06.86N 056-06.46E
4. MARINERS CAUTIONED

-----  
SECURITE

061500 UTC DEC 2022

NAVAREA IX 497/22 CENTRAL GULF BAHRAIN

CHARTS BA 3736, 3737 AND 3790

2. STARBOARD HAND BUOY S1-3 PERMANENTLY SHIFTED TO  
POSITION 26-11.31N, 050-37.24E

3. MARINERS CAUTIONED

-----  
SECURITE

301500 UTC NOV 2022

NAVAREA IX 489/22 RED SEA

SAUDI ARABIA (YANBU)(.) CHARTS BA 158 AND 327

- 2 YANBU COMMERCIAL PORT MOORING BUOY B-2 IN POSITION

23 59.10N, 038-01.70E REPORTED MISSING

- 3 MARINERS CAUTIONED

-----  
SECURITE

241500 UTC NOV 2022

NAVAREA IX 480/22 IRAN KHALIJ-E-CHAHBAHAR

CHARTS BA 2851

2. CHANGES IN AID TO NAVIGATION CHAHBAHAR APPROACH CHANNEL

A. BUOYS/BEACON MOVED:

SAFE WATER BUOY ISO (1) 4 SECOND 5M

FROM: 25-16.34N 060-33.23E

TO: 25-16.25N 060-33.29E

CHAHBAHAR LATTICE BEACON FL (2) 15 SECOND 12M

FROM: 25-17.17N 060-36.62E

TO: 25-17.18N 060-36.62E

PORT HAND BUOY NO.2 FL (2) 5 SECOND 5M

FROM: 25-18.92N 060-33.33E

TO: 25-19.02N 060-35.70E

B. NEW BUOYS/BEACON ESTABLISHED:

STARBOARD HAND BUOY NO.1 25-18.89N 060-35.78E FL(2)5SECOND 5M

STARBOARD HAND BUOY (HAFT-E TIR) 25-18.51N 060-36.85E FL(2)5SECOND 3M

STARBOARD HAND BEACON (BREAKWATER END) 25-18.37N 060-35.00E FL(3)6SECOND 5M

STARBOARD HAND BEACON (BREAKWATER BEND) 25-18.09N 060-35.80E FL(3)6SECOND 5M

PORT HAND BEACON (BREAKWATER END) 25-18.64N 060-36.02E FL(3)6SECOND 5M

C. BUOYS PERMANENTLY DISCONTINUED:

PREFERRED CHANNEL TO PORT HAND BUOY	25-18.81N 060-35.58E
SPECIAL BUOY	25-17.87N 060-36.25E
SOUTH CARDINAL BUOY	25-18.74N 060-35.05E
SOUTH CARDINAL BUOY	25-19.02N 060-35.71E

3. MARINERS CAUTIONED

-----  
SECURITE

221500 UTC NOV 2022

NAVAREA IX 477/22 IRAN RAS-E-BOSTANEH

CHARTS BA 2441, 2837 AND 2887

2. LATTICE BEACON IN POSITION 26-30.05N 054-37.32E

TEMPORARILY DISCONTINUED

3. MARINERS CAUTIONED.

-----  
SECURITE

010650 UTC NOV 2022

NAVAREA IX 443/22 EGYPT GULF OF

SUEZ CHARTS BA 159 AND 2374

2. ANCHORING PROHIBITED IN SUBMARINE CABLE

AREA BOUNDED BY FOLLOWING COORDINATES:

28-22.05N 033-04.90E

28-23.13N 033-06.34E

28-22.55N 033-07.05E

28-21.72N 033-05.79E

3. MARINERS CAUTIONED

-----  
SECURITE

151500 UTC SEP 2022

NAVAREA IX 358/22 IRAN BANDAR-E EMAM KHOMEINI

CHARTS BA 1269 AND 2884

2. BUOYS PERMANENTLY DISCONTINUED:

PORT HAND BUOY NO 40 30-22.82N 048-54.28E

PORT HAND BUOY NO 44 30-23.89N 049-00.58E

3. NEW BEACONS ESTABLISHED:

PORT HAND BEACON NO 40 30-22.84N 048-54.26E FL(1) 3SEC 7M

PORT HAND BEACON NO 44 30-23.90N 049-00.53E FL(2) 4SEC 7M

4. MARINERS CAUTIONED

-----  
SECURITE

160440 UTC MAY 2022

NAVAREA IX 185/22 NORTHERN GULF

KUWAIT CHARTS BA 2882, 2884 AND 3773

2. SOUTH CARDINAL BUOY (VQ (6) LFL 10 SECONDS)

TEMPORARILY DEPLOYED TO MARK SUNKEN VESSEL IN  
POSITION 29-19.65N 048-25.48E.

3. MARINERS CAUTIONED



-----  
SECURITE

310300 UTC AUG 2022

NAVAREA IX 331/22 PAKISTAN PORT MUHAMMAD BIN

QASIM CHARTS PAK 5 (INT 7314), 20 (INT 7316) AND BA 59

2. AHSAN CHANNEL FORWARD LEADING LIGHT (FLL) IN POSITION

24-37.98N 067-06.27E REPORTED DAMAGED

3. AHSAN CHANNEL REAR LEADING LIGHT (RLL) IN POSITION

24-39.44N 067-07.29E REPORTED UNLIT

4. MARINERS CAUTIONED

5. CANCEL NAVAREA WARNINGS 336/21 AND 194/22

-----  
SECURITE

301500 UTC AUG 2022

NAVAREA IX 328/22 PAKISTAN KPT CHARTS

PAK 30 (INT 7315) AND BA 40

2. FOLLOWING LEADING LIGHTS REPORTED NON OPERATIONAL:

FRONT LEADING LIGHT (FLL) 24-47.72N 067-00.06E OC G.7S 13 METER

REAR LEADING LIGHT (RLL) 24-47.96N 067-00.28E OC G.5S 31.5 METER

3. MARINERS CAUTIONED

-----  
SECURITE

190500 UTC AUG 2022

NAVAREA IX 311/22 UAE DUBAI CHARTS 2442,

2887, 2889 AND 3413

2. UNDER WATER OPERATION IN PROGRESS (SUBSEA GAS LEAKAGE)

IN POSITION 25-36.90N 054-25.50E

3. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND  
MAINTAIN AN EXCLUSION ZONE OF 500 METERS AROUND THE POSITION

4. CANCEL NAVAREA IX WARNING 301 OF 2022

-----  
SECURITE

041500 UTC AUG 2022

NAVAREA IX 295/22 IRAN SHATT AL ARAB

CHARTS BA 1235 AND 3842

2. 03 LIGHTBUOYS ESTABLISHED:

A. STARBOARD HAND NO.03 FL(2) 18SEC 5M 29-50.72N 048-45.58E

B. STARBOARD HAND NO.11 FL(2) 18SEC 5M 29-52.74N 048-40.94E

C. STARBOARD HAND NO.13 FL(2) 20SEC 5M 29-53.64N 048-39.98E

4. MARINERS CAUTIONED

-----  
SECURITE

041500 UTC AUG 2022

NAVAREA IX 294/22 IRAN

RESHADAT OIL FIELD CHARTS BA 2886, 2887 AND 2889

2.SADRA SADAF-132 ACCOMMODATION BARGE TEMPORARILY  
MOORED WITH ANCHORS AND MARKED BY BUOYS IN POSITION  
25-53.70N 052-54.80E  
4.WIDE BERTH REQUESTED

-----  
SECURITE

071500 UTC JUNE 2022

NAVAREA IX 220/22 PAKISTAN OFF CAPE MONZE

CHARTS PAK 33, 57 (INT 751), BA 38 AND 707

2. 50 METERS LONG DHOW BURHAN NOOR (IMO NO 616897000)

SUNK IN POSITION 24-53N, 066-00E ON 06 JUN 22.

3. MARINERS CAUTIONED

-----  
SECURITE

241500 UTC MAY 2022

NAVAREA IX 198/22 CENTRAL GULF BAHRAIN

CHARTS BA 2837, 2847, 2886, 3738 AND 3790

2. BAHRAIN LIGHT BUOY IN POSITION 26-33.00N, 051-03.59E

REPORTED UNLIT

3. MARINERS CAUTIONED

-----  
SECURITE

171550 UTC MAR 2022

NAVAREA IX 112/22 CENTRAL GULF QATAR

CHARTS BA 2837, 2883, 2886 AND 2887

2. VESSEL REPORTED CAPSIZED IN POSITION 26-52.1N, 052-19.4E  
WITHIN QATAR NORTH OIL AND GAS FIELD. THE SEARCH AND RESCUE  
STILL LOOKING FOR ONE OF THE CREW MEMBERS WITHIN THE AREA

3. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION WHILE  
TRANSITING IN THE AREA

-----  
SECURITE

111500 UTC MAR 2022

NAVAREA IX 102/22 PAKISTAN

PORT MUHAMMAD BIN QASIM CHARTS

PAK 5, 20 AND BA 59

2. AHSAN CHANNEL BEACON NO.3 IN POSITION

24-34.70N 067-04.08E REPORTED DAMAGE AND BROKEN

3. NEW BOUY NO-3 FL(3)G 7S LAYED IN POSITION

24 34.68N 067 04.07E

4. MARINERS CAUTIONED

5. CANCEL NAVAREA IX WARNING 340/21

-----  
SECURITE

071500 UTC MAR 2022

NAVAREA IX 095/22 PAKISTAN PORT  
MUHAMMAD BIN QASIM CHARTS PAK 5 (INT 7314),  
20 (INT 7316) AND BA 59  
2. KHUDDI LIGHT HOUSE (APPROACHES TO PORT  
QASIM CHANNEL) REPORTED UNLIT.  
3. MARINERS CAUTIONED

-----  
SECURITE

161100 UTC FEB 2022  
NAVAREA IX 067/22 EASTERN GULF  
DUBAI (PALM DEIRAH) CHARTS BA 2887, 2888,  
3175 AND 3176  
2. AN OBSTRUCTION REPORTED IN POSITION 25-20.90N  
055-08.62E  
3. MARINERS CAUTIONED

-----  
SECURITE

281500 UTC JAN 2022  
NAVAREA IX 039/22 EASTERN GULF  
DUBAI (PALM DEIRAH) CHARTS BA 2888, 2889, 3175 AND 3412  
2. SHALLOW PATCHES REPORTED IN AREA BOUNDED BY  
FOLLOWING COORDINATES:  
25-20.90N 055-12.90E  
25-23.00N 055-10.60E  
25-23.80N 055-12.10E  
25-22.50N 055-14.80E  
3. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION

-----  
SECURITE

170450 UTC JAN 2022  
NAVAREA IX 027/22 CENTRAL GULF  
BAHRAIN CHARTS BA 2847, 2886 AND 3790  
2. WRECK BUOY IN POSITION 26-35.94N, 050-58.51E  
REPORTED UNLIT  
3. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

-----  
SECURITE

141500 UTC DEC 2021  
NAVAREA IX 491/21 IRAN BANDAR-E PARS  
CHARTS BA 2837, 2858, 2883, 2886 AND 2887  
2. DEEPSEA TREASURE JACKUP DRILLING RIG ESTABLISHED  
IN POSITION 26-57.49N 052-26.85E  
4. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION  
AND GIVE WIDE BERTH

-----

SECURITE

141500 UTC DEC 2021

NAVAREA IX 490/21 IRAN KHALIJ-E CHABAHAR

CHARTS BA 2851, 2858 AND 4705

2. PREFERRED CHANNEL PILLAR LIGHT BUOY MOVED TO POSITION  
25-18.81N 060-35.58E WITH FOLLOWING CHARACTERISTICS:

FLASHING: (2+1)7 SECONDS

HEIGHT : 3 METERS

RANGE : 3 MILES

3. PORT HAND BUOY IN POSITION 25-18.22N 060-34.39E  
PERMANENTLY DISCONTINUED

4. MARINERS CAUTIONED

-----  
SECURITE

171500 UTC NOV 2021

NAVAREA IX 448/21 IRAN SOUTH PARS

GAS FIELD CHARTS BA 2523, 2837, 2886 AND 2887

2. FATEH 900 ACCOMMODATION BARGE TEMPORARILY  
MOORED IN POSITION 26-48.63N 052-20.16E WITH  
ANCHORS MARKED BY BUOYS

3. MARINERS CAUTIONED

-----  
SECURITE

151500 UTC NOV 2021

NAVAREA IX 445/21 CENTRAL GULF

(.) QATAR CHART BA 2886 AND 2887

2. CREW BOAT MOORING BUOY AT AL KHALIJ  
OILFIELD REPORTED MISSING IN POSITION 25-56.10N  
052-41.40E

3. MARINERS CAUTIONED

-----  
SECURITE

251500 UTC OCT 2021

NAVAREA IX 399/21 PAKISTAN KARACHI

CHARTS PAK 33, 57 (INT 751), 58 (INT 7019), BA 38  
AND 707

2. KARACHI RADIO (NAVTEX STATION) IN POSITION 24-52.78N  
067-09.94E INOPERATIVE ALL NAVIGATIONAL WARNINGS ARE  
BEING TRANSMITTED ON INTERNATIONAL SAFETYNET AND AVAILABLE  
ON WEBSITE [WWW.HYDROGRAPHY.PAKNAVY.GOV.PK/NAVAREA-IX-WARNINGS](http://WWW.HYDROGRAPHY.PAKNAVY.GOV.PK/NAVAREA-IX-WARNINGS)

3. MARINERS CAUTIONED.

4. CANCEL NAVAREA IX WARNING 301 OF 2021

-----  
SECURITE

251500 UTC OCT 2021

NAVAREA IX 397/21 ARABIAN SEA, GULF OF OMAN

AND PERSIAN GULF

2. US NGA HYDROPAC (NAVIGATIONAL WARNING)1478/20 (62,63)  
IS REPRODUCED AS RECEIVED FOR THE INFORMATION OF MARINERS  
AND SAFETY OF NAVIGATION

3. U.S. NAVAL FORCES ARE CONDUCTING ROUTINE OPERATIONS IN  
THE REGION WITH A COMMITMENT TO FREEDOM OF NAVIGATION AND  
THE FREE FLOW OF MARITIME COMMERCE. DUE TO RECENT EVENTS,  
IN ORDER TO ENHANCE SAFETY, MINIMIZE AMBIGUITY, AND REDUCE  
OPPORTUNITIES FOR MISCALCULATION, ALL VESSELS ARE ADVISED  
TO MAINTAIN A SAFE DISTANCE OF AT LEAST 100 METERS FROM U.S.  
NAVAL VESSELS IN INTERNATIONAL WATERS/STRAITS. ARMED VESSELS  
APPROACHING WITHIN 100 METERS OF A U.S. NAVAL VESSEL MAY BE  
INTERPRETED AS A THREAT AND SUBJECT TO LAWFUL DEFENSIVE MEASURES.  
MARINERS ARE REMINDED TO OPERATE IN ACCORDANCE WITH INTERNATIONAL  
LAW AND WITH DUE REGARD FOR THE SAFE NAVIGATION OF OTHER VESSELS.  
ALL VESSELS OPERATING IN THE VICINITY OF U.S. NAVAL VESSELS ARE  
ADVISED TO CLEARLY COMMUNICATE INTENTIONS, RESPOND TO QUERIES  
CONCERNING COURSE AND SPEED, EXERCISE PRINCIPLES OF PRUDENT  
SEAMANSHIP AS REQUIRED UNDER INTERNATIONAL LAW, AND REMAIN AT  
THE MAXIMUM AVAILABLE DISTANCE FROM U.S. NAVAL FORCE.

4. CANCEL NAVAREA IX WARNING 215 OF 2020

-----  
SECURITE

141500 UTC MAR 2021

NAVAREA IX 109/21 QATAR CENTRAL GULF

CHARTS BA 3772, 3950, 2886, 2837, 2847, AND 2858

2. BARGE WRECK BUOY MISSING AT POSITION

25-57.71N 051-52.86E

3. MARINERS ARE REQUESTED TO EXERCISE EXTREME CAUTION  
WHEN TRANSITING THIS AREA

4. CANCEL NAVAREA IX WARNING 096 OF 2019  
-----