

InspectionWale - Vehicle Inspection Report

Rebranded from Whizzcheck

Inspection ID: MH04KD2255-20251002-001
Date: 2025-10-02



Vehicle Registration Details

| | | | |
|---------------------|-------------------|-------------------|---------------|
| Registration Number | MH04KD2255 | Make / Model | Maruti Brezza |
| Chassis Number | MA3NYF81SKD535417 | Engine Number | D13A-5818272 |
| Manufacture Date | 2019-04-01 | Registration Date | 2019-09-19 |
| Fuel Type | Diesel | Owners | 2 |

Key Highlights

Accidental: Yes
Flood Damage: No
Fire Damage: No
Top Comments: Car has impact on front and rear both

Exterior / Body

| | | |
|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Bonnet | Good (Paint depth: 345) | |
| Front Bumper | Repainted | |
| Windshield | Replaced | |
|  |  |  |

Interior

| | |
|--------------|------|
| Dashboard | Good |
| AC Vents | Yes |
| Music System | Yes |

Engine

| | |
|-----------------------|------|
| Battery | Good |
| Oil Leak | No |
| Estimated Repair Cost | 0 |

Tires & Wheels

| | |
|-----------|---------------------|
| Front LHS | 90-100 - Yokohama |
| Front RHS | 70-80 - Bridgestone |
| Spare | - |

Structure & Test Drive

Structure: Minor repairs on front members
Test Drive Notes: Brakes OK; steering slightly stiff

Documents & Images

| | | |
|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
|  Chassis plate |  RC Image |  CNG plate |
|-------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|

Disclaimer: InspectionWale offers visual inspection reports. Mechanical condition beyond visual inspection is not guaranteed. Refer to the original report.
Report generated by InspectionWale