

InspectionWale - Vehicle Inspection Report

Rebranded from Whizzcheck

Inspection ID:
INS-1769137225164
Date: 11 Oct 2024

Vehicle Registration Details

Registration Number	MH04KD2255	Year of Manufacture	2020
Make / Model	Toyota Fortuner	Registration Date	2020-03-15
Variant	2.8 4x2 AT	Color	Pearl White
Chassis Number	MABKT26GXJM012345	Fuel Type	Diesel
Engine Number	1GDKC23Z8JM567890	Odometer Reading	45000 km

Current Owner Details

Owner Name	Amit Sharma
Contact Number	9876543210
Email Address	amit.sharma@example.com
Inspection Location	Mumbai, Maharashtra


Vehicle Documents

PHOTO	PHOTO	PHOTO
RC Book	Chassis Plate	Odometer Reading


Exterior / Body

No visible dents or scratches, Paint in excellent condition, All panels aligned properly, Headlights and taillights working, Windshield crack-free

The exterior is well-maintained with original paint. Minor scratches on rear bumper are purely cosmetic and do not affect structural integrity.



Front Bumper



Bonnet



Front Grille




Headlights




Windshield




Wipers



Driver Front Door




Passenger Front Door



Driver Rear Door



Passenger Rear Door




Left Mirror




Right Mirror



Rear Bumper



Boot Closed




Boot Open



Taillights



Rear Windshield




Roof


Interior

Dashboard in good condition, All controls functioning, Seats clean with minor wear, AC working perfectly, Music system operational


Interior shows normal wear consistent with 45,000 km usage. All electronic components including music system, AC, and power windows are functioning properly.




Dashboard




Instrument Cluster




Steering Wheel




Front Seats




Rear Seats




AC Control Panel



Music System



Gear Lever



Interior Roof

Engine & Mechanical

Engine starts smoothly, No oil leaks detected, Battery in good condition, Cooling system normal, All fluids at proper levels

Engine bay is clean with no signs of major repairs. Oil levels are optimal and no leaks detected. Battery shows good charge retention.

PHOTO	PHOTO	PHOTO
Engine Bay	Engine Block	Battery
PHOTO	PHOTO	PHOTO
Radiator	Oil Cap	Belts & Hoses

Tires & Wheels

Good tread depth, No sidewall damage, Proper inflation, Wheels undamaged, Spare tire available

All four tires have adequate tread depth (6mm+). Spare tire is in unused condition. Wheel alignment is proper.

PHOTO	PHOTO	PHOTO
Front Left Tire	Front Right Tire	Rear Left Tire
PHOTO	PHOTO	
Rear Right Tire	Spare Tire	

Structure & Undercarriage

No rust on chassis, Undercarriage intact, Suspension working properly, No frame damage, Exhaust system good

Undercarriage inspection reveals no structural damage or rust. Suspension components are in good working order with no unusual sounds.

PHOTO

Front Undercarriage

PHOTO

Rear Undercarriage

PHOTO

Exhaust System

PHOTO

Front Suspension

PHOTO

Rear Suspension

Test Drive

Test Drive Conducted: Yes

Vehicle drives smoothly without any issues. Gear shifts are smooth, brakes respond well, and steering is precise. No unusual noises or vibrations detected during the test drive.

Issues Found & Recommendations

Major Issues Found:

Minor wear on brake pads, recommend replacement within 5000 km. Slight scratches on rear bumper (cosmetic only).

Recommendations:

Overall vehicle in excellent condition. Regular maintenance up to date. All major components functioning properly. Recommended for purchase with routine brake pad replacement in near future.

Overall Condition: Excellent

Disclaimer: InspectionWale offers visual inspection reports. Mechanical condition beyond visual inspection is not guaranteed.

Disclaimer: InspectionWale offers visual inspection reports. Mechanical condition beyond visual inspection is not guaranteed.

Disclaimer: InspectionWale offers visual inspection reports. Mechanical condition beyond visual inspection is not guaranteed.

Disclaimer: InspectionWale offers visual inspection reports. Mechanical condition beyond visual inspection is not guaranteed.

Disclaimer: InspectionWale offers visual inspection reports. Mechanical condition beyond visual inspection is not guaranteed.

