



## KSZ8895MQ Rev.A3 Errata Sheet

The following errata are exhibited in the Rev. A3 of the KSZ8895 products family.  
From Rev.A3, KSZ8995 family goes to production.

Item	Symptom	Solution/Workaround
1	In I2C mode, EEPROM contents can not be downloaded to registers after reset	Workaround: Works fine if write chip ID=0 in EEPROM.