

INVOICE

TO : MOHAMMED HASSIM ASHRAF BIN MOHAMMED AZIZ
C/O: SPRINT MOTOR PTE LTD
18 SOON LEE STREET
#01-91 PIOINEER PLAZA
SINGAPORE 672518

Invoice No.: 0920/SM658
Date: 20-Oct-2020

PARTICULARS

Vehicle Registration No.: FBE 2074 J
Date of Loss: 23-Jul-2020
Date of Assessment: 17-Sep-2020

SERVICES

FEES

1. Assessment with report Photographs - Including films, developing, storage and Transport.	\$450.00
--	----------

TOTAL	\$450.00
--------------	-----------------

SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"ULTRA AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

ULTRA AUTO CONSULTANTS LLP

ULTRA AUTO CONSULTANTS LLP

23 Chin Swee Road #09-33 Tong Chew Building Singapore 163621
Telephone +65 97237452 Facsimile +65 68231557 Email dion@ultraac.com
Reg. No. LL0406438L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO : MOHAMMED HASSIM ASHRAF BIN MOHAMMED AZIZ
C/O: SPRINT MOTOR PTE LTD
18 SOON LEE STREET
#01-91 PIONEER PLAZA
SINGAPORE 672518

Our Reference: 0920/SM658
Date: 20-Oct-2020

ASSESSMENT OF VEHICLE NO. FBE 2074 J

DATE OF LOSS: 23-Jul-2020

We have carried out a physical assessment at SPRINT MOTOR PTE LTD,
18 Soon Lee Street #01-91 Pioneer Plaza Singapore 672518, according to your instruction
on 17-Sep-2020 and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: FBE 2074 J
Make & Model: SUZUKI GSX1300RLO
Year of Registration: 2010
Engine Capacity: 1340
Chassis No.: JS1CK111100107839
Engine No.: X704131452
Colour: BLUE

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
Make/Size/Thread: PIRELLI 120/70 R17 – 75%


Rear
Make/Size/Thread: PIRELLI 180/55 R17 – 75%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the LH & RH portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$10,268.70
Adjusted Amount:	\$7,736.70
Lump Sum:	\$5,500.00
Estimated Repair Days:	7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Ultra Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. FBE 2074 J

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT WINDSHIELD	Repair	280.00	-
1	HEADLAMP COWLING	Cracked	760.00	760.00
1	HEADLAMP	Repair	460.00	-
1	SIDE MIRROR L/R -SET	Cracked	220.00	220.00
2	HEADLAMP COWLING INNER GARNISH L/R	Cracked	120.00	120.00
1	HANDLE BAR LH	Repair	180.00	-
1	HANDLE BAR BALANCER L/R	Cut	120.00	120.00
1	HANDLE CLUTCH LEVER	Bent	80.00	80.00
1	FRONT SIGNAL L/R	Repair	180.00	-
1	FRONT FENDER	Cut	370.00	370.00
1	FRONT FORK ASSY	Repair	1,280.00	-
2	SIDE FAIRING COWLING L/R	Cracked	980.00	980.00
1	ENGINE CRANK CASE STATOR COVER LH	Cracked	388.00	388.00
1	FRONT RH FOOTREST	Bent	95.00	95.00
1	FUEL TANK COWLING FAIRING	Cracked	650.00	650.00
1	REAR SEAT COWLING FAIRING	Cracked	600.00	600.00
2	REAR FOOTREST L/R	Bent	180.00	180.00
2	REAR EXHAUST PIPE L/R ASSY	Bent	1,200.00	1,200.00
			8,143.00	5,763.00
Less 10% discount			814.30	576.30
Parts Total:			7,328.70	5,186.70

ASSESSMENT REPORT FOR VEHICLE NO. FBE 2074 J

SPECIAL NETT ITEMS

1	SIDE FAIRING COWLING L/R STICKER - SET	Necessary	240.00	240.00
1	ENGINE OIL	Necessary	160.00	160.00
1	FRAME SLIDER CRASH PROTECTOR L/R - SET	Cut	220.00	220.00
Special Nett Total :			620.00	620.00

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	Fork alignment.	120.00	100.00
2	Check wiring system and light.	100.00	80.00
3	To check, align and balance body main frame.	300.00	250.00
4	Spray painting.	800.00	700.00
5	Labour for repair and replace parts .	1,000.00	800.00
Labour Total :		2,320.00	1,930.00
TOTAL (PARTS & LABOUR) \$		10,268.70	7,736.70

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$5,500.00 (SINGAPORE DOLLARS FIVE THOUSAND FIVE HUNDRED ONLY)

Dion Ong
 Automobile Assessor

**18 SOON LEE STREET
#01-91 PIONEER PLAZA
SINGAPORE 672518
TEL : 62774184 FAX : 65400071
EMAIL: sprintmotor888@sprintmotor.com.sg**

Our Reference:	WAVE/FBQ6931K
Date:	20-Oct-2020
Vehicle Num:	FBE 2074 J
Make/Model:	SUZUKI GSX1300RLO
Chassis No.:	JS1CK111100107839
Engine No.:	X704131452
Accident Date:	23-Jul-2020

[illegible]

SPRINT MOTOR PTE LTD