

2006-025

before



outlet



after

before



inlet, river left



after



river right approach (post-restoration)



2006-026 (Honeymoon Brook tributary)



looking upstream from road



2006-041

river right approach (pre-restoration)



river right approach (post-restoration)



river left approach (pre-restoration)



river left approach (post-restoration)



outlet (pre-restoration)



outlet (post-restoration)





inlet, post-restoration (from
river right)



looking downstream from road,
post-restoration

2007-177

Outlet, pre-restoration (post-restoration pictures will be taken this spring)



arch culvert being assembled



2006-304



View of inlet and associated meadow pre- and post- restoration.



looking upstream pre- and post- restoration



View of outlet, pre- and post- restoration



2007-537 (Beaver Meadow)



river left approach (post-restoration)

looking downstream (post-restoration of crossing)



looking upstream (post restoration)



Looking at inlet from old hatchery water control pool



2007-302 (Beldon Brook)



inlet and outlet, post-restoration





Hayes Brook

outlet, pre- and post-restoration



river left approach,
post-restoration



looking upstream, pre- and post- restoration (not submerged rock in upper photo for reference)



Bear Brook

river right approach pre-restoration



river right approach post-restoration



Bear Brook continued: sequence of draining upstream deadwater





Bear Brook inlet, pre- and post- restoration



Bear Brook outlet, pre- and post- restoration

