



Notes:

1. R1 must be preinned before installation for reliable connections.
2. HN connector connects to R1 via miniature cup soldered onto end of R1 via miniature copper strip.
3. MVV connector connects to HV PCB via pin which goes through preamp PCB.

Title			Schematic 1: HE3 Detector Preamp HV PCB Ver 3		
Size	A	Document Number	Rev	1.0	
Date:	Monday, October 06, 2014		Sheet	1	of 1