

## I. summary

CNC stepper motor driver board 96560A V1 adopts the new chip TB6560AHQ of TOSHIBA, the max output current can reach to 3.5A , this driver board can drive the 2-phase or 4-phase stepper motor whose current is less than 3A.

The advantages of the TB6560AHQ chip :

( 1 ) The vibration of the motor is small and low noise: because of the 2/8/16 resolution can satisfy the different speed.

( 2 ) flush type low heat : The area of the chip can support itself to cool when the current is low

( 3 ) supports a lot of stepper motors

( 4 ) the advantages in the high-speed running condition

## Features


- 1、 4-wire 0-3.5A ( normally 3A , the 3.5A is the peak current ) can be regulated rate current output, bipolar stepper motor driver
- 2、 Standard parallel port , supports Mach 2, KCAM 4 etc.
- 3、 Optical isolated (IO) and DCDC power isolated to protect the PC parallel port and other equipments
- 4、 Limit and emergency stop port ( standard DB9 port)
- 5、 4 working modes: mixed mode , fast mode, slow mode, standard mode
- 6、 4-resolution : 1 1/2 1/4 1/16
- 7、 12-36V single power input uses the switch power chip as the 5V power supply, stable and low heat
- 8、 Adopts RC + 7414 auto semi-flow
- 9、 The relay output can control the main axis
- 10、 5<sup>th</sup> axis extension control port

## Definition of the Pin

### 1、 The 25 Pin of the parallel control

DB25 Pin	Function of the Pin	
1	All axis EN( enable)	
2	STEPX	
3	DIRX	
4	STEPY	
5	DIRY	
6	STEPZ	
7	DIRZ	
8	STEPA	
9	DIRA	
10	LIMIT-1	
11	LIMIT-2	
12	LIMIT-3	
13	LIMIT-4	
14	Relay control	
15	Suspended	
16	STEPB-	Connect the extension port DB 9 Pin 8
17	DIRB-	Connect the extension port DB 9 Pin 7
18-25	GND	

- Please connect the switch power supply larger than 12-24V 4A as the wiring diagram , the + and – of the power are showed on the driver board
- Limit port definition : LPT10= P10 of the PC parallel port , LPT11=P11  
LPT12=P12 LPT13= P13 , LPT XX and the COM port connect the power switch. The power signal can be collected by the MACH 3.
- The 5<sup>th</sup> extension control port definition: from the top to buttom GND EN  
GND CW GND CK, they control the EN, pulse- , pluse+, direction- and direction+ of the 5<sup>th</sup> axis stepper motor




LED LIGHT


XYZA ATTENUATION AND RESOLUTION SETUP

## Wiring diagram of the stepper motors


### 4-wire motor



### 6-wire motor



8-wire motor



**attenuation mode choice (D1D2----control the motor attenuation time)**

DIP switch D1 and D2 , D2/D1 : **ON/ON——100% ;    ON/OF——25% ;**

**OF/ON——50% ;    OF/OF——0% ;**

D1	D2	Working mode
ON	ON	100%
OF	ON	50%
ON	OF	25%
OFF	OFF	0%

#### 4. Current Decay Settings

Output is generated by four PWM blasts; 25% decay is created by inducing decay during the last blast in Fast mode; 50% decay is created by inducing decay during the last two blasts in Fast mode; and 100% decay is created by inducing all four blasts in Fast mode.

If there is no input with the pull-down resistor connection then the setting is Normal.

Dcy2	Dcy1	Current Decay Setting
L	L	Normal 0%
L	H	25% Decay
H	L	50% Decay
H	H	100% Decay

## Resolution setup


DIP switch M2 and M1 , S4/S3 :      **OFF/OFF——1** ;                      **ON/OFF—— 1/2** ;

**ON/ON——1/8 ;                      OFF/ON——1/8 ;**

DIP M2	DIP M1	Resolution mode
OFF	ON	1/16
OFF	OFF	1/8
ON	OFF	1/2
OFF	OFF	1

## Current setup

T2/T1 :	OFF/OFF	100%*2.5A,	OFF/ON	75%*2.5A
	ON/OFF	50%*2.5A,	ON/ON	25%*2.5A



## Attentions:

### 1 ---the choice of the voltage of the power supply

Generally speaking, the higher the voltage, the larger the torque of the high-speed running motor, it can avoid the loss of step when running in high-speed, but the high voltage may do some damages to the driver, and in the condition of high voltage, the low speed running motor will vibrate a lot

### 2 ----the setup data of the output current

To the same motor, the current is larger, the output torque of the motor is larger, but the large current will cause the over-heat. so we have to set up the current in a perfect condition


(1) 4-wire and 6-wire high speed running motor : the output current should be the same or lower than the rate current

(2) 6-wire motor large toque mode: the output current should set up as the

70% of the rate current

(3)8-wire motor serial connecting mode: the output current should set up as the 70% of the rate current

(4)8-wire motor parallel connecting mode: the output current should set up as the 1.4X the rate current



After running 15-30 mins when the setup of the motor current is done, if the motor is over-heat , you should reduce the current, if the reduce of the current causes the lack of the output of the torque , please add the fan or improve the cooling condition to protect the motor and the driver.



# How to use the MACH3 software.




FIG 1

Fig1: open the mach3 software , choose the mach3 MILL ---choose ok.




FIG 2

Fig2: we deploy the mach3 software.




FIG 3

Fig3: open the port and pin menu under the config menu.




FIG 4

Fig4:set the standard frequency in the first circle , this data influence the speed of the motor , and then choose the definition in the second circle to set up the pin.






FIG 5

Fig5 : follow the circle in the figure to set the software.




FIG 6

Fig6:choose the output signals , follow the circle in the figure to set .




FIG 7

Fig7: choose ok and the open the G code that we need to run.




FIG 8






FIG 9

Fig8:after opening the G code , you will see the red reset , click it and then run the cyclestart.

If need the manuel control , you can use the TAB to control it .

For the 3 axis driver

## Definition of the Pin

1、 The 25 Pin of the parallel control

## DB25 Pin Function of the Pin

1All axis EN( enable)

2STEPX

3DIRX

4STEPY

5DIRY

6STEPZ

7DIRZ

8STEPA

9DIRA

10LIMIT-1

11LIMIT-2

12LIMIT-3

13LIMIT-4

14Relay control

15Suspended

18-25GND