

सम्मिश्र जांच दल/ Composite Trials Team
द्वारा नेवी कार्यालय/ c/o Navy Office
मुख्यालय/ Headquarter
अन्डमान एवं निकोबार कमान/
Andaman & Nicobar Command
पोर्ट ब्लेयर/ Port Blair - 744 102


CTT/300/11/02/TECH

29 Sep 22

The Commodore Superintendent
{for SM(L)}
Naval Ship Repair Yard
c/o Navy Office
Port Blair – 744 102

CAUSATIVE ANALYSIS TOWARDS DEECT ON MCS-5 PANEL - INS CHETLAT

1. Refer to HQANC letter ANC/42002/EG17/1 dated 23 Sep 22.
2. The Unit has been directed to undertake causative analysis of defect on MCS 5 battery charger on board INS Chetlat vide HQANC letter ibid. It is understood that initial DI/DR has been undertaken by a local firm based at Port Blair. Towards further analysis, following details are required :-
 - (a) The preliminary investigation carried out by firm on board and the subsequent rectification carried out on the rectifier.
 - (b) Authorisation from OEM to firms towards carrying out DI/DR (if any).
3. It is requested that the details sought may be forwarded to this Unit at an early date for progress in conduct of causative analysis.


(जगन्नाथ गुरुमूर्ति /Jagannath Gurumurthy)
लेफ्टिनेंट कमांडर / Lieutenant Commander
उप-प्रभारी अधिकारी/ Dy. Officer-in-Charge
क्रिते प्रभारी अधिकारी/ for Officer-in-Charge

Copy to:-

The Commander-in-Chief
{for SSO(ME) II}
Headquarters
Andaman & Nicobar Command
Port Blair - 744 102