

दूरभाष /Tele : 248306

सम्मिश्रजांच दल/Composite Trials Team
द्वारा नेवी कार्यालय/ C/o Navy Office
मुख्यालय/ Headquarter
अन्धमान एवं निकोबार कमान/
Andaman & Nicobar Command
पोर्टब्लेयर/ Port Blair - 744 102

CTT/300/03/13/Tech

23 Mar 23

The Commander-in-chief
{for CTO (ML)}
Headquarters
Andaman and Nicobar Command
Port Blair – 744102

HIGH SPM OF DIESEL ALTERNATOR

1. Refer to this unit letter of even no dated 24 Feb 23
2. A study of SPM log books of LCU MK IV class ships was undertaken and it was observed that most DAs are being exploited with high SPM readings. Extract of SPM log book pertaining to IN LCU 55, 56, 57 & 58 are placed at enclosure.
3. In view of above following requested.
 - (a) HQNAVC/SO(L) be directed towards undertaking analysis of similar condition existing on balance ships.
 - (b) Weekly trending of SPM values.
 - (c) Take up with OEM towards resolution of above defect at an early date.



23/03

(एस सी विलियम/ S C William)
कमांडर/ Commander
प्रभारी अधिकारी/ Officer-in-Charge

Encl. As above

Copy to.

The Commodore Superintendent
{for DGM(PR & PP)}
Naval Ship Repair Yard
c/o Navy Office
Port Blair – 744 102

The Naval Component Commander
{for SSO(Tech)}
c/o Navy Office
Andaman & Nicobar Command
Port Blair – 744 102