

ISE Voltage

50
40
30
20
10
0

Resin depleted

Regeneration

Calcium sensor reading drifts over the course of several hours.

Anomolous spike
caused by low flow

9-7

9-8

9-9

9-10

9-11

9-12

9-13

9-14

Time

