

INSPECTION REPORT


Excavator

Client Name :	DURGA SCREENING PLANT	Ref. : QV/2024-25/2408202440033/1
Enterprise Name :	KOGTA FINANCIAL (INDIA) LIMITED	Date : 26-08-2024
GPS No :	NA	



SUMMARY			
Asset No	NA	Serial No.	2001-50532
Request No.	EV240820240033	Chassis No.	2001-50532
Make	Tata Hitachi	Regn No.	NA
Model	EX 200 LCI	Engine No.	NA
Year of Mfg	2012	Site Address	PANCHKULA, HARYANA
HMR	0	Inspector	Sahil Yadav
KMR		Distance	50 KM



Invoice available



ASSY/SUB ASSY CONDITION DEAILS

CATEGORY	DESCRIPTION	A	B	C	D	REMARKS
 GENERAL APPEARANCE	Diagonal View - Front			✓		Looks average
	Diagonal View - Rear			✓		Looks average
	Paint Condition			✓		Average condition
	Visual Cracks & Welds					No cracks and welds
	Rust Condition					No rust found
	Step Ladders		✓			All fitted
	Hand Rails			✓		
	Fenders/Brackets			✓		All intact
	Guards			✓		All fitted
	Hoods					N/A
 CABIN/ CANOPY	Cab Structure			✓		Average in shape
	Mirrors & Glasses			✓		All installed
	Operator Seats			✓		Available
	Dashboard			✓		Average condition
	Control Leavers			✓		All intact

CATEGORY	DESCRIPTION	A	B	C	D	REMARKS
 ENGINE	Working / Smoke condition		✓			Normal
	Oil Leaks					No leakage
	Fuel Leaks					No leakage
	Radiator Leaks					No leakage
	Blow Bye					Unable to check
	Turbocharger			✓		Properly working
	Fan & Belt			✓		Properly working
	FIP & Injectors			✓		Properly working
 ELECTRICAL	Lights - Front & Rear			✓		All fitted
	Horn / Alarm		✓			Available
	Alternator			✓		Properly working
	Self Starter			✓		Properly working
	ECM / Solenoids			✓		Fitted
	battery Condition			✓		Available
 HYDRAULICS	Pump			✓		Properly working
	Control Valve			✓		Properly working
	Oil Tank			✓		Average in shape
	Cylinders			✓		All working
	Hoses Condition			✓		All intact
	Oil Leaks					No leakage
	Swing motor & Device			✓		Properly working
	Travel motor & Device			✓		Both working
	Centre Joint					

CATEGORY	DESCRIPTION	A	B	C	D	REMARKS
 CHASSIS & FRAME	Cracks & Welds					No cracks and welds
	Boom Cylinder			✓		Properly working
	Arm Cylinder			✓		Properly working
	Bucket Cylinder			✓		Properly working
	Boom			✓		Average condition
	Arm / Stick			✓		Average condition
 UNDER CARRIAGE	Track Shoes			✓		Approx., 40 % wear and tear
	Bushes & Pins			✓		Approx., 40 % wear and tear
	Track Adjuster			✓		Average condition
	Sprocket			✓		Approx., 40 % wear and tear
	Idler			✓		Approx., 40 % wear and tear
	Roller (upper & lower)			✓		Approx., 40 % wear and tear
	Slew Ring			✓		Average condition
 ATTACHMENT & ACCESSORIES	Excavation Bucket			✓		Average condition
	Bucket Teeth			✓		Approx., 40 % wear and tear
	Rock Breaker					Not applicable
	Pins & Bushes			✓		Approx., 40 % wear and tear

OVERALL GENERAL CONDITION

Tata Hitachi make EX 200 LCI hydraulic excavator is powered by 6-cylinder TC diesel engine is in average condition. All system major components and accessories of engine, hydraulic, swing & travel is available in average working condition. Cabin interior & exterior is average with all controls & gauges. All accessories of undercarriage approx. 40 % wear and tear noticed. In overall view this 20-toner excavator is average working condition. The estimated remaining residual life of this asset will be 4-5 years with proper maintenance.

MARKET VALUE (MV) is the estimated amount for which an asset should exchange on the date of valuation between a willing buyer and a willing seller in an arm's length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. The above info is based on date of inspection and SMU provided by customer which is on

ASSESSED MARKET VALUE : RS. 2,105,000




IQIPPO Services Ltd Ground Floor, IPCL Building, Plot No. X-1, 2 & 3; Block-EP, Salt Lake City, Kolkata - 700091, West Bengal, India

Corporate Membership Registration No: LCM-5646
For Plant Machinery & Vehicles Under The Indian Institution of Valuers, Pune.

PHOTO GALLERY



24-08-2024 09:06:47 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:48 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:48 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:46 Latitude : 28.6059012 Longitude : 76.987736




24-08-2024 09:06:45 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:46 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:45 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:48 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:26 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:25 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:46 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:17 Latitude : 28.6059012 Longitude : 76.987736



24-08-2024 09:06:17 Latitude : 28.6059012 Longitude : 76.987736