

DGM Aircraft / Justice Air
Maintenance

9100 Republic Airport
Farmingdale, NY 11735 US
+1 6312704144
diana@justiceair.com



INVOICE

BILL TO
Avi
Aspire Aviation
1100 New Highway
Farmingdale, NY 11735

INVOICE 1983
DATE 04/10/2024
TERMS Net 10
DUE DATE 04/20/2024

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Labor Rate	N433SP - Ammeter showing high amp discharge. Voltmeter reading only 23V with running engine.. Followed AMM Alternator troubleshooting flow chart 24-20-00, discovered shorted alternator cable and destroyed alternator B terminal. New alternator was ordered.Removed and replaced alternator IAW AMM 24-20-00. Replaced alternator power wire ring terminal, replaced alternator capacitor wire and ring terminal. Ops checked OK. Battery Voltage 28V while engine running, low volts annunciation no longer illuminated, ammeter discharge rate now normal. (6.0 hr)	6	95.00	570.00
Aircraft Part	Alternator	1	614.96	614.96
Aircraft Part	Alternator core (Fee will be returned upon core acceptance)	1	200.00	200.00
Aircraft Part	Silicone nipple	1	1.61	1.61
Aircraft Part	Miscellaneous hardware	1	5.50	5.50
Shipping and Freight Charges	Core return for alternator	1	32.90	32.90

WO# 710

BALANCE DUE

\$1,424.97