

Barishal  
20/2/20

**INTERNATIONAL TRACTORS LIMITED**  
**VILL.CHAK GUJRAN P.O. PIPLANWALA. JALANDHAR ROAD , HOSHIARPUR -146001**

**IMPLEMENTS WARRANTY CLAIM FORM**

<b>DISTRIBUTOR NAME:</b> ACI MOTORS	<b>DISTRIBUTOR CODE:</b> 2000036
<b>DISTRIBUTOR ADDRESS:</b> DHAKA BANGLADESH	<b>CUSTOMER'S NAME AND ADDRESS:</b> Md.Jamal Chowkider ,Golachipa, Patuakhali.

<b>Distributor REF .No.:- 01</b>	<b>Warranty Claim No:- SR/23/03/004</b>	<b>DATE :- 09-02-2023</b>
----------------------------------	---	---------------------------


<b>PRODUCT DETAIL:</b> Sonalika Smart Rotavator	<b>DATE:-</b>	<b>Engine load problem</b>
<b>MODEL DETAILS:</b> S. Series	<b>DATE OF SALE:</b> 31-10-2022	
<b>PRODUCT SERIAL NO :</b> HU309003	<b>DATE OF FAILURE:</b> 07-02-2023	
<b>PRODUCT MANUFACTURING YEAR:</b> 2022-23	<b>DATE OF REPAIR:</b> 08-02-2023	
<b>ATTACHED TRACTOR NAME/ HP :</b> DI-50RX	<b>SOIL TYPE:</b> Muddy land.	
<b>HOURS WORKED :</b> 480	<b>ITL INVOICE NO &amp; DATE:</b>	

<b>Distributor Analysis:</b> The rotavator 16/20 pinion plowing Inad is causing engine load problem. As a result of planting 17/19 pinion in the later now there in no load problem and cultivation is going well .	<b>Distributor Action Taken:</b> Replaced the failure parts under warranty.
--	---

Sr No	ITL Part No	Parts Description	Quantity	Remarks
1	[M02108111]	GEAR Z-19	1	
2	[M02108113]	GEAR Z-17	1	
3				
4				
5				

Note- The Claim must be submitted with In 30 days from date of Repair.  
Claim will not be considered if required documents (Warranty claim, 3-4 failed parts photograph, Customer Installation certificate, sublet bill if any).  
Attach photo of Sr. No Plate.

<b>DISTRIBUTOR'S SIGN &amp; STAMP</b>	<b>ITL SERVICE MANAGER SIGNAURE &amp; REMARKS</b>
---------------------------------------	---

<b>ITL REF NO. &amp; DATE OF APPROVAL:</b>	<b>ITL REMARKS IF ANY :</b> 
--	---