



Multi-Point Vehicle Inspection

Thursday, June 15, 2023

AutoFax Rating



<https://form.jotform.com/231650670946056>



Inspection Date

Thursday, June 15, 2023

Customer Name

Shirjeel Arshad

Make

Land Rover

Model

Range Rover Velar

Year

2022

Kilometers

15000

Engine Capacity

3000 CC

Fuel Type

Gasoline

Registration City

HCMC

VIN

SALYM2RV6JA718920

Transmission

Automatic



Engine Oil

| | GOOD | FAIR | POOR | % |
|---------------------------|------|------|------|-----|
| Remaining Engine Oil Life | ✓ | | | 85% |

Body/Exterior Lights

| | WORKING | NOT WORKING | REPLACEMENT REQUIRED | OTHER/PAINT % |
|---------------|---------|-------------|----------------------|---------------|
| Headlamps | ✓ | | | |
| Tail Lamps | ✓ | | | |
| R Turn Signal | ✓ | | | |
| L Turn Signal | ✓ | | | |
| Front End | ✓ | | | |
| Rear End | ✓ | | | |
| Drive Left | ✓ | | | |

| | WORKING | NOT WORKING | REPLACEMENT REQUIRED | OTHER/PAINT % |
|-----------------|---------|-------------|-------------------------|---------------|
| Passenger Right | ✓ | | | |

| | GOOD | FAIR | OTHER |
|---------------------|------|------|-------|
| Condition | ✓ | | |
| Cable & Connections | ✓ | | |
| Voltage | ✓ | | 12V |

Take Photo



| | |
|----------------------------|---------|
| Battery Warning Light | WORKING |
| Oil Pressure Warning Light | WORKING |
| Airbag Warning Light | WORKING |
| ABS Warning Light | WORKING |
| Temperature Warning Light | WORKING |
| Instrument Cluster | WORKING |
| ODB Port | WORKING |

Thread/ Rim Condition

| | |
|-------------|-----------------|
| Left Front | 7/32 to 4/32 |
| Right Front | 7/32 to 4/32 |
| Left Rear | 8/32 or Greater |
| Right Rear | 8/32 or Greater |

Are all 4 tires of the same brand ?

Yes

Services

| | |
|------------------|-----|
| Rotation Needed | Yes |
| Alignment Needed | No |
| Balance Needed | Yes |

FRONT - Check / Measure Front & Rear Brake Lining

| | 7 mm or Greater | 6 mm to 4 mm | 3 mm or Less | Lowest Lining |
|---------------------|-----------------|--------------|--------------|---------------|
| Left Front / VI mm | ✓ | | | |
| Right Front / VI mm | | | | |

REAR - Check / Measure Front & Rear Brake Lining

| | 4 mm or Greater | 3 mm | 2 mm or Less | Lowest Lining |
|--------------------|-----------------|------|--------------|---------------|
| Left Rear / VI mm | ✓ | | | |
| Right Rear / VI mm | ✓ | | | |

Brake System

| | |
|-------|------|
| Lines | GOOD |
| Hoses | GOOD |

| | |
|----------------------|------|
| Parking Brake | GOOD |
| Friendliness | FAIR |

| | |
|-----------------------------|------|
| Left Front | GOOD |
| Right Front | GOOD |
| Rear (if applicable) | GOOD |
| Windshield Condition | GOOD |
| Cracks | GOOD |
| Chips | GOOD |
| Sunroof Glass | GOOD |

Levels

| | |
|--|------|
| Engine Oil | GOOD |
| Brake Fluid Reservoir | GOOD |
| Transmission (if equipped w/dipstick) | GOOD |
| Coolant Recovery Reservoir | GOOD |
| Power Steering | GOOD |
| Windshield Washer | GOOD |


Inspect for Visible Leaks and Visual Condition

| | |
|---|------|
| Fuel System (includes gas cap seating) | GOOD |
| Engine, Transmission, Drive Axle, Transfer Cases | GOOD |
| Engine Cooling System | GOOD |
| shocks and Struts (also check operation) | GOOD |
| Belts: Engine, Accessory, Serpentine, and / or V-drive | GOOD |
| Hoses: Engine, Power Steering and HVAC | GOOD |
| Engine Air Filter | GOOD |
| Cabin Air Filter | |
| Passenger Compartment Air Filter | GOOD |
| Steering cComponents and Steering Linkage | GOOD |
| CV Drive Axle Boots or Driveshafts and U-joints | GOOD |
| Exhaust System Components | GOOD |
| Body Components Lubrication | GOOD |

| | |
|---|------|
| Restraint System Component Check | GOOD |
| Chassis Components Lubrication | GOOD |
| Drive Axle (Leak / Other) | GOOD |

Interior

| | |
|-----------------------------------|---------|
| Steering Wheel Condion | WORKING |
| Dashboard | WORKING |
| Driver Seat | WORKING |
| Passanger Seat | WORKING |
| Rear Seats | WORKING |
| Infotainment System | WORKING |
| Air Conditioning | WORKING |
| Front Seat Belts | WORKING |
| Rear Seat Belts | WORKING |
| Sunroof | WORKING |
| Front Row-Driver Window | WORKING |
| Front Row Passanger Window | WORKING |
| Rear Row Driver Window | WORKING |
| Rear Row Passanger Window | WORKING |




Comments

A2 -REAR DRIVER DOOR
U2-REAR DRIVER QUARTER

LEGEND

P:Paint marked
A2:Scratch
A3:Big Scratch
U1:Small Dent
A1:Small Scratch
B1:Small dent with scratch (size like a thumb)
U2:Dent
U3:Big Dent
:Minor Scratches/Dents

Front



Driver Side



Passanger Side



Rear



Left Corner



Right Corner



Interior








Engine



Odometer




Chassis Plate



Comments

Overall vehicle in good condition, damage to rear wrap as shown in photos below

Additional Photos



Disclaimer: In case of any query or concern regarding inspection please call +84 9 3899 0140
This report is based on the condition of the vehicle on the date of certification and provides an approximate estimate of the condition on that date. Except where indicated, the parts were in working condition - this report does not take into account the condition of parts not visible or not inspected. AutoCoin.sg has relied on the odometer reading for kms driven as seen at the time of inspection and is not responsible for verifying its genuineness. The report is in no way a commitment on the condition of the car. All reports are subjective and AutoCoin.sg and its associates cannot be held liable in any way due to the use of this report.
Unless mentioned by the dealer, cars with W1 grade paint cannot be detected by the human eye, hence it can be possible for such paint to go undetected