

# CLAIM INSIGHT

## AI-Powered Insurance Claim Assessment Report

Generated: December 04, 2025 at 09:10 AM

### DAMAGE IMAGE



### EXECUTIVE SUMMARY

**Damage Type:** Flood Damage  
**Severity Level:** SEVERE (84/100)  
**Estimated Cost Range:** 30,000 - 2,00,000  
**Report Status:** READY FOR CLAIM PROCESSING

### RECOMMENDED ACTION:

IMMEDIATE PROFESSIONAL INTERVENTION REQUIRED - Contact repair services within 24 hours

# DETAILED ASSESSMENT REPORT

Claim Reference: CI-202512040910

## 1. CLAIM INFORMATION

Policy Holder:	Shivam
Contact Information:	shivamgverma99@gmail.com   +919834278625
Incident Location:	fghnjm,, Nagpur, Maharashtra, 440008
Date of Assessment:	December 04, 2025
Assessment ID:	CI-20251204091028

## 2. DAMAGE ASSESSMENT SUMMARY

**SEVERE DAMAGE** Score: 84/100

Damage Type:	Flood Damage
Affected Components:	Water damage throughout vehicle, Moisture intrusion in interior, Electrical system damage, Engine compartment flooding, Upholstery and carpet water damage, Potential mold/mildew growth, Corroded metal components, Contaminated fluid systems
Repair Complexity:	High (structural/critical repair)
Estimated Cost Range:	30,000 - 2,00,000

## 3. DETAILED ANALYSIS

Image Analysis: Image analysis indicates visible damage to property. External surfaces show signs of impact.

CRITICAL DAMAGE DETECTED (Score: 84/100) The damage assessment indicates extensive structural compromise requiring immediate attention. Multiple critical components are affected, posing safety risks if not addressed promptly.

## 4. COMPONENT BREAKDOWN

1. Water damage throughout vehicle
2. Moisture intrusion in interior
3. Electrical system damage
4. Engine compartment flooding
5. Upholstery and carpet water damage
6. Potential mold/mildew growth
7. Corroded metal components
8. Contaminated fluid systems

# RECOMMENDATIONS & COST ESTIMATE

Claim Reference: CI-202512040910

## RECOMMENDATIONS:

- 1. IMMEDIATE ACTION REQUIRED:** Contact certified structural or auto-repair professionals within 24 hours to prevent further deterioration and ensure critical issues are addressed promptly.
- 2. SAFETY FIRST:** Do not enter, touch, or operate the affected area until a qualified technician performs a safety inspection to avoid injury or secondary damage.
- 3. THOROUGH DOCUMENTATION:** Capture high-quality photos and videos of all damaged surfaces from multiple angles, including close-ups, wide shots, and any visible structural impact.
- 4. PROFESSIONAL ASSESSMENT:** Arrange a full structural and functional evaluation to identify hidden issues such as internal cracks, compromised supports, or electrical hazards.

## COST ESTIMATE GUIDANCE:

Based on damage severity and affected components, the estimated repair cost falls within:

**30,000 - 2,00,000**

*Note: This is a preliminary estimate. Actual costs may vary based on:*

- Labor rates in your area
- Parts availability
- Additional hidden damage
- Insurance coverage terms

---

### IMPORTANT DISCLAIMER:

This report is generated by ClaimInsight AI Assessment System and is for preliminary assessment purposes only. The estimated costs are approximate and may vary based on actual repair requirements, labor rates, and parts availability. A physical inspection by a certified professional is recommended for accurate assessment and claim processing.