









<div></div>	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	1/14









	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899
	Project : Site Investigation		Cone no. : C10CFPT.C09016
	Location: CRL - Auckland		Project no. : 02AC1
	Position: 803490, 399950		CPT no. : 203 3/14






	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	4/14






	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	5/14




	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFIPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	6/14





	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	7/14






	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	8/14








	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFIPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	9/14




	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	10/14






Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899
Project : Site Investigation		Cone no. : C10CFIPT.C09016
Location: CRL - Auckland		Project no. : 02AC1
Position: 803490, 399950		CPT no. : 203
		11/14



	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	12/14





	Test according A.S.T.M Standard D 5778-12		Date : 30-12-1899	
	Project : Site Investigation		Cone no. : C10CFIPT.C09016	
	Location: CRL - Auckland		Project no. : 02AC1	
	Position: 803490, 399950		CPT no. : 203	14/14