

Known Issues

Hardware Version 1.0 (the original AVR HV Rescue Shield)

- Parts configured for a fast internal clock (ie. $\geq 4\text{MHz}$) and short (0ms) startup time can't be read/written by the shield.

Hardware Version 2.0

- Parts configured for a fast internal clock (ie. $\geq 4\text{MHz}$) and short (0ms) startup time can't be read/written by the shield.

Hardware Version 2.1

There are no known issues at this time.

products/hvrescue/issues.txt · Last modified: 02/04/2011 22:18 by jeff

Except where otherwise noted, content on this wiki is licensed under the following license: CC Attribution-Share Alike 3.0 Unported [<http://creativecommons.org/licenses/by-sa/3.0/>]