

CAA P.O. BOX 50137, LUSAKA ZAMBIA	 REPUBLIC OF ZAMBIA	AIP SUPP
Tel: 260 21 1 253250 Fax: 260 21 1 251841 AFTN: FLHQYOYX Email: <i>aviation@coppernet.zm</i>		005/2014 28 TH July 2014

AIP SUPPLIMENT

AIRCRAFT TURNING OUT EARLY OFF KENNETH KAUNDA INTERNATIONAL AIRPORT RUNWAY.

It has been observed that aircraft taking off at Kenneth Kaunda International Airport to the north are turning out early at a low altitude overhead the private hangars or fuel depot. This poses safety risk to the hangars and the fuel depot should an aircraft develop engine failure over these points. This will result in catastrophic destruction of property or loss of life.

In view of this, all aircraft taking off must avoid turning out too early (left turn out RWY 10 or right turn out RWY 28) except as instructed by Air Traffic controllers.

This AIP supplement takes effect immediately.



Gabriel Lesa
 Director General
Civil Aviation Authority

