


41TE (604) '94

GPM/HZ

POOR



Condition: TCC switch valve cycling.

Correction: Converter friction, controller update and correct fluid required.

Notes: Known good bypass valve under pump (3-second screen time).