

## COMPLAINT

### SECONDARY COMPLAINTS

## TCC slip, forward clutch failure

• Damage to sealing rings and stator tube • TCC lining failure • Forward clutch drags on in neutral and reverse

## CAUSE

A worn stator support bushing allows forward clutch oil to cross leak into TCC release oil circuits.


## CORRECTION

Replace the worn bushing in the stator support shaft with this replacement bushing.

## Stator Support Bushing

**22005A-01K**

1 Stator Support Bushing



### Sonnax Part Summary

The stator support bushing in 47RH/RE transmissions can wear out, allowing forward clutch oil to cross leak into TCC release oil circuits. This can lead to TCC slip, forward clutch failure and damage to the sealing rings and stator tube. Sonnax replacement bushing **22005A-01K** will help you avoid these problems.

### Features & Benefits

- Bushing is made from steel-backed aluminum to provide greater wear resistance than bronze in heavy-duty applications.
- Bushing is precision-machined to provide minimal clearance with the mating shaft, which is essential to extending bushing life in high load conditions.
- Prevents clutch failure.