

## COMPLAINT

### SECONDARY COMPLAINTS

## Differential side gear thrust washer failure

- Washers not serviced separately • Excess differential/axle backlash

## CAUSE

Worn side gear thrust washers allow the gears to move away from pinions, causing backlash and clunk.

## CORRECTION


Hardened thrust washers allow differential salvage and correct set-up.

## Thrust Washer

**75890-30**

4 Thrust Washers

2 3/16" O.D.



### Sonnax Part Summary

Sonnax has designed a replacement thrust washer 75890-30 for differentials with 2-3/16" outer diameter washers when these OEM washers get worn or destroyed.

### Features & Benefits

- Shims not available elsewhere.
- Thrust washer is hardened.
- Salvages differential assemblies.