

## COMPLAINT

Excessive total transmission endplay

## CAUSE

Endplay due to worn gears, snap rings, and/or splines.


## CORRECTION

This shim reduces transmission endplay for 3- or 4-tanged OEM washers.

## Rear Planet Endplay Shims

### 22700-Z

10 Shims (.010" thick)



### Sonnax Part Summary

It is often difficult to reduce the total transmission endplay in some A727, 46 or 47RH/RE transmissions. Excessive total and/or rear unit endplay is often the result of gear, snap ring and/or spline wear. Rear unit endplay can be difficult to reduce with available selective washers. When rear unit endplay is loose, the total unit endplay measurement is excessive also. Sonnax offers a .010" shim, 22700-Z, which is installed between the OEM thrust washer and the rear planetary.

### Features & Benefits

- Adding a shim or shims between the OEM thrust washer and the rear planetary reduces rear unit endplay, which also reduces total assembled transmission endplay.
- This shim will fit either the 3- or 4-tanged OEM thrust washer design.