

COMPLAINT

Damaged stator support turbine shaft sleeve

CAUSE

Sealing ring contact, worn stator support bushing, or turbine shaft breakage.


CORRECTION

This stator support sleeve salvages damaged stator supports and restores the sealing ring surface for the turbine shaft.

Stator Support Sleeve

34203-01K

1 Stator Support Sleeve



No machining required!

Sonnax Part Summary

The sealing ring surface on the turbine shafts in 4L80-E units can wear because of sealing ring contact, worn stator support bushings or shaft breakage. Sonnax offers a stator support sleeve, **34203-01K**, that salvages the stator supports and restores the sealing ring surface for the turbine shaft. This sleeve is a direct replacement for the OEM sleeve, and does not require any machining to install.