

COMPLAINT

Sluggish shifts

CAUSE

Fatigued OEM 3-4 accumulator springs.


CORRECTION

This 3-4 accumulator spring re-establishes proper shift feel in these transmissions. This is a duplicate of OEM diesel application 47RE.

3-4 Accumulator Spring

12861-01

1 Spring



Sonnax Part Summary

In vehicles with 42-46-47RH/RE transmissions, it is common for the 3-4 accumulator spring to fatigue, causing sluggish shifts, or to break. Sonnax now offers a specially designed 3-4 accumulator spring **12861-01** to restore the proper shift feel.

Features & Benefits

- Restores proper shift feel.
- Sonnax spring is the duplicate of the OEM spring in the 47RE diesel application.
- Improves shift quality.