

COMPLAINT

SECONDARY COMPLAINTS

1-2 shift is too soft or long

- Persistent 1-2 slide shift with end bump
- Calibrated 1-2 accumulator shift springs difficult to find

CAUSE

Fatigued or poorly calibrated springs result in ineffective accumulator action.

CORRECTION


The Sonnax springs can improve clutch feed or reduce accumulator piston rate, depending on selection.

1-2 Accumulator Piston Spring Kit

96706-02K

Includes 1 each of the following

1-2 Accumulator Spring	Large
1-2 Accumulator Spring	Medium
1-2 Accumulator Spring	Small
1-2 Capacity Modulator Valve Spring	



Sonnax Part Summary

1-2 shift quality in AXODE and AX4S units can be particularly affected by fatigued or poorly calibrated 1-2 accumulator springs. Complaints of soft or long 1-2 shifts and persistent slide shifts with end bump can be addressed with the **96706-02K** Accumulator Spring Kit. Sonnax has developed these high-quality, precision-manufactured springs to correct problems in a variety of units with a broad range of recalibration needs.

Features & Benefits

- A single spring, or combination of springs, offers moderate to greatly increased spring rates over OE springs.
- Results in firmer, shorter 1-2 shifts.
- Eliminates persistent 1-2 slide shift with end bump.
- High quality, precision-made drop-in replacements.