


4R100 ('99 & up)



Condition: Repeated overdrive failure, overheat.

Correction: Replace cooler, bypassing OEM completely, cooler above, Tru-Cool LPD 4590.

Notes: Low flow even after extensive hot flush. OE external cooler may also have restrictions.