

Motors are hot

Motors are hot once it is enabled. 80 degree celsius hot on motor surface is normal, and below 120 degree celsius is ok.

Y axis motor only runs at its 50% of its ability, and other motors such as X axis motor, extruder motors run at its 70% of its ability. Usually these motors will be hotter.