



Report Title 1



*Ermetal Otomotiv A.Ş.
Dumlupınar / Osmangazi, Bursa
Bursa, Turkey*

Factory: Ermetal Otomotiv A.Ş.
 Machine-Name: Press031
 Component-Name: dengeleme

Author: Admin Machinaide
 Date: 2021-07-03

Description

report description

Summary of Data

Total Number of Alerts: 7

Time interval the listed alerts encompass: 17-02-2021 => 05-03-2021

Total number of recorded failures: 1

Time interval the listed failures encompass: 23/02/2021 => 23/03/2021

Total number of maintenance records: 64

Time interval the listed maintenance reports encompass: 23/02/2021 => 23/03/2021

Alerts Pie Chart Distribution


Alerts

Component Failures

	SOURCENAME	SEVERITY	COST	STARTTIME	ENDTIME
0	Press031.dengeleme.sensor1	major	None	2021-04-06T10:17	2021-05-10T09:50
1	Press031.dengeleme.sensor2	critical	None	2021-04-15T16:41	2021-04-15T16:41
2	Press031.dengeleme	major	750	2021-04-14T16:41	2021-04-23T16:41
3	Press031.dengeleme.sensor1	critical	740	2021-04-15T15:40	2021-04-15T22:41
4	Press031.dengeleme.presAnaHavaAkis	acceptable	None	2021-05-07T08:32	

	SOURCENAME	SEVERITY	COST	STARTTIME	ENDTIME
5	Press031.dengeleme.sensor1	major	None	2021-05-08T00:27	
6	Press031.dengeleme.sensor2	critical	None	2021-05-08T00:28	
7	Press031.dengeleme.sensor1	major	None	2021-05-11T10:31	
8	Press031.dengeleme.sensor1	critical	None	2021-05-11T10:31	
9	Press031.dengeleme.sensor1	major	None	2021-05-11T10:32	
10	Press031.dengeleme.sensor1	acceptable	None	2021-05-01T10:32	
11	Press031.dengeleme	acceptable	None	2021-07-01T17:47	

Maintenance Reports Pie Chart Distribution



■ Maintenance 1

Machine Maintenance Records

	ASSET	DATE	DURATION	MAINTENANCETYPE
0	Press030.dengeleme.sensor1	2021-04-13T10:18	23	Maintenance 1
1	Press030.dengeleme.presAnaHavaAkis	2021-04-20T10:32	0	Maintenance 1

Component SnapShots