

## Known Issues R520.1\_TCU1\_SCN\_to\_R520.1\_TCU4\_SCN

PAR	Impact	Function	Description
RCEPROC-1252	Engineering/ Configuration	CE900 IO	Error Indication: The PFQ module continues to accumul
RCEPROC-1262	Engineering/ Configuration	CE900 IO	Error Indication: Control Builder is crashing during "uplo
RCEPROC-1264	Engineering/ Configuration	CE900 IO	Error Indication: AVRAW and AV parameter values are
RCEPROC-1273	Engineering/ Configuration	CE900 IO	Error Indication: Writing Reset to the Pulse input channe
RCEPROC-1265	Engineering/ Configuration	CE900 IO	Error Indication: AIREF block PV value does not flow to
RCEPROC-1271	Engineering/ Configuration	CE900 IO	Error Indication: The download of the IO point with confi
RELCN-3970	System Stability	ELCN Bridge	Error Indication: There is no clear indication of this error
1-FCJXEMPL	OPM- Interoperability	cosmetic anomaly-CMW	Error Indication: [M&I] AI_LLAI module ver_ rev entries
1-FDI4PGP	Migration	UOC-SERIES-A	Error Indication: The PROFIBUS data read by the Contr
1-FFC6HR9	System Stability	3rdParty- EthernetIP	Error Indication: Momentary communication issue with S
1-FJ6TSH7	Ace Cut Over	CM- Configuration Management	Error Indication: The ACE Ver_rev entry is not updated,