

Known Issues R511.2_SCN_to_R511.4_SCN

PAR	Function	Impact	Description	Release
1-EJYYPEL	OPMController Migration	Migration	Error Indication: Cx-PPIX01 with App version 520.04103.05.001 is shown as module with '...	R520.04103.05.001
RCEPROC-1252	CE900 IO	Engineering/ Configuration	Error Indication: The PFQ module continues to add bus counts even though the H...	R520.04103.05.001
RCEPROC-1262	CE900 IO	Engineering/ Configuration	Error Indication: Control Builder is crashing during "Uploading update to project" of CM co...	R520.04103.05.001
RCEPROC-1264	CE900 IO	Engineering/ Configuration	Error Indication: AVRAW and AV parameters values are simulated based on the sim...	R520.04103.05.001
RCEPROC-1273	CE900 IO	Engineering/ Configuration	Error Indication: Writing Reset to the Push button block in SCADA from a push block with only...	R520.04103.05.001
RCEPROC-1265	CE900 IO	Engineering/ Configuration	Error Indication: AIREF block PV value is not updated to the DACA block. Description:...	R520.04103.05.001
RCEPROC-1271	CE900 IO	Engineering/ Configuration	Error Indication: The download of the IOP201 with configuration changes causes the...	R520.04103.05.001
RELCN-3970	ELCN Bridge	System Stability	Error Indication: There is no clear indication of the status which can be presented in m...	R520.04103.05.001
1-FCJXEML	cosmetic anomaly-CMW	OPM- Interoperability	Error Indication: [M&I] AI_LLAI module version 520.04103.05.001 marked as Cx-PAIM51 ins...	R520.04103.05.001
1-FDI4PGP	UOC-SERIES-A	Migration	Error Indication: The PROFIBUS data received by the UOC is not the same as the PROFIB...	R520.04103.05.001
1-FFC6HR9	3rdParty- EthernetIP	System Stability	Error Indication: Momentary communication loss between A output modules under...	R520.04103.05.001
1-FJ6TSH7	CM- Configuration Management	Ace Cut Over	Error Indication: The ACE Ver_rev entry is not updated, which causes the cutover to f...	R520.04103.05.001