

Sarovar - Equipment Not Working Data			
Category	Flow Annunciator Panels - Fire Sprinkler	CP Hoses	Sprinkler Charged (floor wise)
S.No	14	15	17
Description of Issue	Flow Annunciator Panel not working	228 Male & Female CP Hose couplings are missing	Sprinkler system reactivation is pending in 17 floors
Root Cause	Due to malfunctioning of flow switches	Due to wear & tear	Uncovering of concealed sprinklers is pending 12 floors in different blocks, due to inaccessibility of flats sprinkler reactivation is pending in 05 floors in different blocks
Action Required/Planned	Need to reactivate the entire system, Involved huge cost	Need to replace with new CP Hose couplings	-
Pending from days	-	-	-
Estimated Date of Completion	-	-	-
Responsibility	Society	Society	Society
Notified to the concerned	Society	Society	Society