

Aura STP Not working Data		
Category	Filter Feed Pumps	STP MCC Panel
S.No	5	14
Description of Issue	Filter Feed Pump not working	STP MCC Panel is not working.
Root Cause	Bearings problem	Electrical MCC panel is located inside the STP. The exposure to Heat and moisture damaged the components.
Action Required / Planned	Sent for repair	Shifting of Electrical panel is in the final stage.
Pending from days	15	15
Responsibility	APMS	APMS
Estimated Date of Completion	22.01.2019	31.01.2019
Notified to the concerned	APMS (Working from 21.01.2019)	APMS