

Sarovar Grande STP Not working Data	
Category	De-watering Pump
S.No	2
Description of Issue	De-watering pump is not working.
Root Cause	Motor shaft is jammed and bearing to be replaced.
Action Required / Planned	Sent to workshop for repair.
Pending from days	40
Responsibility	APMS
Estimated Date of Completion	05.12.2018
Notified to the concerned	APMS (Working from 06.12.2018)