

Boulevard STP Not working Data	
Category	De-watering Pump
S.No	8
Description of Issue	De-watering pumps are not working
Root Cause	Winding is damaged due to aging of pump. it is beyond economical repair
Action Required / Planned	Informed to the society for procuring new pump. Third party price quotation is also submitted to society
Pending from days	64
Responsibility	Society
Estimated Date of Completion	-
Notified to the concerned	Society